

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 9233K

DATE 15/3/2018 16:15

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips <i>X</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover <i>X</i>			\$ 225.00
	<b>SUB TOTAL</b>			\$ 1,907.35
	<b>LESS 20% <i>25%</i></b>			\$ 381.47
	<b>DISCOUNTED TOTAL</b>			\$ 1,525.88
	 Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
				<b>Nett</b>
				\$ 135.70
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>250.00</del> <i>100</i>
	Spray Painting Charge			\$ <del>250.00</del> <i>200</i>
	Wiring Charge			\$ <del>50.00</del> <i>X</i>
	R/Refix Reverse Sensor			\$ <del>120.00</del> <i>X</i>
	<b>TOTAL LABOUR</b>			\$ 670.00
	<b>ESTIMATE TOTAL</b>			\$ 2,331.58
<i>Kaluh 11/11/14</i> <i>15/3/18 1500hrs.</i> <i>2 Days</i> <i>P/P</i> <i>After Repair photo</i>				
<div> LKK Auto Consultants hence notify the Repaire of the following: <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div> <div> Acknowledged by Repairer  Signature: </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				