

SERVICE ESTIMATE

88704 - C00001
Mr Jamaji Rustom
137 Sunset Way
#07-07

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Singapore 597159

Inv.No. : B&P 0 Page 1

Inv.date. : 19/03/2018

WIP No. : 50749

Veh.In/Out:

*Tel.No. : Mobile: 90464161

Reg.No. : SJB849P

Reg.date : 28/02/2017

Mileage : 0

Chassis No: SALCA2AG3HH668964

Closed by : Mandy Neo

Svc Consultant :

Remarks : Mr Jamaji Rustom

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
						3600.	
802	TO REPLACE REAR BOOT LID,REAR EMBLEM,REAR BUMPER,REAR SKID PLATE,REAR SENSOR,REAR BRACKET, ETC	0	6000.00	0		6,000.00	S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,ETC	0	4000.00	0		4,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	1000.00	0		1,000.00	S ✓
802	TO TRANSFER REAR BOOT LID PART	0	500.00	0		500.00	S ✓
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S ✓
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S ✓
	RESETTING OF ALL ELECTRICAL MODULES						
	TAILGATE PANEL DSPOR	1.0 EA	3265.10		bt✓	3,265.10	S
	BUMPER COVER REAR DS	1.0 EA	1918.60		de✓	1,918.60	S
	BUMPER - COVER LOWER	1.0 EA	430.00		de✓	430.00	S
	BRACKET - BUMPER MOU	1.0 EA	114.60		ne✓	114.60	S
	BRACKET - BUMPER MOU	1.0 EA	114.60		ne✓	114.60	S

Tanjim 17495749
WP 16/4/18 @ 1045
Resurvey before paint.
sur@lkanp.com
5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Date:

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

88704 - C00001
Mr Jamaji Rustom
137 Sunset Way
#07-07

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 19/03/2018

WIP No. . : 50749

Veh.In/Out:

*Tel.No. . : Mobile: 90464161

Reg.No. . : SJB849P

Reg.date. : 28/02/2017

Mileage . : 0

Chassis No: SALCA2AG3HH668964

Singapore 597159

Closed by : Mandy Neo

Svc Consultant :

Remarks : Mr Jamaji Rustom

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET - BUMPER MOU	1.0 EA	106.80		net	106.80	S
	BRACKET - BUMPER MOU	1.0 EA	106.80		net	106.80	S
	BRACKET - BUMPER	1.0 EA	187.50		net	187.50	S
	BRACKET - BUMPER	1.0 EA	187.50		net	187.50	S
	REINFORCEMENT BAR RE	1.0 EA	816.30		?	816.30	S
	TOW HOOK COVER REAR	1.0 EA	27.30		dl	27.30	S
	SENSOR - PARKING AID	4.0 EA	395.40		?	1,581.60	S
	FOG LAMP REAR RH DSP	1.0 EA	335.40		x	335.40	S
	FOG LAMP REAR LH DSP	1.0 EA	350.80		x	350.80	S
	BADGE REAR "DISCO" D	1.0 EA	171.30		net	171.30	S
	BADGE REAR "VERY" DS	1.0 EA	153.70		net	153.70	S
	BADGE OVAL REAR RR3	1.0 EA	91.20		net	91.20	S
	ADHESIVE SEALER FL2	1.0 EA	425.40		net	425.40	S
	GLASS - BACK WINDOW	1.0 EA	1119.60		net	1,119.60	S
	ADHESIVE AND SEALER	2.0 EA	116.10		net	232.20	S
	D PRIMER GLASS & P	1.0 EA	37.40		net	37.40	S

Gross Total. 24,039.70

Labour Total 12,266.00
Parts Total 11,773.70
Package Total 0.00

Net..... 24,039.70
GST @ 7.0% 1,682.78
Total..... 25,722.50
Paid..... 0.00
Please Pay.. 25,722.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated