

INS. CASE OWNER

Rashidh CC 6/AIG1800 5094, Umb39

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$:

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES/NO : TP GIA REPORT: YES/NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hup motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time:

21/2/18

SJS1568D - X

VIN 61748 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$:

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$:

1200

Loss of Rental (LOR):

\$:

200

(

2 days)

100

Loss of Use (LOU):

\$:

(5

x

days)

Loss of Income (LOI):

\$:

(5

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search:

\$:

200

Medical:

\$:

Disbursement:

\$:

(e.g. Tow/ Independent)

Legal Cost:

\$:

1402.00

Total:

\$:

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$:

1402.00

Name 1:

HUP MOTOR TRADING &amp; SERVICE

Payee 2: (Strike if N.A.)

\$:

Name 2:

Payee 3: (Strike if N.A.)

\$:

Name 3:

RECEIVED 05 APR 2018

COPY SENT 5/4/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320 + \$20

CH 4/4/18

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJS1568Dat Workshop m/s Hyundai 1030

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 2 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJS1568D Yr Regn: 7109Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or 4A /Make: Hyundai Avante c.c. 1591Colour: white A/C: Insured / Std / NI / NASp. Reading: 13362 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHOU43R9U809648Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModj: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SilverstoneFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/3/18 D.O.I. 21/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No new parts replacement. Repairer must p/p for repair2/4/18 cont. and Repair sum \$1200 with David.(rel \$153004/ 56.37%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18005094/mb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 19-03-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLN 6174B	Veh. Inspected	SJS 1568D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	18/03/2018	Inspection Date		
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2895/03/18 Your Ref: \_\_\_\_\_ Date: 19th March 2018

MR TAN CHEE TONG  
BLK 231, ANG MO KIO AVE 3  
#02-1240, SINGAPORE 560231

### Estimate cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

1 pc front bumper		\$R 453.00	X
8 pcs front bumper clips	@ \$ 3.50	rec 28.00	—
2 pcs front bumper o/s & n/s side retainer	@ \$ 28.00	cut 56.00	—
2 pcs front bumper o/s & n/s side clips	@ \$ 5.00	rec 10.00	—
1 pc front bumper reinforcement		1 284.00	X
1 pc front bumper sponge damper		CRA 114.00	✓
1 pc front bumper centre lower airscoop grille		11 47.00	X
5 pcs front bumper lower shield rubber clips @ 3.50		11 17.50	X
2 pcs front bumper o/s & n/s fog lamp assy @ \$ 141.00		CRA 282.00	✓
2 pcs front bumper o/s & n/s LED light @ \$ 70.50		11 141.00	X
1 pc front grille (with chrome moulding)		CRA 366.00	—
5 pcs front grille clips @ \$ 3.50		rec 17.50	—
2 pcs front bumper o/s & n/s top retainer @ \$ 36.00		11 72.00	X
		\$ 1,888.00	873.5
	Less 20%	\$ 377.60	698.80
		\$ 1,510.40	
To wiring check up & adjust headlight alignment.		50.00	20
To respray Tuff-Kote on all affected accident parts.		11 90.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.		500.00	300
To putty & respray painting on all affected accident parts.		600.00	300
		\$ 2,750.40	

Dollars : Two Thousand Seven Hundred Fifty And Cents Forty Only.

P-1358.80

### HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Not Noted  
dk  
1/3/18  
Teh, to the up on  
2 dy  
21/3/18  
Repair sum \$ 1200

哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2895/03/18 Your Ref: \_\_\_\_\_ Date: 21st March 2018

MR TAN CHEE TONG  
BLK 231, #02-1240  
ANG MO KIO AVE 3  
SINGAPORE 560231


 SUPPLEMENTARY Bill for HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

1 pc front number & frame

*50* \$ 50.00 Nett *405.00 Nett*

Dollars : Fifty Only.

HUP MOTOR TRADING & SERVICE

.....  


**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 4436G

**Vehicle Details**

Vehicle No.: SJS1568D  
Vehicle to be Exported: No  
Intended De-registration Date: 21 Mar 2018  
Vehicle Make: HYUNDAI  
Vehicle Model: HD AVANTE 1.6 A  
Primary Colour: White  
Manufacturing Year: 2009  
Engine No.: G4FC9U685291  
Chassis No.: KMH DU41BR9U809648  
Maximum Power Output: 89.7 kW (120 bhp)  
Open Market Value: \$11,231.00  
Original Registration Date: 30 Jul 2009  
First Registration Date: 30 Jul 2009  
Transfer Count: 0  
Actual ARF Paid: \$11,231.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Jul 2019  
PARF Rebate Amount: \$6,177.00

**Intended COE Rebate Details**

COE Expiry Date: 29 Jul 2019  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$15,291.00  
COE Rebate Amount: \$2,071.00  
**Total Rebate Amount: \$8,248.00**

The information contained herein is correct as at 21 Mar 2018

OK

## Bevan Lim (LKK Auto)

---

**From:** Bevan Lim (LKK Auto)  
**Sent:** Wednesday, 21 March 2018 2:55 PM  
**To:** 'David Ang'  
**Cc:** Vic (LKKAuto)  
**Subject:** RE: RE : Your Ref : CC6/AIG18005094/mb3

Your ref: **SJS 1568D**  
Our Ref: CC6/AIG18005094/Umb3

*Without Prejudice*

Dear Sirs,

### **ACCIDENT INVOLVING SLN 6174B(AIG) & SJS 1568D ON 18/03/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

**From:** David Ang [mailto:[hupmotor@gmail.com](mailto:hupmotor@gmail.com)]  
**Sent:** Wednesday, 21 March 2018 11:51 AM  
**To:** Bevan Lim (LKK Auto) <[bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)>  
**Subject:** RE : Your Ref : CC6/AIG18005094/mb3

Dear Bevan,

Kindly see the attach video footage, Please let us hear from you,

B  
**est Regards**

**David Ang**

**Tel : 6784 0039, Fax : 6784 0076**  
**HP : 9815 4655**

**Hup Motor Trading & Service**  
**Blk 9004 Tampines St 93**  
**#01-120**  
**Singapore 528838**



Virus-free. [www.avg.com](http://www.avg.com)



哈 汽 車 貿 易 服 務

**HUP MOTOR TRADING & SERVICE**

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2895/03/18 Your Ref: \_\_\_\_\_ Date: 21st March 2018

MR TAN CHEE TONG  
BLK 231, #02-1240  
ANG MO KIO AVE 3  
SINGAPORE 560231

 SUPPLEMENTARY Bill for HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

1 pc front number & frame

\$ 50.00 Nett

Dollars : Fifty Only.

**HUP MOTOR TRADING & SERVICE**

.....  


**Bevan Lim (LKK Auto)**

---

**From:** Bevan Lim (LKK Auto)  
**Sent:** Wednesday, 4 April 2018 2:20 PM  
**To:** 'Brendan Toh'  
**Cc:** Vic (LKKAuto)  
**Subject:** RE: Accident involving SLN6174B and SJS1568D (CC6/AIG18005094/Umb3)

Without Prejudice

Dear Brendan,

We refer further to your below email and we had just received the letter of demand from the claimant.

Please find below the adjusted breakdown of the proposed amount for settlement to the claimant for your reference.

Cost of Repair	\$1,200.00
Loss of Rental(\$100-120 x 2 recommended days)	\$ 240.00
GIA Search Fee	\$ 2.00
<b>TOTAL</b>	<b>\$1,442.00</b>

Our surveyor is in the opinion that based on the damages sustained to the claimant's vehicle and the adjusted amount is already fair and reasonable.

We hope the above matter clarifies.

Thank you.

Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

**From:** Brendan Toh [mailto:[brendantoh@gmail.com](mailto:brendantoh@gmail.com)]  
**Sent:** Wednesday, 28 March 2018 11:32 AM  
**To:** Bevan Lim (LKK Auto) <[bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)>  
**Subject:** Accident involving SLN6174B and SJS1568D (CC6/AIG18005094/Umb3)

Hi Bevan,

Thank you for the earlier tele-conversation. As mentioned, can I confirmed with AIG and LKK that there is a 3rd party claim amount of estimated max S\$2750 (pending final amount after surveyor completed the survey) and surveyor had suggested to 3rd party workshop 2 days of repair (loss of use) ? Thank you.

2. I would also like to confirm that AIG or your side had received a video confirming my car indeed knocked onto SJS1568D when I was reversing. If it is so, then I will accept as it is.

3. I have also attached the link to download all the photos to show there wasn't any damage to the car, SJS1568D as well as my car, SLN6174B. Hence, I seek LKK surveyor who is acting on behalf of AIG Motor Claims to protect AIG Policy holder and ensure that the types and amount of claim matches that of what I showed in the photos. Please do not allow them to make false claims on parts or damages not caused by me. I can provide more if your surveyor needed more to also show the top engine view to see that the brackets did not come loose at all.

Link to photo : [https://1drv.ms/f/s!ArNjJ0A7hr\\_N53vK-vfjnawvNWC4](https://1drv.ms/f/s!ArNjJ0A7hr_N53vK-vfjnawvNWC4)

4. I have also contacted AIG and informed them of the matter. May I seek your assistance to email me on the final claim amount after your negotiation with 3rd party claim and also let me know the types (which parts of the vehicle) claim they are claiming against me.

5. I am not repairing my car as there is no damage on my car.

6. Thank you for your kind assistance.

Best Regards,  
Brendan Toh Teck Kiong  
92722685

## Bevan Lim (LKK Auto)

---

**From:** Bevan Lim (LKK Auto)  
**Sent:** Wednesday, 4 April 2018 2:12 PM  
**To:** David Ang  
**Cc:** Marcus Chua (LKKAuto); Vic (LKKAuto)  
**Subject:** RE: RE : YOUR REF : CC6/AIG18005094/mb3

Without Prejudice

Dear David,

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,200.00
2. Loss of Rental (2days x \$100.00)	\$ 200.00
3. LTA search	\$ 2.00
Total	<b><u>\$ 1,402.00</u></b>

Please confirm acceptance.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

**From:** David Ang [mailto:[hupmotor@gmail.com](mailto:hupmotor@gmail.com)]  
**Sent:** Wednesday, 4 April 2018 12:55 PM  
**To:** Bevan Lim (LKK Auto) <[bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)>  
**Cc:** Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Subject:** RE : YOUR REF : CC6/AIG18005094/mb3

Dear Bevan,

Attach our letter of demand, final bill, car rental bill, receipt, GIA third party insurer search fee & owner authorisation letter for your reference & attention,

Please let us have your settlement soonest, we will forwards the original documents to yours by mail,

**Best Regards**

**David Ang**

**Tel : 6784 0039, Fax : 6784 0076**

**HP : 9815 4655**

**Hup Motor Trading & Service**

**Blk 9004 Tampines St 93**

**#01-120**

**Singapore 528838**



Virus-free. [www.avg.com](http://www.avg.com)

**Bevan Lim (LKK Auto)**

---

**From:** Brendan Toh <brendantoh@gmail.com>  
**Sent:** Wednesday, 4 April 2018 2:41 PM  
**To:** Bevan Lim (LKK Auto)  
**Subject:** Re: Accident involving SLN6174B and SJS1568D (CC6/AIG18005094/Umb3)  
**Attachments:** image001.jpg

Hi Bevan,

Noted for the confirmation of the amount S\$1442 claimed by 3rd party. Thank you.

Best Regards,  
Brendan Toh

On Wed, 4 Apr 2018, 2:20 pm Bevan Lim (LKK Auto), <[bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)> wrote:

Without Prejudice

Dear Brendan,

We refer further to your below email and we had just received the letter of demand from the claimant.

Please find below the adjusted breakdown of the proposed amount for settlement to the claimant for your reference.

Cost of Repair	\$1,200.00
Loss of Rental(\$100-120 x 2 recommended days)	\$ 240.00
GIA Search Fee	\$ 2.00
<b>TOTAL</b>	<b>\$1,442.00</b>

Our surveyor is in the opinion that based on the damages sustained to the claimant's vehicle and the adjusted amount is already fair and reasonable.

We hope the above matter clarifies.

Thank you.

Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**From:** Brendan Toh [<mailto:brendantoh@gmail.com>]

**Sent:** Wednesday, 28 March 2018 11:32 AM

**To:** Bevan Lim (LKK Auto) <[bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)>

**Subject:** Accident involving SLN6174B and SJS1568D (CC6/AIG18005094/Umb3)

Hi Bevan,

Thank you for the earlier tele-conversation. As mentioned, can I confirmed with AIG and LKK that there is a 3rd party claim amount of estimated max S\$2750 (pending final amount after surveyor completed the survey) and surveyor had suggested to 3rd party workshop 2 days of repair (loss of use) ? Thank you.

2. I would also like to confirm that AIG or your side had received a video confirming my car indeed knocked onto SJS1568D when I was reversing. If it is so, then I will accept as it is.

3. I have also attached the link to download all the photos to show there wasn't any damage to the car, SJS1568D as well as my car, SLN6174B. Hence, I seek LKK surveyor who is acting on behalf of AIG Motor Claims to protect AIG Policy holder and ensure that the types and amount of claim matches that of what I showed in the photos. Please do not allow them to make false claims on parts or damages not caused by me. I can provide more if your surveyor needed more to also show the top engine view to see that the brackets did not come loose at all.

Link to photo : [https://1drv.ms/f/s!ArNjJ0A7hr\\_N53vK-vfjnawvNWC4](https://1drv.ms/f/s!ArNjJ0A7hr_N53vK-vfjnawvNWC4)

4. I have also contacted AIG and informed them of the matter. May I seek your assistance to email me on the final claim amount after your negotiation with 3rd party claim and also let me know the types (which parts of the vehicle) claim they are claiming against me.

5. I am not repairing my car as there is no damage on my car.

6. Thank you for your kind assistance.

Best Regards,

Brendan Toh Teck Kiong

92722685



# 哈 汽 車 貿 易 服 務


## HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: <http://hupmotor.com.sg> Reg. No. 378091/00W

Our Ref: **TP 2985/03/18**

Your Ref: \_\_\_\_\_

Date: **4th April 2018**

 The Claim's Manager  
Motor Claims Dept.  
AIG Asia Pacific Insurance Pte. Ltd.  
78, Shenton Way, #07-16,  
Chartis Bldg. Singapore 079120

Dear Sirs,

RE : ACCIDENT ON 18/03/18 ALONG BLK 186A, RIVERVALE DRIVE  
INVOLVING : SJS 1568 D & YOUR INSURED : SLN 6174 B

We act for Mr Tan Chee Tong., NRIC No : S25344368  
Who is the registered owner of Veh. No : SJS 1568 D Which was involved  
in the above accident with Veh. No : SLN 6174 B Which we understand  
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and  
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,  
therefore, seeking compensation from you for my financial losses as  
itemised below : -

Cost of repair	\$ 1,200.00
Car rental for 2 days ( 1 day X \$ 120.00 )	240.00
LTA Search Fee & GIA-RMC Search Fee	2.00
Survey Fee	0.00
	<hr/>
	\$ 1,442.00
	=====

We have enclosed copies of relevant documents to support my client's  
claim, There was no receipt enclosed, as my client's did not pay us  
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

**HUP MOTOR TRADING & SERVICE**

  
Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation  
Letter, ~~GIA Report, Survey Report & Ins. Cert.~~ Car Rental Receipt.

Remark : Kindly acknowledge receipt.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC6/AIG18005094/Umb3** ✓

23 MARCH 2018

**TOH TECK KIONG( ZHUO DEQIANG)**  
BLK 10 CHAI CHEE ROAD ✓  
#02-09 ✓  
SINGAPORE 467010 ✓

Dear Sir/Madam,

**ACCIDENT INVOLVING SLN 6174B AND SJS 1568D ON 18/03/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim  
Case Handler  
DID: 6749 4274  
FAX: 6741 4108  
Email: [bevanlim@lkkauto.com](mailto:bevanlim@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

TO : AIG ASIA PACIFIC INSURANCE PTH. LTD.

## AUTHORIZATION TO ACT

I, Mr Tan Chee Tong (S25344360) ("the third party claimant")

of Blk 231, #02-1240, Ang Mo Kio Ave 3, S (560231) (address),

owner of SJS 1568 D (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my Vehicle No. SJS 1568 D that was damaged pursuant to the accident which occurred on 18/03/18 (date) along Blk 186A, Rivervale Drive (location)

involving Vehicle No/s SLN 6174 B


("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 4th day of April (month) 20 18 (year)

**HUP MOTOR TRADING & SERVICE**

  
Owner Of SJS 1568 D  
Mr Tan Chee Tong (S25344360)  
Signed by "the third party claimant"

  
Signed by "the workshop"

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **HUP MOTOR TRADING & SERVICE**("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,200.00** (Repair Cost), **S\$200.00** (Loss of Use/Rental), **S\$2.00**(Disbursement) for vehicle no. **SJS1568D** that was damaged pursuant to the accident which occurred on **18/03/2018** (date) along **186A RIVERVALE DRIVE** (location) involving vehicle no/s **SLN 6174B**. This is pursuant to the inspection conducted on **21/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TAN CHEE TONG** ("the third party claimant") of vehicle no. **SJS 1568D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJS 1568D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 04 (day) of 04 (month) 2018 (year)



Signed by appointed surveyor

**HUP MOTOR TRADING & SERVICE**

Signed by "the workshop" (with chop)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2985/03/18 Your Ref: \_\_\_\_\_ Date: 4th April 2018

MR TAN CHEE TONG  
BLK 231, #02-1240,  
ANG MO KIO AVE 3  
SINGAPORE 560231

INVOICE for cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

To supply front bumper clips, side retainer, sponge damper, front o/s & n/s fog lamp assy, front grille, clips, front number plate & necessary parts,

Labour charge to remove & cut out damage parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts,

To putty & respray painting on all affected accident parts, including wiring check up.

Repair Sum : \$ 1,200.00  
\*\*\*\*\*

Dollars : One Thousand And Two Hundred Only.

HUP MOTOR TRADING & SERVICE

.....  




專營運善必甲出租  
汽車修理  
汽車保險賠償服務  
嘉實多授權服務中心

# 國家汽車服務

## NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279  
(off Ang Mo Kio Avenue 3) Singapore 569536  
TEL: 6482 5577 (3 Lines) FAX: 6482 5000  
TOWING SERVICE: 6858 4067 (After 10.30pm)  
Reg. No: 062389/00M



TRUCK RENTAL  
MOTOR REPAIR  
INSURANCE CLAIMS  
AGENCY  
AUTHORISED CASTROL  
SERVICE CENTRE

### 車輛出租合同 VEHICLE RENTAL AGREEMENT

Date: 02/04/2018

Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")

Hirer: MR TAN CHEE TONG (OWNER OF SJS 1568 D)

Address: BLK 231, #02-1240, ANG MO KIO AVE 3, S (560231)

NRIC / Co. Reg. No: S2534436/G

Tel: Fax: H/P: 94509883

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SLK 5130 A TOYOTA ALTIS 1.6 (A) SALOON		Agreement No.: 56620-A	
Driver's Particulars		Odometer: 20647 (full tank fuel)	
Name: MR TAN CHEE TONG		Date & Time Out: 02/04/2018 (09:30)	
Address: As Above		Date & Time In: 04/04/2018 (09:50)	
I/C No: S2534436G	Dr/Licence No: S2534436G	Hour @\$	
Date of Issue: 07/09/2015	Occupation: SELF-EMPLOYED	2 Days @\$ 120-00	\$ 240-00
YOD: 26/04/1977	Tools: One Set	Wks @\$	
Date of Birth: 30/03/1956	Spare Tyre: One	Mths @\$	

#### Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 5,500/- comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

#### Own Vehicle Damage

Hirer is responsible for the first \$ 4,000/- excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreen) plus loss of earnings while damaged vehicle is under repair.

#### Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

#### Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable):

NIL

Sub-Total:

\$ 240-00

Balance To Pay:

\$ 240-00

PETROL/DIESEL AT YOUR OWN EXPENSE  
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE



國家汽車服務  
NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2 #01-279  
Singapore 569538. Tel: 6482 5577 (3 Lines) Fax: 6482 5000

正式收據  
OFFICIAL RECEIPT

DATE 4/4/18

註收到

RECEIVED FROM:

Tan chee Tong

款額

AMOUNT:

Two Hundred & Forty

BEING PAYMENT OF: 1. 對過

(SUBJECT TO CHEQUE CLEARANCE)

Vehicle of SLF 5730 A

此收據必須俟支票過賬之後始屬有效。

from 2/4/18 to 4/4/18

\$

240/-  
CASH/CHEQUE  
現銀 / 支票

NATIONAL AUTOMOBILE SERVICE



RECORDS MANAGEMENT CENTRE

## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-041080

Date of Request: 19/03/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 19/03/2018  
Enquiry By Sandy Loo Chwee Ngoh  
TP Vehicle No. SLN6174B  
Accident Date 18/03/2018

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLN6174B	AIG Asia Pacific Insurance Pte. Ltd.	11/05/2017-10/05/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.





RECORDS MANAGEMENT CENTRE

# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-041080

Date of Request: 19/03/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 19/03/2018  
Enquiry By Sandy Loo Chwee Ngoh  
TP Vehicle No. SLN6174B  
Accident Date 18/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018 <a href="#">Edit Reg</a>		21 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	TOH TECK KIONG (ZHUO DEQIANG), ID: S8212905G		
Main Claimant:	TAN CHEE TONG, ID: S2534436G		
Vehicle Reg. No.:	SJS1568D	Date of Loss:	18/03/2018 01:00 - :59 [103 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1388242383SG	Policy/Cover Note No.:	1700004565 (Comprehensive)
Vehicle Reg. No. (Insured):	SLN6174B	Policy No. (Claimant):	M492437
		Excess:	
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/03/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJS1568D (1388242383SG)**  
**[SLN6174B]**  
**TP**  
**TAN CHEE TONG**  
**Mar 18 2018 1:40AM**  
**[TOH TECK KIONG (ZHUO DEQIANG)]**  
**Hup Motor Trading & Service**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Video</b>														1 per page			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	21/03/18 14:55	Video - Accident											Load MP4				
<b>Letters/Correspondences</b>														1 per page			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
<b>Assessment Reports</b>														1 per page			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	20/03/18 11:25	Accident Statement From: SC - Reg. No: SLN6174B, Claimant: TOH TECK KIONG (ZHUO DEQIANG)											Load HTM				
<b>Photos/Images</b>														3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	21/03/18 18:27	Odometer Reading											Load JPG				
2	21/03/18 18:27	General View											Load JPG				
3	21/03/18 18:27	Chassis Number											Load JPG				
4	21/03/18 18:27	General View											Load JPG				
5	21/03/18 18:27	General View											Load JPG				
6	21/03/18 18:27	General View											Load JPG				
7	21/03/18 18:27	General View											Load JPG				
8	21/03/18 18:27	General View											Load JPG				
9	21/03/18 18:27	General View											Load JPG				
10	21/03/18 18:27	General View											Load JPG				
11	21/03/18 18:27	General View											Load JPG				
12	21/03/18 18:27	General View											Load JPG				
13	21/03/18 18:27	General View											Load JPG				
14	21/03/18 18:27	General View											Load JPG				
15	21/03/18 18:27	General View											Load JPG				
16	21/03/18 18:27	General View											Load JPG				
17	21/03/18 18:27	General View											Load JPG				
18	21/03/18 18:27	General View											Load JPG				
19	21/03/18 18:27	General View											Load JPG				
20	21/03/18 18:27	General View											Load JPG				
21	21/03/18 18:27	General View											Load JPG				
22	21/03/18 18:27	General View											Load JPG				
23	21/03/18 18:27	General View											Load JPG				
24	21/03/18 18:27	General View											Load JPG				
25	21/03/18 18:27	General View											Load JPG				
26	21/03/18 18:27	General View											Load JPG				
27	21/03/18 18:28	General View											Load JPG				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
29	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
30	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
31	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
32	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
33	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
34	21/03/18 18:28	General View	Load JPG	<input checked="" type="checkbox"/>
35	02/04/18 20:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	02/04/18 20:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	02/04/18 20:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	02/04/18 20:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 18:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/03/18 15:54	TP EST & GIA REPORT	Load PDF	
2	21/03/18 15:19	LETTER TO OI	Load PDF	
3	22/03/18 17:38	TP ESTIMATE- MARKED	Load PDF	
4	09/04/18 08:58	WORKSHOP INVOICE	Load PDF	
5	09/04/18 08:58	AUTHORISATION TO ACT FORM	Load PDF	
6	09/04/18 08:58	Release Voucher	Load PDF	
7	09/04/18 08:58	RENTAL RECEIPT	Load PDF	
8	09/04/18 08:58	GIA SEARCH	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN6174B (Insd veh)	Model:	HYUNDAI AVANTE 1.6 (A)
	SJS1568D (TP veh)		
Date of Accident:	18/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	2,800.40
Final Repair Cost	:	\$	1,200.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	200.00      2 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,402.00

Is Third Party Workshop GIA Registered?    ☐ YES    ☒ NO    (Kindly indicate below)

A) For **Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For **GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	:	\$ 1,402.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Apr  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18005094/UMB3Q2

Date: 09/04/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700004565  
**Claimant Vehicle** SJS1568D **Insured Vehicle No :** SLN6174B  
**No :**  
 Date of Loss: 18/03/2018 Nature of Claim: TP Claim No: 1388242383SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS1568D**  
 Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FC9U685291  
 Reg. Date: 30/07/2009 (Man. Year: 2009) Chassis No: KMHDU41BR9U809648  
 Colour: White Odometer: 133621 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15  
 Front Left Side: Silverstone 6 mm Rear Left Side: Silverstone 6 mm  
 Front Right Side: Silverstone 6 mm Rear Right Side: Silverstone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,560.40	738.80	821.60	52.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	620.00	620.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,800.40</b>	<b>1,358.80</b>	<b>1,441.60</b>	<b>51.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,800.40</b>	<b>1,200.00</b>	<b>1,600.40</b>	<b>57.15</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,402.00</b>		

### INSPECTION

Date of Assignment: 21/03/2018  
 Date Inspected: 21/03/2018 Inspected At: Hup Motor Trading & Service (HQ)  
 Blk 9004 Tampines Street 93, #01-120  
 Singapore 528838  
 Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Lim Chin Siong Bevan

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	453.00 FL	*- FL
2	8		*FRONT BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
3	2		*FRONT BUMPER O/S & N/S SIDE RETAINERS	Bent	56.00 FL	*56.00 FL
4	2		*FRONT BUMPER O/S & N/S SIDE CLIPS	Necessary	10.00 FL	*10.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	284.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE DAMPER	Cracked	114.00 FL	*114.00 FL
7	1		*FRONT BUMPER CENTRE LOWER AIRSOOP GRILLE	Not Necessary	47.00 FL	*- FL
8	5		*FRONT BUMPER LOWER SHIELD RUBBER CLIPS	Not Necessary	17.50 FL	*- FL
9	2		*FRONT BUMPER O/S & N/S FOG LAMP ASSY	Cracked	282.00 FL	*282.00 FL
10	2		*FRONT BUMPER O/S & N/S LED LIGHT	Not Necessary	141.00 FL	*- FL
11	1		*FRONT GRILLE (WITH CHROME MOULDING)	Cracked	366.00 FL	*366.00 FL
12	5		*FRONT GRILLE CLIPS	Necessary	17.50 FL	*17.50 FL
13	2		*FRONT BUMPER O/S & N/S TOP RETAINER	Not Necessary	72.00 FL	*- FL
14	1		*FRONT NUMBER & FRAME	Bent	50.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,938.00</b>	<b>913.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>377.60</b>	<b>174.70</b>

<b>Total Parts (S\$)</b>	<b>1,560.40</b>	<b>738.80</b>
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	0.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	500.00	300.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	600.00	300.00
Gross Labour Cost (S\$)			<b>1,240.00</b>	<b>620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >