

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2895/03/18

Your Ref:

Date: 19th March 2018

MR TAN CHEE TONG
BLK 231, ANG MO KIO AVE 3
#02-1240, SINGAPORE 560231

Estimate cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

1 pc front bumper		\$ 453.00	?
8 pcs front bumper clips	@ \$ 3.50	28.00	—
2 pcs front bumper o/s & n/s side retainer	@ \$ 28.00	56.00	—
2 pcs front bumper o/s & n/s side clips	@ \$ 5.00	10.00	—
1 pc front bumper reinforcement		284.00	X
1 pc front bumper sponge damper		114.00	?
1 pc front bumper centre lower air scoop grille		47.00	X
5 pcs front bumper lower shield rubber clips @ 3.50		17.50	—
2 pcs front bumper o/s & n/s fog lamp assy @ \$ 141.00		282.00	1/2
2 pcs front bumper o/s & n/s LED light @ \$ 70.50		141.00	?
1 pc front grille (with chrome moulding)		366.00	—
5 pcs front grille clips @ \$ 3.50		17.50	—
2 pcs front bumper o/s & n/s top retainer @ \$ 36.00		72.00	?
		\$ 1,888.00	
	Less 20%	\$ 377.60	
		\$ 1,510.40	
To wiring check up & adjust headlight alignment.		50.00	20
To respray Tuff-Kote on all affected accident parts.		90.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.		500.00	300
To putty & respray painting on all affected accident parts.		600.00	300
		\$ 2,750.40	
		=====	

Dollars : Two Thousand Seven Hundred Fifty And Cents Forty Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Not Acknowledged
4/5/3
Take the other up on
2 days
21/3/18

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2895/03/18 Your Ref: _____ Date: 21st March 2018

MR TAN CHEE TONG
BLK 231, #02-1240
ANG MO KIO AVE 3
SINGAPORE 560231


 SUPPLEMENTARY Bill for HYUNDAI AVANTE 1.6 (A) Saloon - SJS 1568 D

1 pc front number & frame

50 \$ 50.00 Nett *405.00 Nett*

Dollars : Fifty Only.

HUP MOTOR TRADING & SERVICE


.....