

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

19-Mar-18

Our ref : TP/4479/18

Hock Beng Seng Coach Service

TP LCR
Xiao Tony

BE637GB00577

RE : estimate cost for vehicle no : PA 2212Y

1 pc rear bumper *re-hd*
1 pc rear lh fender *re-fet*
1 pc rear lh mudflap *torn*

less 25%

1 pc rear lh tyre *free*
1 pc rear lh rim *free*
Panel beating.
Spray painting.
Alignment.

Plus 7% GST

\$	4,981.00	1682
	7684.00	600 (Local Repair)
	362.00	
	13027.00	
	3,256.75	2044 S.N: 600
	9,770.25	1533
	400.00	snett *
	300.00	*
	2,000.00	600
	1,500.00	600
	80.00	x
	14,050.25	
	983.52	
	15,033.77	1200

SD : Fifteen thousand & thirty-three & cents seventy-seven only.

U/s Adrian Lj
19/03/18.
06 Dps.
total 3333
U/s 2650.