

ASS. REC. BY:

REF: CS/SM018 005125 R/qd3ⁿ² Special Instruction:

Surveyor:

Resul

ASSIGNMENT (Office)

From (Person):

Irene Henry

of

8MD

Date/Time:

19/3/18 @ 10:47am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5412K

Insured:

SLD4247R

at Workshop m/s:

Prime Auto

Tel:

6861 0908

of

6 Benoi place

Policy No:

Claim No:

CMTD180118

Sum Insured:

Excess:

Make of Veh:

D.O.A

17/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

12:22pm @ 19/3/18

Person Contacted:

Pei Yee

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 5412K - CS/FCI 17017/12/R/qbe2

D.O.A: 2/9/2017

SLD4247R - CC4/AxA16016718/yb3XX

D.O.A: 1/9/16

20/3/18 @ 2:51pm revised to Irene Henry by email.

Karni Analised to \$3250, 5 days.

CPed \$2789.84, 46%

John

31282

Form

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SKW 5412K**

at Workshop no: **PRIME AUTO**

of: **Sompo / TP**

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No


Est. Repairs: 5 days Res: Yes or No

Turn Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS.

Date Person Contacted:

Vehicle: IN / OUT



Vehicle No: **SKW 5412K** (Plate) **2015 Nov**

Type: **C** (Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover)

Truck / Trailer

Make: **TOYOTA PRINS HYBRID 18A** 1797

Colour: **Green** A/C Insured / Std / NI / NA

Sp/Reading: **313432** T/Plate Insured / Std / NI / NA

Engine:

C/No: **ZVW 300455 206**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **C** (normal / Jammed / Leaked / Burnt)

Brake: **C** (normal / Jammed / Leaked / Burnt)

Modi: **C** (Nil / 5/11mm / STD A/Rim)

Tyre Size: **F: 185/55R15**
R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **GOODRIDE**

Front: **6** mm R/Bal: **6** mm

L/Bal: **6** mm D.O.A: **17/03/18** B.O.L: **19/03/18**

Survey held at: **PRIME AUTO**

Des. of Damages: **Rear** (Frt / Rear / O/S / N/S / U/C / Rooftop)

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 23 MAR 2018

Initials: **28/3/18**

Copy/Time: The Police/22

☐ Prel. Report

☐ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Copied Formal

Stamp Sum: **TP 3750**

Add Fee:

☐ Site Ins: 15

☐ Interview: 15

☐ Report: 15

☐ 24hrs: 15

Survey Fee

Insurance


250

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18005125/R1qd3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 19-03-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 4247R	Veh. Inspected	SKW 5412K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD180118	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	19/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/03/2018	Inspection Date		
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD180118/FW

Date: 20th March 2018

Our Ref: CS/SMO18005125/R1qd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKW 5412K .


We thank you for the instruction on 19/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2018 at the premises of M/s PRIME AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,039.94</u> .
Revised Estimate Amount	: S\$ <u>4,063.19</u> .
"Check" Items Amount	: S\$ <u>421.50</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have not authorized repair.

Yours faithfully

Rasul
Automobile Assessor

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 19 March 2018 10:47 AM
To: assignments
Cc: Nivitha (LKK Auto)
Subject: SOMPO REF: CMTD180118/FW: PRI REQUEST TO ACCIDENT ON 17.03.2018 INVOLVING SKW5412K & SLD4247R
Attachments: img-180317134503.pdf
Importance: High

Dear LKK AUTO,

Kindly assist to contact the uninsured for the arrangement to conduct the motor survey for the mentioned (SKW 5412K).

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

m: Pei Yee [mailto:peiyee@primeautoclaims.com]

Sent: Saturday, 17 March, 2018 11:55 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: aliceleong@primeautoclaims.com

Subject: PRI REQUEST TO ACCIDENT ON 17.03.2018 INVOLVING SKW5412K & SLD4247R

Importance: High

Hi

The above referred.

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

Please inform surveyor to avoid 1145-1245hrs lunch hour.

***We agreed to your in-house surveyor to survey our vehicle. Please survey after 1030hrs on 19.03.2018**

***Please arrange PRI soonest possible due to loss of income and loss of rental per day count.**

Thank you.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.

Office : 5 Benoi Place Singapore 629926

Workshop : 6 Benoi Place Singapore 629927

Tel: 6861 0908

Fax: 6515 2948

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Virus-free, www.avast.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 March 2018 2:51 PM
To: 'Henry, Irene James'; assignments
Cc: SUR
Subject: RE: SOMPO REF: CMTD180118/FW: PRI REQUEST TO ACCIDENT ON 17.03.2018 INVOLVING SKW5412K & SLD4247R
Attachments: CSSMO18005125R1qd3.pdf

Dear Irene,

Enclosed herewith preliminary advice of SKW 5412K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 19 March 2018 12:29 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD180118/FW: PRI REQUEST TO ACCIDENT ON 17.03.2018 INVOLVING SKW5412K & SLD4247R

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Monday, 19 March 2018 10:47 AM
To: assignments <assignments@lkkauto.com>
Cc: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: SOMPO REF: CMTD180118/FW: PRI REQUEST TO ACCIDENT ON 17.03.2018 INVOLVING SKW5412K & SLD4247R
Importance: High

Dear LKK AUTO,

Kindly assist to contact the unsigned for the arrangement to conduct the motor survey for the mentioned (SKW 5412K).

Best Regards
Irene Henry

MPRI18030422 / Prime Auto Claims Service Pte Ltd - HQ
ENTRY DATE & TIME: 17/03/2018 10:22
SUBMITTED BY: Liu Pei You

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/03/2018 10:22
Date Of Accident 17/03/2018 06:50
Exact Location Of Accident TAMPINES AVE 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW5412K
Insured/Policyholder
Name Of Registered Owner SECTION CREDIT & MOTOR LEASING PTE LTD
Co Reg No 198703128Z
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-68628878
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS HYBRID-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number 17-MI001630-R00
Cover Note Number
Driver
Name of Driver TAN CHEE HWEE
NRIC No S7821317E
Date Of Birth 23/07/1978
Occupation OUTDOOR
Date Of Driving Pass 16/09/1999
Driving Experience 18 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83638312
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 504 BEDOK NORTH STREET 3 #06-140 SINGAPORE
 Postcode 460504
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : PASSENGER A

GENDER: : MALE

Passenger 2 NAME: : PASSENGER B

GENDER: : MALE

Passenger 3 NAME: : PASSENGER C

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD4247R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver YVAN LIM

NRIC/Passport Number S9131331F

Contact Number 97978998

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN CHEE HWEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKW5412K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 504 BEDOK NORTH STREET 3 #06-140 SINGAPORE

Postcode

460504

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17/03/18 09:49hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17.03.2018 @ 0650 hrs, my car SKW5412K was stationary with 3 passengers (2 males and one female) along Tampines Avenue 1 traffic light junction on right lane as traffic light was in red. While stationary, one car SLD4247R rear-ended into my stationary car rear portion.

After the accident, we alighted from our vehicles to check on the damages. We exchanged phone numbers. Driver of SLD4247R, Mr. Yvan Lim verbally admitted his fault and wrote a note to me. I felt backache so I will consult doctor if my ache persisted.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 17/03/18 0949hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

THIRD PARTY ADMIT FAULT STATEMENT Pg. 1

I, Yvan Lim, S9131331F,
driver of SW4247R,
hit SKW5412K on the
rear at junction of
Tampines Ave 10 on
17 March 2018 0650am.

Yvan Lim

Tan Joo Kah



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 19.03.2018

Sompo Insurance Singapore Pte Ltd

50 Raffles Place #05-01/06

Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SKW5412K TOYOTA PRIUS HYBRID 1.8L A (2015)

To Supply

1)	1pc	Rear bumper	\$	1,218.00	DE -
2)	1pc	Rear bumper right side retainer	\$	122.25	nee -
3)	1set	Rear bumper clip	\$	30.00	nee -
4)	1pc	Tail gate	\$	1,450.00	PT -
5)	1pc	Tail gate weatherstrip	\$	284.00	nee -
6)	1pc	Tail gate "Toyota" emblem	\$	62.00	nee X HVC
7)	1pc	Tail gate "Prius" emblem	\$	72.00	nee X HVC
8)	1pc	Tail gate "Hybrid Synergy Drive" emblem	\$	51.00	nee X HVC
9)	1pc	Rear end panel	\$	782.00	R
10)	1pc	Rear end panel top garnish	\$	562.00	? X HVC
11)	1set	Rear end panel top garnish clip	\$	40.00	nee -

Sub total parts	\$	4,673.25
Less: 25% discount	\$	1,168.31
	\$	3,504.94

To Supply S.Nett Parts

1)	1tube	Rear glass sealant	\$	45.00	nee -
2)	1pc	Inner seal	\$	40.00	nee -
3)	2pcs	Tail gate lower glass moulding (2pcs)	\$	60.00	nee -
4)	1set	Tail gate glass moulding (3pcs)	\$	240.00	nee -

Sub total S.Nett Parts	\$	385.00
------------------------	----	--------

L/charge

1)	To remove & refit tail gate glass	\$	120.00	/
2)	To remove & refit tail gate lower glass	\$	80.00	40

- 3) To transfer tail gate trim, handle & mechanism parts \$ ~~100.00~~ 60
- 4) To cut / welding rear end panel, knock floor panel. To remove rear bumper, tail gate & end panel. Replace the above parts. Align & adjust rear bumper & tail gate \$ ~~850.00~~ 500
- 5) To putty, respray painting tail gate inlet & outer, rear end panel, floor panel, rear bumper \$ ~~1,000.00~~ 600

Sub total L/charges	\$	2,150.00
Estimated Grand Total	\$	<u>6,039.94</u>

Resue
 Hp 90010068
 5 days
 H/S
 19/03/18 @ 1720
 Resue after repair

[Signature]
 20/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

19-03-18 11:38 From

To: 62658941



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
 5 Benoi Place Singapore 629926
 Tel: 6861 0908 Fax: 6515 2948

Date: 19.03.2018

Sompo Insurance Singapore Pte Ltd
 50 Raffles Place #05-01/06
 Singapore Land Tower
 Singapore 048623

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SKW5412K TOYOTA PRIUS HYBRID 1.8L (1335)

To Supply

1)	1pc	Rear bumper	\$	1,218.00	DE -
2)	1pc	Rear bumper right side retainer	\$	122.25	ne -
3)	1set	Rear bumper clip	\$	30.00	ne -
4)	1pc	Tail gate	\$	1,450.00	TH -
5)	1pc	Tail gate weatherstrip	\$	284.00	ne -
6)	1pc	Tail gate "Toyota" emblem	\$	62.00	ne X suc
7)	1pc	Tail gate "Prius" emblem	\$	72.00	ne X suc
8)	1pc	Tail gate "Hybrid Synergy Drive" emblem	\$	51.00	ne X suc
9)	1pc	Rear end panel	\$	782.00	R X suc
10)	1pc	Rear end panel top garnish	\$	562.00	? X suc
11)	1set	Rear end panel top garnish clip	\$	40.00	ne -

Sub total pa
 Less: 25% discou

4,673.25
 1,168.31
 3,504.94

3144.25
 25%
 2358.18

To Supply S. Nett Parts

1)	1tube	Rear glass sealant		45.00	ne -
2)	1pc	inner seal		40.00	ne -
3)	2pcs	Tail gate lower glass moulding (2pcs)		60.00	ne -
4)	1set	Tail gate glass moulding (3pcs)		240.00	ne -

Sub total S. Nett Par

385.00 ✓

L/charge

1)	To remove & refit tail gate glass	120.00	✓
2)	To remove & refit tail gate lower glass	80.00	40

385

11/36 From

To: 62659941

21/8

- 3) To transfer tail gate trim, handle & mechanism parts
- 4) To cut / welding rear end panel, knock floor panel. To remove rear bumper, tail gate & end panel. Replace the above parts. Align & adjust rear bumper & tail gate
- 5) To putty, respray painting tail gate inlet & outer, rear end panel, floor panel, rear bumper

Sub total L/
Estimated Grant

60
500
132
600

00 1320.00
94 4066.94
- 813.89

3253.55
↓
3250/-

Res
4/ or

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

19/11

Res

2358.18
388.00
1320.00
4066.18
- 150%
3250.54

40-3,250
5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18005125/R1qd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 28-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 4247R	Veh. Inspected	SKW 5412K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD180118/FW	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	19/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID 1.8L A	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZVW300455206	Colour	GREY
Odometer	313432	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	GOODRIDE	6 mm
L/H Front Tyre	185/55 R15	GOODRIDE	6 mm
R/H Rear Tyre	185/55 R15	GOODRIDE	6 mm
L/H Rear Tyre	185/55 R15	GOODRIDE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2018	Inspection Date	19/03/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5412K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,218.00	1,218.00
1	REAR BUMPER RIGHT SIDE RETAINER	NECESSARY	122.25	122.25
1	SET REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	TAIL GATE	BENT	1,450.00	1,450.00
1	TAIL GATE WEATHERSTRIP	NECESSARY	284.00	284.00
1	TAIL GATE "TOYOTA" EMBLEM	SERVICEABLE	62.00	-
1	TAIL GATE "PRIUS" EMBLEM	SERVICEABLE	72.00	-
1	TAIL GATE "HYBRID SYNERGY DRIVE" EMBLEM	SERVICEABLE	51.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	782.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	562.00	-
1	SET REAR END PANEL TOP GARNISH CLIP	NECESSARY	40.00	40.00
	LESS 25% DISCOUNT		-1,168.31	-786.06
			3,504.94	2,358.19
<u>SPECIAL NETT ITEMS</u>				
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	45.00	45.00
1	INNER SEAL (SN)	NECESSARY	40.00	40.00
2	TAIL GATE LOWER GLASS MOULDING (SN)	NECESSARY	60.00	60.00
1	SET TAIL GATE GLASS MOULDING (3PCS)(SN)	NECESSARY	240.00	240.00
			385.00	385.00
<u>LABOUR</u>				
	TO REMOVE & REFIT TAIL GATE GLASS.		120.00	120.00
	TO REMOVE & REFIT TAIL GATE LOWER GLASS.		80.00	40.00
	TO TRANSFER TAIL GATE TRIM,HANDLE & MECHANISM PARTS.		100.00	60.00
	TO CUT/WELDING REAR END PANEL,KNOCK FLOOR PANEL.TO REMOVE REAR BUMPER,TAIL GATE & END PANEL.REPLACE THE ABOVE PARTS.ALIGN & ADJUST REAR BUMPER & TAIL GATE.		850.00	500.00
	TO PUTTY,RESPRAY PAINTING TAIL GATE INLET & OUTER,REAR END PANEL,FLOOR PANEL,REAR BUMPER.		1,000.00	600.00
			2,150.00	1,320.00
GRAND TOTAL			6,039.94	4,063.19



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00
---	--	--	----------

Report Ref No. CS/SMO18005125/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.