

INS. CASE OWNER:

CC 3 / CTI1800 5772, S. 19/3/18

LKK
IDAC:

Surveyor:

YWK

DOI:

ASSIGNMENT

19/3/18

Date / Time:

19/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GX 79437

Claim No.:

SNM180 0541 COV

Name of Insured:

VENTURE FURNITURE AND RENOVATION

Policy No.:

DMLV 166264201

Insured Tel No.:

HP:

16/3/18 P11

Make / Model:

TOYOTA

Excess Sec II : \$5

D.O.A.:

Place of Accident:

MABLEMEIN RD PICTON NT.

Is driver the owner?

(YES / NO)

Nature of Accident:

VE TMS MONYMS

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SHB 1367E



INSRS:

WSP:

Tel:

Liability:

RMKS:

GMR.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

5/4/18

Bevan

16/5/18

11/9/18 (ollina)

16/5/18

2/9/18

SHB 1367E - 24/09/2018/20/09/2018

GX 79437 - Y

11001 GIA, SENT OUT WT LETTER

m-11 11961444 yuelow 2070

PIR received from both LBS & SHRT. Proceed no other / 11/09/18

(Can do below 3E)

Bevan had sent out LOI.

File pass to SHUPET to close.

RECEIVED 24 SEP 2018

PRELIMINARY ADVICE

Date/Time:

10/7/18

Sent By:

Dm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/9/18

Confirm with:

Lee Hek

Email

Call

Final Liability:

%

100

(Agreed / Accepted) BOLA S/N No.:

NIL.

If No or B 28, Ass. Lia:

Repair Cost:

SS

2250.00

Loss of Rental (LOR):

SS

667.68

(5 days)

X#11128

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOR only

LOU only

LOR + LOU

LOR + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

LOU + LOI

GIA/LTA Search

SS

7.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost:

SS

-

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#400.00

Total:

SS

2924.68

Global Sum SS:

2800.00

FINAL PAYMENT

Date/Time:

20/9/18

Confirm with:

Lee Hek

Email

Call

Payee 1:

SS

2800.00

Name 1:

SMRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

Signature:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time / Action / Instruction

45# 2250 (Ref # 6400 / 78%).

7/15/14

LKR.

Chin Teiping

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

1)

Report Format:

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

\$ + RS

Phone

Cable

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18005172/Smb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-03-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GX 7943Z	Veh. Inspected	SHB 1367E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/03/2018	Inspection Date	19/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

11, BEAVY L 002-25 PAYA LEBBIN STREET PARK, SINGAPORE 408903 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18005172/Smb3

Date: 20.03.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB1367E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.03.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,665.66
Revised Estimate Amount	: S\$	2,347.64
"Check" Items Amount	: S\$	128.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1367E
 Ref. No : TAX/03/18/2079
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : REVEENDRAN VIJAYAN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 14/03/2018 10:52:00 AM
 Accident Reported Date / Time : 16/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095080
 Special Instruction to ARC, if any :



Prepared Date : 16/03/2018 02:22:33 PM

Sebastian
 17/3/18
 - Lump Sum Repair.
 - Question Mark In
 Photo.
 - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U205741498

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,808.00	0.00
Total Material Charges	: 4,263.66	4,350.68
Other Charges	: 580.00	0.00
TOTAL	: 8,665.66	0.00
Lum Sum Total	: 8,650.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 16/03/2018 03:35:10 PM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/03/2018 03:35:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 50
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY DOOR HANDLE	180.00	0.00 50
Total Spray Painting & Panel Beating	2,808.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	580.00	0.00

Part 4.- Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace R	No X
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace R	No X
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace R	No X
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace JAC	No ✓
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace R	No X
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace JAC	No ✓
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace X	No X
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace ✓	No ✓
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace ✓	No ✓
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace R	No ✓
69217-74010			COVER, FRONT DOOR OUTSIDE HANDLE	1	14.10	25.00	10.57	Replace	Replace R	No X
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace R	No X
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace R	No ✓
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace R	No ✓
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace JAC	No ✓
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace JAC	No ✓
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No X
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace R	No X
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace JAC	No ✓
TOTAL MATERIALS								5,438.37	5,438.35	
TOTAL MATERIALS(Discounted)								4,263.66	4,350.68	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



~~23-3-18 15:41~~
 23-3-18 / 10:41
 23-3-18 / 14:41

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

19-3-18 / 14:41

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1367E
 Ref. No : TAX/03/18/2079
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : REVEENDRAN VIJAYAN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 14/03/2018 10:52:00 AM
 Accident Reported Date / Time : 16/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle Issued? : No
 Accident Repair Job Card No : 000024095080
 Special Instruction to ARC, if any : chine 4s



BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121
 LUMPSUM REPAIR

Prepared Date : 16/03/2018 02:22:33 PM

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

2nd witness

Date

452954
 1 1 3 1
 4 2 4 1

23/3/18 15.00 pass

453038

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 23-3-18

Vehicle Return Time: 14:12

SMRT staff sign:

Chassis No : JTDKN36U205741498

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	500.00
Total Spray Painting Charges	: 2,808.00	1,400.00
Total Material Charges	: 412.83	310.11
Other Charges	: 580.00	60.00
TOTAL	: 4,814.83	2,270.11
Lum Sum Total	: 4,800.00	2,250.00
No. of Repair Days	: 7.00	4.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 16/03/2018 03:35:10 PM	19/03/2018 02:41:58 PM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/03/2018 03:35:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0568

Invoice No :

Quotation Date : 24/3

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00 ✓	500.00 /
Total Labour	1,014.00	500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00 ✓	200.00 /
TO RESPRAY FRONT FENDER LH	378.00 ✓	200.00 /
TO RESPRAY FRONT DOOR LH	378.00 ✓	200.00 /
TO RESPRAY VIEW MIRROR	180.00 ✓	50.00 /
TO RESPRAY REAR DOOR LH	378.00 ✓	200.00 /
TO RESPRAY REAR FENDER LH	378.00 ✓	200.00 /
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	180.00 ✓	100.00 /
TO RESPRAY DOOR HANDLE	180.00 ✓	50.00 /
Total Spray Painting & Panel Beating	2,808.00	1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIX WING MIRROR	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	580.00	60.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	R 1	462.00	100.00	0.00	Replace	Repair	No R
52116-47040		6505516	BUMPER SUPPORT F/LH	X 1	76.40	25.00	57.30	Replace	Check	No X
53802-47050		6505558	FENDER FRT/LH	R 1	723.40	100.00	0.00	Replace	Repair	No R
75374-47051			NAME PLATE (HYBRID)	V 1	51.90	25.00	38.92	Replace	Replace	No ✓
67002-47070		6505529	DOOR FRT/LH	R 1	894.40	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT (DOOR)	V 1	60.00	0.00	60.00	Replace	Replace	No ✓
87940-47310		6505599	MIRROR ASSY, LH	X 0	1,224.90	25.00	0.00	Replace	Not given	No X
81740-52040		6505465	MIRROR LAMP LH	V 1	65.30	10.00	58.77	Replace	Replace	No ✓
87945-74010		6505597	COVER, OUTER MIRROR, LH	V 1	107.40	25.00	80.55	Replace	Replace	No ✓
89210-74030			DOOR OUTER HANDLE FRT/LH	R 1	370.80	100.00	0.00	Replace	Repair	No R
69217-74010			COVER, FRONT DOOR OUTSIDE HANDLE	R 1	14.10	100.00	0.00	Replace	Repair	No R
75852-47900			MOULDING BODY, LH	R 1	673.60	100.00	0.00	Replace	Repair	No R
67004-47080		6505487	DOOR RR/LH	R 1	954.50	100.00	0.00	Replace	Repair	No R
61602-47091		6505476	FENDER RR/LH	R 1	788.80	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT	V 1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	V 1	21.60	0.00	21.60	Replace	Replace	No
52159-47905		6505548	BUMPER REAR	R 1	458.60	100.00	0.00	Replace	Repair	No R
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	X 1	94.80	25.00	71.10	Replace	Check	No X
			PIXEL STICKER	V 2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS							516.05	387.64		
TOTAL MATERIALS(Discounted)							412.83	310.11		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

387.64 /
 - 20%
 310.11 /
 + 500.00 /
 + 1460.00 /
 2270.11 /

L/S \$2250/-
 Substition
 27/5/18

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1367E
Vehicle to be Exported:	No
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZRD208980
Chassis No.:	JTDKN36U205741498
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	07 May 2014
First Registration Date:	07 May 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 May 2022
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	06 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$31,167.00
Total Rebate Amount:	\$37,443.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Mar 2018

OK

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Wednesday, 4 April 2018 11:00 AM
To: Shu Pei (LKKAUTO)
Cc: Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving GX7943Z (OI : CTI - SNM18D01541C02) and SHB1367E (TP : LKK REF -CC3/CTI18005172/Smb3) on 14.03.2018

Dear Shu Pei,

We refer to your email on even date.

Please be advised that till date our Insured had not filed SAS Report.

Kindly do the next course of action soonest possible.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 4 April, 2018 8:33 AM
To: Lucas Lee
Cc: Jowyn Tay; Angie Foo
Subject: RE: Direct Settlement - Accident Involving GX7943Z (OI : CTI - SNM18D01541C02) and SHB1367E (TP : LKK REF - CC3/CTI18005172/Smb3) on 14.03.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 2 April 2018 11:37 AM

To: 'Lucas Lee' <lucas.lee@sg.cntaiping.com>

Cc: 'Jowyn Tay' <jowyn.tay@sg.cntaiping.com>; 'Angle Foo' <angle.foo@sg.cntaiping.com>

Subject: FW: Direct Settlement - Accident Involving GX7943Z (OI : CTI - SNM18D01541C02) and SHB1367E (TP : LKK REF - CC3/CTI18005172/Smb3) on 14.03.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]

Sent: Friday, 23 March 2018 1:54 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Angle Foo <angle.foo@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving GX7943Z (OI : CTI - SNM18D01541C02) and SHB1367E (TP : LKK REF - CC3/CTI18005172/Smb3) on 14.03.2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, 20 March, 2018 6:46 PM

To: Claims Dept of CTI

Cc: Jowyn Tay; Bevan Lim (LKK Auto); Admin A

Subject: Direct Settlement - Accident Involving GX7943Z (OI ; CAI - TBA) and SHB1367E (TP : LKK REF - CC3/CTI18005172/Smb3) on 14.03.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 1367E at M/s SMRT Automotive Services Pte Ltd – Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Our Reference: **SNM18D01541/C02/7**Date : **23 MARCH 2018**

via Ordinary & Registered Mail

**VENTURE FURNITURE AND RENOVATION PTE LTD
5 ANG MO KIO INDUSTRIAL PARK 2A
#07-29/30
SINGAPORE 567760**

Dear Sir / Madam

**ACCIDENT INVOLVING GX7943Z AND SHB1367E ON 14 MARCH 2018
ALONG CTE TOWARDS PIE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB1367E**, is filing a third party property claim against your vehicle.We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.Yours truly,
Claims Department*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : BEVAN
Ref : CC3/CT18005172/SMB3
Contact No : 67494274
via Email : BEVAN@LKKAUTO.COM

CC : Agent - (AN0458A) - TOH SEOK PENG CINDY



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18005172/Smb3

05TH Apr 2018

VENTURE FURNITURE AND RENOVATION PTE LTD

5 ANG MO KIO INDUSTRIAL PARK 2A

#07-29/30

SINGAPORE 567760

Dear Sir / Madam,

**ACCIDENT INVOLVING GX7943Z AND SHB1367E ON 14 MARCH 2018
ALONG CTE TOWARDS PIE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** dated 23 MARCH 2018.

To enable us to look into the matter immediately, please let us hear from you within **seven (7)** days from date of this letter (by 12 APR 2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Bevan Lim

Claims

Tel : 6749 4274

Fax: 6741 4108

Email : bevanlim@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 14 September 2018 8:06 AM
To: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Cc: CS A Team; Admin A
Subject: RE: [CTI]: URGENT / FINAL REMINDER Yr Ref: CC3/CTI18005172/Smb3 ACCIDENT INVOLVING GX 7943Z AND SHB 1367E ON 14/03/2018 (Our Ref: TAX/03/18/2079/lg)

Without Prejudice

Hi Lee Gek,

We refer to the above matter.

We propose settlement at a global sum of **\$2,600.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto)
Sent: Tuesday, 11 September 2018 2:48 PM
To: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <LeeGek@smrt.com.sg>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: [CTI]: URGENT / FINAL REMINDER Yr Ref: CC3/CTI18005172/Smb3 ACCIDENT INVOLVING GX 7943Z AND SHB 1367E ON 14/03/2018 (Our Ref: TAX/03/18/2079/lg)

LKK Ref: CC3/CTI18005172/Smb3

Hi Lee Gek,

Thank you for your email. We are seeking our Principal's mandate. Will get back to you. Kindly hold.

Hsiao Tong (LKKAUTO)

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
<LeeGek@smrt.com.sg>
Sent: Friday, 14 September 2018 11:39 AM
To: Hsiao Tong (LKKAUTO)
Cc: CS A Team; Admin A
Subject: RE: [CTI]: URGENT / FINAL REMINDER Yr Ref: CC3/CTI18005172/Smb3 ACCIDENT INVOLVING GX 7943Z AND SHB 1367E ON 14/03/2018 (Our Ref: TAX/03/18/2079/lg)

Dear Hsiao Tong,

Your offer of \$2,600/- is unacceptable. We are prepared to accept a global sum of \$2,860.00 (LOR at 5.5 days including weekends)

Please reconsider your offer and let us hear from you soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



2700 - 2480.00
#2860 (6/5)
###

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: 14/09/2018 08:06
To: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Cc: CS A Team; Admin A
Subject: RE: [CTI]: URGENT / FINAL REMINDER Yr Ref: CC3/CTI18005172/Smb3 ACCIDENT INVOLVING GX 7943Z AND SHB 1367E ON 14/03/2018 (Our Ref: TAX/03/18/2079/lg)

Without Prejudice

Hi Lee Gek,

We refer to the above matter.

We propose settlement at a global sum of **\$2,600.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4
Singapore 757705
Tel : 65 6866 2647
Fax : 65 6368 7421
www.smrt.com.sg

China Taiping Insurance (S) Pte Ltd
c/o LKK Auto Consultants Pte Ltd
No. 51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 16 April 2018

Our Ref.: TAX/03/18/2079/LG

Dear Sirs,

**ACCIDENT ON 14/03/2018 INVOLVING SHB 1367E & GX 7943Z
ALONG CTE TOWARDS PIE**

LETTER OF CLAIM

We claim on behalf of SMRT Taxis Pte Ltd, the owner and the hirer of taxi no.: SHB 1367E. Your insured's negligent driving has caused the above accident. As a result, our clients have suffered the following losses:-

1. Cost of Repair	:	\$ 2250.00
2. Loss of Rental for <u>7</u> days @ S\$ <u>111.28</u> /day	:	\$ 778.96
3. Loss of Income for _____ days @ S\$ _____ /day	:	-
4. Police Report/ SAS Report/ LTA Search Fee	:	\$ 7.00
5. Survey Fee	:	-
Total Claims :		\$ 3,035.96

We enclose the following documents:

<input checked="" type="checkbox"/> Repair Invoice	<input checked="" type="checkbox"/> Letter of Authorisation
<input type="checkbox"/> Survey Report	<input checked="" type="checkbox"/> LTA Search result
<input type="checkbox"/> Photographs _____ pcs	<input checked="" type="checkbox"/> Others :
<input type="checkbox"/> Investigation results	1. <u>vehicle laid-up report</u>
<input checked="" type="checkbox"/> Proof of Loss of Use/Rental/Income	2. _____
<input checked="" type="checkbox"/> Police / SAS report of <u>SHB 1367E</u>	3. _____

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to **SMRT TAXIS PTE LTD**.

Yours sincerely,
SMRT AUTOMOTIVE SERVICES PTE LTD


Tan Lee Gek
For Manager, Claims
Claims Department
DID: 6866 2647
Email: leegeek@smrt.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/CTI18005172/Smb3

16 MAY 2018

VENTURE FURNITURE AND RENOVATION PTE LTD
5 ANG MO KIO INDUSTRIAL PARK 2A
#07-29/30
SINGAPORE 14/03/2018

Dear Sir/Madam,

ACCIDENT INVOLVING GX 7943Z AND SHB1367E ON 14/03/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **27/05/2018**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)



Date: 16/3/2018

Our Ref. No.:

Letter of Authorisation

I, ^{Name} REVEENDRAN V. JAYAN (NRIC No.: 50121884J) the registered hirer / relief driver / contract hirer of SMRT taxi registration number SHB1367E hereby authorise **SMRT Automotive Services Pte Ltd** ("AutoSvs") to deal with all matters arising out of the accident between my taxi and GX7943Z happened on 14/3/18 at 1052 along C.P. G

(the "Accident") on my behalf, including but not limited to instituting and any claims or proceedings against such party or parties (as AutoSvs deems fit in its absolute discretion) in respect of any claim, demand, loss, cost, expense, liability, damages or action made against us or incurred or suffered by us.

Without prejudice to the foregoing, I further authorise AutoSvs to negotiate, resolve and settle any proceeding or claim arising out of the accidents, including but not limited to doing any act or executing any document or signing the Discharge Voucher on my behalf as may be required.

Name Reveendran V. Jayan Signature: [Signature] 16/3/18 0900
NRIC No. 50121884J
Tel No. 90055120
Address 21 PARRY VIEW
S'PORE 547081

AUTHORIZATION TO ACT

I, **SMRT TAXIS PTE LTD** (the third party claimant") of **BLK 60 WOODLANDS INDUSTRIAL PARK E4 (S) 757705** (address), owner of **SHB 1367E** (vehicle no.) hereby authorize **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no **SHB 1367E** that was damaged pursuant to the accident which occurred on **14/03/2018** (date) along **CTE TOWARDS PIE** (location) involving vehicle no/s **GX 7943Z** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 20 (day) of Sept (month) 2018 (year)

A circular stamp with the text "SMRT TAXIS PTE LTD" around the perimeter. Inside the circle, there is a handwritten signature.

Signed by "the third party claimant"
(with chop if applicable)

A circular stamp with the text "SMRT AUTOMOTIVE SERVICES PTE LTD" around the perimeter. Inside the circle, there is a handwritten signature.

Signed by "the workshop"
(with chop)

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN1663841701

Claim No : SNM18D01541C02

Claimant : SMRT TAXIS PTE LTD

Amount : S\$2,800.00

Singapore Dollars TWO THOUSAND EIGHT HUNDRED Only

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHB1367E

Insured Vehicle No. : GX79432

Date of Loss : 14/03/2018

Place of Accident : CTE TOWARDS PIE

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : VENTURE FURNITURE AND RENOVATION PTE LTD
Driver Name : TAN CHEE WAI TONY

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 2,800.00
TOTAL	S\$ 2,800.00

Claimant Name : _____

NRIC No : S1420706 F

Signature : _____

Date : 20 SEP 2018

Our acceptance of your offer of settlement would not negate or prejudice our driver's right of recovery for his/her losses.



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV180300707
Date : 27.03.2018
Vehicle No. : SHB1367E
Your Ref No. : TAX/03/18/2079
Our Ref No. : 24095080
Terms : 30 Days



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Description	Qty	Unit Cost	Add / (Discount) \$ Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00		\$	2,250.00
GRAND TOTAL				\$ 2,250.00

Remark :

Make/Model : TOYOTA PRIUS

Accident Date : 14.03.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



Our Ref : TAX/03/18/2079/LG

Date : 23/03/2018

To : Claims Department

From : SMRT Taxis Pte Ltd

ACCIDENT INVOLVING SHB1367E & GX7943Z ON 14/03/2018 ALONG CTE TOWARDS
PIE

CONFIRMATION OF TAXI RENTAL

This is to confirm the daily taxi rental rate for taxi registration no. SHB1367E is \$111.28/day.

Kindly proceed to recover any rental loss from the third party as a result of this accident.

Thank you.



SMRT Taxis Pte Ltd



Accident Vehicle Laid-Up Report

Registration No. : SHB1367E Accident Case No. : TAX/03/18/2079

Make / Model : TOYOTA PRIUS Ref. No. : 24095080

Date and Time Vehicle off-road for Accident Repair : 16.03.2018 11:15:00

Date and Time Repair Completed : 23.03.2018 15:28:11

Remarks :

Generated by : POHSUAN

Printed on : 23.03.2018

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Mar 2018 / 15:56:25		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	GX7943Z		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAHO - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20180316155625714942

Search Date / Time: 14 Mar 2018 10:52:00
Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#) [Back to List](#)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Report No : TP/IP/19723/2018
Date : 28 May 2018

Tan Chee Wai Tony
Blk 35 Lorong 5 Toa Payoh
#22-329
Singapore 310035

RECIPIENT'S COPY

STERN WARNING


1. Investigations against you, Tan Chee Wai Tony, S6937848Z, into the following offence(s):

ALLEGED OFFENCE(S)				
S/No	Offence	Legislation	Date & time committed	Place
1	Inconsiderate Driving	Section 65(b) of the Road Traffic Act Chapter 276	14 March 2018, at about 1055hrs	CTE

have been completed.

2. After careful consideration of the facts of the case, and with the concurrence of the Attorney-General's Chambers, you are warned to refrain from any criminal conduct. If you commit any offence in future, the same leniency may not be shown towards you.

3. If you have any clarification, you may contact the Investigation Officer, SI Esther Chong at office number: 6547 6368.


CHEW SOOK YENG, ASP
for HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

28 May 2018
Date



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

NOTE

1. This stern warning is issued to you because while an assessment that you have committed the offence(s) listed in paragraph 1 has been made, a decision has been taken not to prosecute you in court for the offence(s).
2. This stern warning:
 - (a) does not amount to a conviction for an offence or a finding of guilt by a court of law;
 - (b) does not mean that you now have a criminal record of the offence(s) listed in paragraph 1;¹
 - (c) will not be raised by the Prosecution as a criminal record against you in any future court matters for purposes of enhancing a sentence; and
 - (d) does not affect any of your legal rights, interests, or liabilities.

¹ As defined in the Registration of Criminals Act (Cap 268, 1985 Rev Ed.)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408855
Tel +65 6547 0000
Fax +65 6547 4863
www.police.gov.sg

Our Ref : TP/IP/19723/2018
Date : 28 May 2018

Reveendran Vijayan

Dear Sir / Madam,

**TRAFFIC ACCIDENT INVOLVING SHB1367E AND GX7943Z ALONG CTE ON
14/03/2018 AT ABOUT 1055 HRS**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of **GX7943Z** had committed the offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276. Action has been initiated against the driver for the said offence.
3. If you have any clarification, you may contact the Investigation Officer, SI Esther Chong at office number: 6547 6368.
4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18005172/Spb3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 03-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 7943Z	Veh. Inspected	SHB 1367E
Policy No.	DMCVSN1663841701	Coverage (\$)	0.00
Claim No.	SNM18D01541C02	Excess (\$)	0.00
Assign From		Assign Date	19/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U205741498	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/03/2018	Inspection Date	19/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1367E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	COVER ,OUTER MIRROR, LH (DISC 25%)	CUT	107.40	80.55
1	MIRROR LAMP LH (DISC 10%)	CRACKED	65.30	58.77
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	MIRROR ASSY ,LH	NOT NECESSARY	1,224.90	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	FENDER FRT/LH	TO REPAIR SEE LABOUR	723.40	-
1	DOOR FRT/LH	TO REPAIR SEE LABOUR	894.40	-
1	DOOR OUTER HANDLE FRT/LH	TO REPAIR SEE LABOUR	370.80	-
1	COVER,FRONT DOOR OUTSIDE HANDLE	TO REPAIR SEE LABOUR	14.10	-
1	MOULDING BODY ,LH	TO REPAIR SEE LABOUR	673.60	-
1	DOOR RR/LH	TO REPAIR SEE LABOUR	954.50	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			7,168.30	387.64
LABOUR				
PANEL BEATING & BODY WORK,INCLUSIVE OF THE REPAIR OF DOOR FRT/LH,DOOR OUTER HANDLE FRT/LH,COVER,FRONT DOOR OUTSIDE HANDLE,MOULDING BODY ,LH,DOOR RR/LH,FENDER RR/LH AND BUMPER REAR .			1,014.00	500.00

Report Ref No. CC3/CTI18005172/Spb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		2,808.00	1,400.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,402.00	1,960.00
GRAND TOTAL			11,570.30	2,347.64

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	-----------------

Report Ref No. CC3/CTI18005172/Spb3q2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.