

# PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg  
GST:201006949C RCB NO:201006949C

**M/S :** NG WAI FUN KELLY  
2 JALAN TIGA RATUS #01-06  
SINGAPORE 488067

**Estimate No:** EST1503434  
**Date:** 19 Mar 2018  
**Policy No:** 17-MV004774-R01  
**Veh Reg No:** SKB5880C  
**Make/Model:** MERCEDES BENZ C 180  
**Chassis No:** WDD2040492A540921  
**Engine No:** 27182030226547  
**Reg. Date:** 14/06/2011

**ATTN:** AXA INSURANCE PTE LTD  
**Your Ref No:** TP 0318-4993  
**Claim Type:** Third Party  
**Accident Date:** 17/03/2018  
**TP Veh Reg No:** YN9408D

## Estimate Repair Cost to Vehicle No :SKB5880C

| Description                                                          | U/Price  | Quantity           | Price                | Amount      |
|----------------------------------------------------------------------|----------|--------------------|----------------------|-------------|
|                                                                      |          |                    | <u>SS</u>            | <u>SS</u>   |
| <b>List Price</b>                                                    |          |                    |                      |             |
| 1 REAR BUMPER                                                        | 1,500.00 | 1 PC <i>Deepen</i> | 1,500.00             | <i>X</i>    |
| 2 REAR BUMPER SIDE HOLDER - LH                                       | 40.00    | 1 PC <i>11</i>     | 40.00                | <i>X</i>    |
| 3 REAR BUMPER SIDE HOLDER - RH                                       | 40.00    | 1 PC <i>11</i>     | 40.00                | <i>X</i>    |
| 4 REAR BUMPER CLIPS                                                  | 6.00     | 10 PC <i>11</i>    | 60.00                | <i>X</i>    |
| 5 TAIL LAMP ASSY - RH                                                | 790.00   | 1 PC <i>11</i>     | 790.00               | <i>X</i>    |
|                                                                      |          |                    | 2,430.00             |             |
|                                                                      |          | Less 10%           | 243.00               | 2,187.00    |
| <b>Special Net</b>                                                   |          |                    |                      |             |
| 6 REAR BUMPER SENSOR (4PCS)                                          | 440.00   | 1 SET <i>11</i>    | 440.00               | <i>X</i>    |
| 7 REAR BUMPER LOWER SPOILER                                          | 1,800.00 | 1 PC               | 1,800.00             | <i>?</i>    |
| 8 REAR BUMPER STICKER                                                | 350.00   | 1 SET <i>11</i>    | 350.00               | <i>300</i>  |
|                                                                      |          |                    | 2,590.00             | 2,590.00    |
| <b>Labour</b>                                                        |          |                    |                      |             |
| 9 TO KNOCK OUT DENTS, RH REAR FENDER, REMOVE, REPLACE ACCIDENT PARTS | 500.00   | 1 JOB              | 500.00               | <i>300</i>  |
| 10 TO RESPRAY PAINT ON ACCIDENT PORTIONS                             | 700.00   | 1 JOB              | 700.00               | <i>400</i>  |
| 11 TO CHECK WIRING                                                   | 20.00    | 1 JOB              | 20.00                | <i>✓</i>    |
| 12 TO REMOVE, REFIX REAR GARNISH                                     | 80.00    | 1 JOB              | 80.00                | <i>60</i>   |
| 13 TO TRANSFER REAR BUMPER SENSOR                                    | 100.00   | 1 JOB              | 100.00               | <i>50</i>   |
|                                                                      |          |                    | 1,400.00             | 1,400.00    |
|                                                                      |          |                    | Total                | SS 6,177.00 |
|                                                                      |          |                    | Add GST @ 7%         | 432.39      |
|                                                                      |          |                    | Total Amount Payable | SS 6,609.39 |

TOTAL - SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED AND NINE AND CENTS THIRTY NINE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

*Not Allowed*  
*11/11*  
*2/5/18*  
*30/4/18*  
*To keep photo attached*