

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

21 MAR 2018

Estimate No. : b1 46315 Page No. : 1 of 2
Date Estimated : 21/03/2018
Prepared By : Merina Chia San San

- ESTIMATE REPAIR FOR -
Kam You Kin (Gan YaoJian)
2L Limau Garden

Singapore 465921

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFY3880D	DD87413	16/07/2014	740LiA	0

DESCRIPTIONVALUE

To replace rear bumper including attachments etc and
to knock out dented area caused by accident

1700 2,550.00

To paint rear bumper and bootlid

1868 2,076.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

Sundries.

? 80.00

Total Labour 1: 5,154.00

DESCRIPTIONQTYPRICVALUE

RR BUMPER LH MOUNT

1 198.30

198.30

RR BUMPER RH MOUNT

1 198.30

? 198.30

RR BUMPER LOWER TRIM (PRIMED)

1 224.45

de 224.45

RR BUMPER CTR GUIDE

1 51.50

? 51.50

ADAPTER

1 81.00

? 81.00

RR BUMPER CARRIER

1 800.80

? 800.80

RR BUMPER PANEL PRIMED

1 1,496.35

de 1,496.35

COVER TOW FITTING REAR PRIMED

1 50.65

? 50.65

MODEL LETTERING 740LI

1 62.55

ne 62.55

DECOUPLING RING PDC TORQUE CONVERTE

4 5.05

ne 20.20

BUMPER PDC SENSOR (A90 SOPHISTOGRAU

2 368.80

? 737.60

Total Parts : 3,921.70

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46315
Date Estimated : 21/03/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFY3880D	DD87413	16/07/2014	740LiA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>21/3/18</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495749</u>	Authorised Yes / No _____
Authorised Date <u>WP</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail <u>tanjiah@lkkauto.com</u>	
No. of Working Days Recommend <u>5 days</u>	

Labour 1	:	5,154.00
Parts	:	3,921.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	635.30
Grand Total	:	<u>9,711.00</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **