

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

20/3/18

Registered in Merimen:

20/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 1976 L

Name of Insured:

Chen Ngai Hui

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

20/03/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Chen Yim Yow

Driver Tel No.:

96578095 (V/L-YES/NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJL 9011 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hock wah



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

DATE / PIC

SJL 9011 C - 02/11/17 307042/1/0132; R00 20/03/18
SKU 1976 L - X

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

2/4/18

spoke to OI, he confirmed the accident details. Informed TP claim and he agree to settle.

RECEIVED 16 APR 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Anysia

Email

Call

Final Liability:

%

100

(Agreed)

(Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2728.50

Loss of Rental (LOR):

S\$

300.00

(3 days)

x100

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

Total:

S\$

3030.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3030.50

Name 1:

HOCK WAH MOTOR WORKSHOP PTE LTD

Payee 2: (Strike if N.A.)

S\$

Payee 2:

Payee 3: (Strike if N.A.)

S\$

Payee 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
6/4/18

(06/11/13) waf

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SSL 9011 Cat Workshop m/s Wodendy

of _____

Insured: SKU1976L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 13

IDAC Accident Rpt: _____ Consistent? : Yes or No

CA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

01/21
Vehicle: IN / OUTDate / Time Action / Instruction L14 6636 9m.LIS - \$ 25504 (Red: \$ 2910.00 / 53%)Veh No: SSL 9011 C Yr Regn: 12 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA1Make: Hyundai Avante C.C. 159Colour: Black A/C: Insured / Std / NI / NASp. Reading: 15100 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHOU4BR9U634480Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: COMFORTMAX

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 Rear: 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/3/18 D.O.I. 23/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) ☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/AIG18005307/Uua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 21-03-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 1976L	Veh. Inspected	SJL 9011C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/03/2018	Inspection Date		
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4
#01-200B/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C. No: 200104141D - GST Reg. No: 20-0104141-D

TO : 53350112A
GIFTED CREATIONS
NO

SINGAPORE
TEL: FAX:
PH:
ATTN:

Term:

ESTIMATE BILL

Number : EB00004773
Date : 21/03/2018
Case No : AD00009622
Vehicle No : SJL9011C
Chassis : KMHIDU41BR9U63448
Year of Mfr : 2008
Policy No : 5096554054
Model : HYUNDAI HD
AVANTE 1.6 A

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	985.00	20	788.00
2	BOOTLID LOGO - S	1.0	27.00	20	21.60
3	BOOTLID LOGO - AVANTE	1.0	31.00	20	24.80
4	BOOTLID EMBLEM	1.0	29.00	20	23.20
5	TAIL LAMP LH	1.0	282.00	20	225.60
6	TAIL LAMP RH	1.0	282.00	20	225.60
7	TAIL LAMP CLIP LH	4.0	3.50	20	11.20
8	TAIL LAMP CLIP RH	4.0	3.50	20	11.20
9	TAIL LAMP PANEL LH	1.0	175.00	20	140.00
10	END PANEL	1.0	581.00	20	464.80
11	END PANEL TOP GARNISH	1.0	52.00	20	41.60
12	REAR BUMPER WITH RETAINER	1.0	447.00	20	357.60
13	REAR BUMPER REINFORCEMENT	1.0	270.00	20	216.00
14	REAR BUMPER SPONGE	1.0	129.00	20	103.20
15	REAR BUMPER BRACKET RH	1.0	79.00	20	63.20
16	REAR BUMPER BRACKET LH	1.0	79.00	20	63.20
17	REAR FENDER INNER SHIELD RH	1.0	27.00	20	21.60
18	REAR FENDER INNER SHIELD CLIP RH	8.0	3.50	20	22.40
19	REAR RADIO ANTENNA	1.0	94.00	20	75.20
List Price - Parts Sub Total					2,900.00
20	REAR FENDER LH - REPAIR	1.0			
21	REAR FENDER RH - REPAIR	1.0			
22	SPARE TYRE PANEL - REPAIR	1.0			
23	REVERSE SENSOR	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					3,180.00
24	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
25	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
26	ANTI-RUST COATING	1.0	250.00	0	250.00
27	WIRING	1.0	80.00	0	80.00
28	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,280.00

E. & O. E.

Let's Auto Consultants hence notify the Reparer of the following:
• To resurvey before/after spray painting
• To replace damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Signature

Page 1 of 2

Issued by : Anysia

HOCK WAH MOTOR WORKSHOP PTE LTD

HEK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 K121
R.O.C No. 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A
GIFTED CREATIONS
NO

SINGAPORE
TEL : FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00004773
Date : 21/03/2018
Case No : AD00009622
Vehicle No : SJL9011C
Chassis : KMHDU41BR9U63448
Year of Mfr : 2008
Policy No : 5096554054
Model : HYUNDAI HD
AVANTE 1.6 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : FIVE THOUSAND EIGHT HUNDRED FORTY-TWO AND CENTS TWENTY ONLY			Less Excess		0.00
			SUBTOTAL		5,460.00
			GST 7.00%		382.20
			TOTAL		5,842.20

Date of accident : 21/03/2018 07:30 AM. Place : SLIP ROAD OF BUKIT TIMAH ROAD FROM CTE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



[Advanced Search](#)
[Home](#) > [Used Cars](#) > [Ong Karz Konzept Pte Ltd](#) > [Hyundai Avante 1.6A](#)

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)

Vehicle Number Plates



Hyundai Avante 1.6A

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price Est. Price	\$11,800
Depreciation (Est. Price)	\$12,320 /yr View models with similar depreciation
Reg Date	14-Nov-2008 (7mths 18days COE left)
Manufactured	2008
Mileage	139,500 km (14.9k /yr)
Transmission	Auto
Engine Cap	1,591 cc
Road Tax	\$738 /yr
Power	89.7 kW (120 bhp) View specs of the Hyundai Avante (2007-2011)
Curb Weight	1,264 kg

Features
 1.6L DOHC CVT Engine, Smooth 4 Speed Automatic Transmission, Digital Climatic Aircon Control, ABS Braking System, SRS Airbags

Accessories
 Leather Seats, Sports Rims, CD Player, Reverse Sensors, Solar Film, Auto Fold Mirror

Description
 Well Maintained By Previous Owner, Tip Top Condition, Low Fuel Consumption, Low Insurance Premium, Low Maintenance, Bank And In-House Loan Available, Low Down Payment With Flexible Scheme. Just Ease Your Mind With \$5000 Drive Off. Call Us For Viewing. Test Drive Most Welcome!

COE	\$11,801	
OMV	\$11,942	
ARF	\$11,942	
Dereg Value	\$6,848 as of today (change)	
No. of Owners	2	
Type of Veh	Mid-Sized Sedan	
Category	RAAF Car	
Availability	Available	

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 03-Mar-2018 | Last Updated on: 03-Mar-2018

Tags: Hyundai Avante, 2008 Hyundai Avante, Hyundai Avante, Used Hyundai

Upfront Payment

[more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$4,140 (change)	Maximum 70% Loan
1st Instalment	\$1,404	
Total Upfront Payment	\$5,569 (excluding Insurance)	

Estimates based on 39% loan at 2.98% interest rate. Check with seller for exact figure.



Seller Information

Company	Ong Karz Konzept Pte Ltd • Dealer's profile • 0 vehs sold 8 vehs available	
Address	13 Kall Bukit Road 4 #03-29 Search cars nearby this location	
Location	Gardley Bz Centre	
Office No	68441184	
Contact Person(s)	Peter Daniel Danny Zeter	98244302 96779645 94553982 91887025

Useful Services

	Make sure of this car condition with STA Evaluation. Vehicle Evaluation
	Find out the market value for your car. Get a free Car Valuation. Free Valuation

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A
GIFTED CREATIONS
NO

SINGAPORE
TEL: FAX:
PH:
ATTN:

Term:

ESTIMATE BILL

Number : EB00004773
Date : 21/03/2018
Case No : AD00009622
Vehicle No : SJL9011C
Chassis: KMHU41BR9U63448
Year of Mfr 2008
Policy No 5096554054
Model : HYUNDAI HD
AVANTE 1.6 A

not authorized
date
2/5/8
4/5/8
23/3/18
to be paid other way

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	985.00	20	788.00
2	BOOTLID LOGO - S	1.0	27.00	20	21.60
3	BOOTLID LOGO - AVANTE	1.0	31.00	20	24.80
4	BOOTLID EMBLEM	1.0	29.00	20	23.20
5	TAIL LAMP LH	1.0	282.00	20	225.60
6	TAIL LAMP RH	1.0	282.00	20	225.60
7	TAIL LAMP CLIP LH	4.0	3.50	20	11.20
8	TAIL LAMP CLIP RH	4.0	3.50	20	11.20
9	TAIL LAMP PANEL LH	1.0	175.00	20	140.00
10	END PANEL	1.0	581.00	20	464.80
11	END PANEL TOP GARNISH	1.0	52.00	20	41.60
12	REAR BUMPER WITH RETAINER	1.0	447.00	20	357.60
13	REAR BUMPER REINFORCEMENT	1.0	270.00	20	216.00
14	REAR BUMPER SPONGE	1.0	129.00	20	103.20
15	REAR BUMPER BRACKET RH	1.0	79.00	20	63.20
16	REAR BUMPER BRACKET LH	1.0	79.00	20	63.20
17	REAR FENDER INNER SHIELD RH	1.0	27.00	20	21.60
18	REAR FENDER INNER SHIELD CLIP RH	8.0	3.50	20	22.40
19	REAR RADIO ANTENNA	1.0	94.00	20	75.20
List Price - Parts Sub Total					2,900.00
20	REAR FENDER LH - REPAIR	1.0			
21	REAR FENDER RH - REPAIR	1.0			
22	SPARE TYRE PANEL - REPAIR	1.0			
23	REVERSE SENSOR	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					3,180.00
24	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
25	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
26	ANTI-RUST COATING	1.0	250.00	0	250.00
27	WIRING	1.0	80.00	0	80.00
28	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,280.00

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Signature:
Type:

Page 1 of 2

Issued by : Anyisia

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A
GIFTED CREATIONS
NO

SINGAPORE
TEL : FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00004773
Date : 21/03/2018
Case No : AD00009622
Vehicle No : SJL9011C
Chassis: KMHDU41BR9U63448
Year of Mfr 2008
Policy No 5096554054
Model : HYUNDAI HD
AVANTE 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : FIVE THOUSAND EIGHT HUNDRED FORTY-TWO AND CENTS TWENTY ONLY			Less Excess		0.00
			SUBTOTAL		5,460.00
			GST 7.00%		382.20
			TOTAL		5,842.20

Date of accident : 21/03/2018 07:30 AM. Place : SLIP ROAD OF BUKIT TIMAH ROAD FROM CTE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18005307/Uua3

03 APRIL 2018

CHEW NGEE HUAT
12 SELATAR HILLS DR
SINGAPORE 807028

Dear Sir/Madam,

ACCIDENT INVOLVING SKU 1976L & SJL 9011C ON 21/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, GIFTED CREATIONS ("the third party claimant")
of - 46 East Coast Road #07-03 East Gate S (428766) (address),
owner of SJL9011C (vehicle no.) hereby authorize
HOCK WAH MOTOR WORKSHOP PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJL9011C that was
damaged pursuant to the accident which occurred on 21/03/2018 (date) along
SLIP ROAD OF BUKIT TIMAH RD FROM CTE (location)
involving vehicle no/s SKU1976L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 21 day of MARCH (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, HOCK WAH MOTOR WORKSHOP PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 2728.50 (repair costs), S\$ 300.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SJL9011C that was damaged pursuant to the accident which occurred on 21/03/2018 (date) along SLIP ROAD OF BUKIT TIMAH RD FROM CTE (location) involving vehicle no/s SKU 1976L.

This is pursuant to the inspection conducted on 23/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GIFTED CREATIONS ("third party claimant") of vehicle no. SJL9011C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJL9011C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 day of 04 (month) 2018 (year)



cks

Signed by AIG appointed surveyor

Am

Chopped & Signed by "the workshop"



HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A

AIG Asia Pacific Insurance Pte Ltd
NO 78 Shenton Way
07-16 CHARTIS Building
SINGAPORE 079120
TEL : 1800 4193000 FAX : 68357416
PH :
ATTN :

TAX INVOICE

Number : IV00054671
Date : 03/04/2018
Case No :
Vehicle No : SJL9011C
Chassis : KMH DU41BR9U63448
Year of Mfr : 2008
Policy No : 5096554054
Model : HYUNDAI HD
AVANTE 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	LUMPSUM REPAIR	1.0	2,550.00	0	2,550.00
	Sub Total				2,550.00
	Parts Total				2,550.00
SINGAPORE DOLLARS : TWO THOUSAND SEVEN HUNDRED TWENTY-EIGHT AND CENTS FIFTY ONLY			Less Excess		0.00
			SUBTOTAL		2,550.00
			GST 7.00%		178.50
			TOTAL		2,728.50

Date of accident : 21/03/2018 07:30 AM. Place : SLIP ROAD OF BUKIT TIMAH ROAD FROM CTE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

Amy
AUTHORISED SIGNATURE



H W CAR RENTAL

Registration no.: 52902602C
3011 Bedok Industrial Park E
#01-2010 Singapore 489977
Tel: 6441 5655 / 8339 6888

CINV - 200019

INVOICE

Refer to Rental Agreement: CRA - 200019

Reference Vehicle: SJL 9011C

Date: 26/03/18

Customer Information

Name: FONG CHEE AN MANFRED @ DAVID NRIC No.: S 16224572

Address: BLK 549 BEDOK NORTH AVE 1 #03-462

S (460549) Contact No: 9728 6610

Rental Car Information

Vehicle No.: SFV24474

Make & Model: TOYOTA ALTIS

Start Date: 23 / 03 / 18 11:40hrs

End Date: 26 / 03 / 18 16:00hrs

Rent for (No. of Days) 3

Rate at (Per Day) \$ 100.00

Total Amount \$ 300.00



Customer Signature



Authorized Signature

H W CAR RENTAL

Registration no.: 52902602C
3011 Bedok Industrial Park E
#01-2010 Singapore 489977
Tel: 6441 5655 / 8339 6888

R.Vehicle No. SJL 9011C**CRA# -200019****RENTAL AGREEMENT - CLAIM****Hirer's Particulars**

Name: FONG CHEE AN MANFRED @ DAVID NRIC No.: S16224577
Address: BLK 549 BEDOK NORTH AVE 1 #03-462
S (460549) Contact No: 97286610
Licence Date: 14 / 11 / 1994 Birth Date: 25 / 07 / 1963

Additional Driver's Particulars

Name: _____ NRIC No.: _____
Licence Date: ____ / ____ / ____ Contact No: _____

Rental Vehicle

Vehicle No.: SFV2447U Start Date: 23 / 03 / 18
Rate (Per day): _____ No. of days: _____ End Date: 26 / 03 / 18
PL (Out): _____ PL (In): OK / Time out/in: 11:40hrs 16:00hrs

The Hirer agreed to the Rental Agreement as followed: -

- ☐ Rental vehicle is restricted to SINGAPORE use only, check water and engine oil daily.
- ☐ No refund if vehicle return early.
- ☐ Hirer is liable to pay all fines, summons, claims, excess within rental period.
- ☐ Hirer shall bear the responsibility if any damages found on/in vehicle.
- ☐ Extension: One day in advance notice is required otherwise no extension will be allowed.
- ☐ Car collection and return shall be within the office operating hour.
- ☐ Excess: In the event when accident occurred, the Hirer is liable to bear the excess of at least S\$4,000 / S\$8,000 (Young, Inexperience Driver) in cash plus loss of earnings.

Any problem arises to vehicle within rental period, Hirer must inform 6441 5655 immediately.

Hirer acknowledges all T&C and signifies acceptance upon signing.



Hirer and Driver Signature

23/03/18

Date & Company Stamp (if any)



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-042638

Date of Request: 21/03/2018

Your Ref No: Online Purchase

Hock Wah Motor Workshop Pte Ltd
Blk 3011, Bedok Industrial Park E,
#01-2008/2010/2012
Singapore 489977

Dear Sir/Madam,

Enquiry Date 21/03/2018
Enquiry By Anyisia Foo Mei Yan
TP Vehicle No. SKU1976L
Accident Date 21/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-042638

Date of Request: 21/03/2018

Your Ref No: Online Purchase

Hock Wah Motor Workshop Pte Ltd
Blk 3011, Bedok Industrial Park E,
#01-2008/2010/2012
Singapore 489977

Dear Sir/Madam,

Enquiry Date 21/03/2018
Enquiry By Anyisia Foo Mei Yan
TP Vehicle No. SKU1976L
Accident Date 21/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKU1976L	AIG Asia Pacific Insurance Pte. Ltd.	09/07/2017-08/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2018 Edit Reg		23 Mar 2018 00:00 Edit Adj Rpt	\$42,550.00 Edit Estimates	\$42,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	CHEW NGEE HUAT , ID: S01885521		
Main Claimant:	GIFTED CREATIONS , Co. Reg. No.: 53350112A		
Vehicle Reg. No.:	SJL9011C	Date of Loss:	21/03/2018 07:00 - :59 [111 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8643260984SG	Policy/Cover Note No.:	2100420403
Vehicle Reg. No. (Insured):	SKU1976L	Policy No. (Claimant):	5096554054
		Excess:	
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/04/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL9011C (8643260984SG)
[SKU1976L]

TP
GIFTED CREATIONS
Mar 21 2018 7:00AM
[CHEW NGEE HUAT]
Hock Wah Motor Workshop Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			▼		
Letters/Correspondences															1 per page			▼			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit					
Photos/Images															3 per page			▼			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	24/03/18 16:19		Chassis Number															Load JPG			☒		
2	24/03/18 16:19		General View															Load JPG			☒		
3	24/03/18 16:19		Odometer Reading															Load JPG			☒		
4	24/03/18 16:19		General View															Load JPG			☒		
5	24/03/18 16:19		General View															Load JPG			☒		
6	24/03/18 16:19		General View															Load JPG			☒		
7	24/03/18 16:19		General View															Load JPG			☒		
8	24/03/18 16:19		General View															Load JPG			☒		
9	24/03/18 16:19		General View															Load JPG			☒		
10	24/03/18 16:19		General View															Load JPG			☒		
11	24/03/18 16:19		General View															Load JPG			☒		
12	24/03/18 16:19		General View															Load JPG			☒		
13	24/03/18 16:19		General View															Load JPG			☒		
14	24/03/18 16:19		General View															Load JPG			☒		
15	24/03/18 16:19		General View															Load JPG			☒		
16	24/03/18 16:19		General View															Load JPG			☒		
17	24/03/18 16:19		General View															Load JPG			☒		
18	24/03/18 16:19		General View															Load JPG			☒		
19	24/03/18 16:19		General View															Load JPG			☒		
20	24/03/18 16:19		General View															Load JPG			☒		
21	24/03/18 16:19		General View															Load JPG			☒		
22	24/03/18 16:19		General View															Load JPG			☒		
23	24/03/18 16:19		General View															Load JPG			☒		
24	24/03/18 16:19		General View															Load JPG			☒		
25	24/03/18 16:19		General View															Load JPG			☒		
26	24/03/18 16:19		General View															Load JPG			☒		
27	24/03/18 16:19		General View															Load JPG			☒		
28	24/03/18 16:19		General View															Load JPG			☒		
29	24/03/18 16:19		General View															Load JPG			☒		
30	24/03/18 16:19		General View															Load JPG			☒		
31	24/03/18 16:19		General View															Load JPG			☒		
32	24/03/18 16:19		General View															Load JPG			☒		
33	24/03/18 16:19		General View															Load JPG			☒		
34	24/03/18 16:19		General View															Load JPG			☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	24/03/18 16:19	General View	 Load JPG	☒
36	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
37	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
38	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
39	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
40	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
41	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
42	03/04/18 08:24	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/18 16:44	TP GIA REPORT	 Load PDF	
2	28/03/18 09:49	TP ESTIMATE - MARKED	 Load PDF	
3	28/03/18 09:50	TP GIA REPORT	 Load PDF	
4	18/04/18 08:24	WORKSHOP INVOICE	 Load PDF	
5	18/04/18 08:24	AUTHORISATION TO ACT FORM	 Load PDF	
6	18/04/18 08:24	Release Voucher	 Load PDF	
7	18/04/18 08:24	RENTAL RECEIPT	 Load PDF	
8	18/04/18 08:24	LETTER TO OI	 Load PDF	
9	18/04/18 08:24	GIA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/03/18 10:16	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKU1976L (Insd veh)	Model:	HYUNDAI AVANTE 1.6 HD (A)
	SJL9011C (TP veh)		
Date of Accident:	21/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	5,842.20
Final Repair Cost	:	\$	2,728.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	300.00 3 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,030.50
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hock Wah Motor Workshop Pte Ltd	:	\$ 3,030.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18005307/UUA3Q2

Date: 18/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100420403
 Claimant Vehicle No: SJL9011C Insured Vehicle No: SKU1976L
 Date of Loss: 21/03/2018 Nature of Claim: TP Claim No: 8643260984SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL9011C**
 Make & Model: HYUNDAI AVANTE, 1.6 HD (A) Engine No: G4FC8U554053
 Reg. Date: 16/12/2008 (Man. Year: 2008) Chassis No: KMHU41BR9U634480
 Colour: Black Odometer: 185500 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Comforser 6 mm Rear Left Side: Comforser 6 mm
 Front Right Side: Comforser 6 mm Rear Right Side: Comforser 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,180.00	1,797.60	1,382.40	43.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,430.00	850.00	37.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,460.00	3,227.60	2,232.40	40.89
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	5,460.00	2,550.00	2,910.00	53.30
+ GST 7.00/7.00% (S\$)	382.20	178.50	203.70	53.30
Nett Amount (S\$)	5,842.20	2,728.50	3,113.70	53.30
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,030.50		

INSPECTION

Date of Assignment: 23/03/2018
 Date Inspected: 23/03/2018 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-

2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	985.00 FL	*985.00 FL
2	1		*BOOTLID LOGO-S	Necessary	27.00 FL	*27.00 FL
3	1		*BOOTLID LOGO-AVANTE	Necessary	31.00 FL	*31.00 FL
4	1		*BOOTLID EMBLEM	Necessary	29.00 FL	*29.00 FL
5	1		*TAIL LAMP LH	Not Necessary	282.00 FL	*- FL
6	1		*TAIL LAMP RH	Not Necessary	282.00 FL	*- FL
7	4		*TAIL LAMP CLIP LH	Not Necessary	14.00 FL	*- FL
8	4		*TAIL LAMP CLIP RH	Not Necessary	14.00 FL	*- FL
9	1		*TAIL LAMP PANEL LH	Repair	175.00 FL	*- FL
10	1		*END PANEL	Repair	581.00 FL	*- FL
11	1		*END PANEL TOP GARNISH	Not Necessary	52.00 FL	*- FL
12	1		*REAR BUMPER WITH RETAINER	Dented / Deformed	447.00 FL	*447.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Cracked	270.00 FL	*270.00 FL
14	1		*REAR BUMPER SPONGE	Torn	129.00 FL	*129.00 FL
15	1		*REAR BUMPER BRACKET RH	Bent	79.00 FL	*79.00 FL
16	1		*REAR BUMPER BRACKET LH	Not Necessary	79.00 FL	*- FL
17	1		*REAR FENDER INNER SHIELD RH	Not Necessary	27.00 FL	*- FL
18	8		*REAR FENDER INNER SHIELD CLIP RH	Not Necessary	28.00 FL	*- FL
19	1		*REAR RADIATOR ANTENNA (CRACKED)	Not Consistent With The Impact	94.00 FL	*- FL
20	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
22	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
23	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,905.00	2,197.00
- List Item Discount on L Items 20.00/20.00% (S\$)	725.00	399.40
Total Parts (S\$)	3,180.00	1,797.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	700.00
3	ANTI-RUST COATING	New	250.00	60.00
4	WIRING	New	80.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			2,280.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >