

2/10/2018

ASS. REC. BY:

REF:

CS/MSG18005316/Acbn2

Special Instruction:

Surveyor

Merman

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG1

Date/Time: 21032018 4:11 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 1222L

Insured:

XE 224K

at Workshop m/s

Premium

Tel:

of

35 Ubi Rd 1

Policy No:

B29067573 MKF

Claim No:

5441211

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 1222L - CS/MSG18005316/Acb

DCA: 140218

27/3/18 @ 3:16pm revised to Jasmine Lok via Merman.

30/3/18 @ 5:42pm confirmed with Mr Bao final fig \$7751.90, 5 days by email.

(Red & 7070.10, 217.)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05/18/18 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC1222L Yr Regn: 2017 / DecType: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan. c.c. 999.Colour: Grey. A/C: Insured / Std / NI / NASp. Reading: 4490. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228V7J1032826Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 05/03/18Survey held at Premium.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPMS16.

[Signature]
30/5/2018

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

11/01/16 TPMS16

Date/Time, File Return to?

2)

Report Format: NET-TPLump Sum / I.B.I: (\$) 2251.90Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

200

10

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005316/Aqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 224K	Veh. Inspected	SLC 1222L
Policy No.	B29067573MKF	Coverage (\$)	0.00
Claim No.	549141	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/02/2018	Inspection Date	05/03/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 22 Mar 2018

Preliminary Advice

Insured Vehicle No	: XE224K	Accident Date	: 06/02/2018
TP Vehicle No	: SLC1222L	Assignment Date	: 21/03/2018
Make	: AUDI A3	Est. Duration of Repair	: 5.00
Date of Inspection	: 05/03/2018		
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,822.00
Revised Amount	:S\$	7,548.00
Check Items (Estimated)	:S\$	801.00
Total	:S\$	8,349.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		21 Mar 2018 16:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BEN FOODS (S) PTE LTD, Co. Reg. No.: UEN : 196900017H		
Main Claimant:	TAN CHIEW BOO, ID: S7040734E		
Vehicle Reg. No.:	SLC1222L	Date of Loss:	06/02/2018 12:00 - :59
Claim Type:	TP / 549141	Policy/Cover Note No.:	B29067573MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	XE224K	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2018]		
Driver/Custodian (Insured):	YUSRI BIN SAMAD (), NRIC: S6842797E		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 30 May 2018 5:42 PM
To: Boo seng yak
Cc: CS A Team; Admin A; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION - SLC1222L - TP MSIG - SURVEYED 5 MAR 18 *** LKK REF: CS/MSG18005316/Aqb

Dear Mr Boo,

Confirm final fig \$7,751.90 before GST and 5 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 21 May 2018 3:58 PM
To: Boo seng yak <boojohnny@gmail.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: FINAL REVISION - SLC1222L - TP MSIG - SURVEYED 5 MAR 18 *** LKK REF: CS/MSG18005316/Aqb

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/MSG18005316/Aqb	Shiau Chan

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Monday, 21 May, 2018 8:59 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 15:42
Date Of Accident	06/02/2018 12:20
Exact Location Of Accident	PENJURU ROAD NEAR WEST COAST ROAD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC1222L
Insured/Policyholder	
Name Of Registered Owner	TAN CHIEW BOO
NRIC No	S7040734E
Email Address	EDDYTAN12@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97505171
Alternative Phone No	OTHERS-91136088

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700088863
Cover Note Number	

Driver

Name of Driver	TAN CHIEW BOO
NRIC No	S7040734E
Date Of Birth	12/11/1970
Occupation	INDOOR
Date Of Driving Pass	12/05/1992
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97505171
Fax Number	
Contact Number	OTHERS-91136088
Email Address	EDDYTAN12@YAHOO.COM

Address	BLK 101 HILLVIEW RISE #23-03
Postcode	667981
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PENJURU ROAD AND STOP AT TRAFFIC LIGHT (WEST COAST ROAD JUNCTION). THE LORRY BEHIND ME COLLIDED INTO MY REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE224K
Vehicle Make/Model/Colour	RED
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	YUSRI BIN SAMAD
NRIC/Passport Number	S6842797E
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

06/feb/2018
1430hrs


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: LYN KEE SENG
NRIC/FIN No.: 98521641M

Sketch Plan #2

SKETCH PLAN

Perijum Road Near West Coast. A: SLC 1222 L
B: XE 224 K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Perijum Road and stop at traffic light (west coast rd junction)

The lorry behind me collided into my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

06 Feb 2018
1430hrs.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Liza Koo Geng

NRIC/FIN No: 48352569M

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7040734E**

Name:

TAN CHIEW BOO

Birth Date: **12 Nov 1970**

Issue Date: **29 Apr 2003**



000432685K

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7040734E**



Name:

TAN CHIEW BOO

陈秋武

Race:

CHINESE

Date of Birth:

12-11-1970

Sex:

M

Country of Birth:

SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

12 May 1992



Licence No: S7040734E

NP 428A



0387351

NRIC No. **S7040734E**



Blood Group:

O+

Date of issue:

17-06-1992

APT BLK 820 YISHUN STREET 81 #10-648
SINGAPORE 760820

NRIC No: **S7040734E**

Date: **14-12-2000**

No: **3843814**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN CHIEW BOO
 Period of Insurance : 19 Dec 2017 To 18 Dec 2019
 Engine No. : CHZ602908
 Chassis No. : WAUZZZ8V7J1032826

Vehicle No. : SLC1222L
 Policy No. : 1700088863
 Endorsement No. :
 Issued Date : 27 Dec 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 185) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN CHIEW BOO - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63602323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125211

PREMIUM LEASING - NC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



Monile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Stephany Loh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0162/2018/NK
Date	:	17-Feb-18

Vehicle NOT in workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept
Tel: 6827 27692 - Fax: 6225 7402

Owner's Name	:	Mr. Tan Chiew Boo
Address	:	Blk 820 Yishun Street 81 #10-648 Singapore 760820
Telephone	:	HP +65 97505171
Type of Claim	:	Own Damage Claims
Policy No.	:	1700088863
Vehicle No	:	SLC 1222 L
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Dec-17
Engine No	:	CHZ602908
Chassis No	:	WAUZZZ8V7J1032826
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	06-Feb-18
Place of Accident	:	Penjuru Road Near West Coast Road Junction.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 1222 L.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓
3	To dismount and renew rear bumper and rear lid. Align to position. Reorganise rear crash management components. Reinstall all parts removed.	\$ 1,800.00 1800
4	To respray rear bumper and rear lid	\$ 1,500.00 1500
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL FRONT LABOUR CHARGES		: \$ 4,052.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Deformed</i>	\$ 1,697.00	✓
2	REAR SPOILER <i>Not New</i> <i>cra</i>	\$ 206.00	✓ <i>205.50</i>
3	REAR REINFORCEMENT <i>Not New</i>	\$ 501.00	? <i>x</i>
4	REAR BUMPER SPOILER LH / RH <i>Not New</i>	2 \$ 46.00	+
5	REAR BUMPER SENSOR INNER/ OUTER <i>Not New</i>	2 \$ 421.00	+
6	REAR LID <i>Deformed</i>	\$ 2,310.00	✓
7	REAR PARKING ADHESIVE <i>Not New</i>	\$ 15.00	✓ <i>14.50</i>
8	AUDI LOGO <i>2</i>	\$ 108.00	✓ <i>107.50</i>
9	REAR A3 EMBLEM <i>Not New</i>	\$ 83.00	✓ <i>82.70</i>
10	REAR TFSI EMBLEM	\$ 83.00	✓ <i>82.70</i>
11	SUNDRIES <i>Not New</i>	\$ 300.00	? <i>x</i>
TOTAL SPARE PARTS CHARGES		:	\$ 5,770.00
TOTAL LABOUR CHARGES		:	\$ 4,052.00
GRAND TOTAL		:	\$ 9,822.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 05/03/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 05 Rys.

Before Paint Required

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
22/3/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0162/2018/NK
Date : 17-Feb-18

Vehicle NOT in workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Hi Adrian

5 days - ok - jb - 21 May 18

Owner's Name : Mr. Tan Chiew Boo
Address : Blk 820 Yishun Street 81
#10-648
Singapore 760820
Telephone : HP +65 97505171
Type of Claim : Own Damage Claims
Policy No. : 1700088863
Vehicle No : **SLC 1222 L**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Dec-17
Engine No : CHZ602908
Chassis No : WAUZZZ8V7J1032826
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Feb-18
Place of Accident : Penjuru Road Near West Coast Road Junction.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 1222 L.

S/n	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	\$	280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	\$	280.00
3	To dismount and renew rear bumper and rear lid. Align to position. Reorganise rear crash management components. Reinstall all parts removed.		\$ 1,800.00	\$	1,200.00
4	To respray rear bumper and rear lid		\$ 1,500.00	\$	1,300.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL FRONT LABOUR CHARGES		:	<u>\$ 4,052.00</u>	<u>\$</u>	<u>3,252.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,697.00	\$ 1,697.00
2	REAR SPOILER	\$ 206.00	\$ 205.50
3	REAR REINFORCEMENT	\$ 501.00	
4	REAR BUMPER SPOILER LH / RH	2 \$ 46.00	
5	REAR BUMPER SENSOR INNER/ OUTER	2 \$ 421.00	
6	REAR LID	\$ 2,310.00	\$ 2,310.00
7	REAR PARKING ADHESIVE	\$ 15.00	\$ 14.50
8	AUDI LOGO	\$ 108.00	\$ 107.50
9	REAR A3 EMBLEM	\$ 83.00	\$ 82.70
10	REAR TFSI EMBLEM	\$ 83.00	\$ 82.70
12	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 5,770.00	\$ 4,499.90
TOTAL LABOUR CHARGES		\$ 4,052.00	\$ 3,252.00
GRAND TOTAL		\$ 9,822.00	\$ 7,751.90

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005316/AQBN2

Date: 01/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29067573MKF
Claimant Vehicle No :	SLC1222L	Insured Vehicle No :	XE224K
Date of Loss:	06/02/2018	Nature of Claim:	TP
		Claim No:	549141

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC1222L	Engine No:	CHZ602908
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V7J1032826
Reg. Date:	19/12/2017 (Man. Year: 2017)	Odometer:	4490 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,770.00	4,499.90	1,270.10	22.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,052.00	3,252.00	800.00	19.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,822.00	7,751.90	2,070.10	21.08
+ GST 7.00/7.00% (S\$)	687.54	542.63	144.91	21.08
Nett Amount (S\$)	10,509.54	8,294.53	2,215.01	21.08

INSPECTION

Date of Assignment:	21/03/2018	
Date Inspected:	05/03/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts: 144	AUDI A3 999cc TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC1222L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,697.00 FS	*1,697.00 FS
2	1		*REAR SPOILER	Cracked	206.00 FS	*205.50 FS
3	1		*REAR REINFORCEMENT	Not Necessary	501.00 FS	*- FS
4	2		*REAR BUMPER SPOILER LH/RH	Not Necessary	46.00 FS	*- FS
5	2		*REAR BUMPER SENSOR INNER/OUTER	Not Necessary	421.00 FS	*- FS
6	1		*REAR LID	Dented	2,310.00 FS	*2,310.00 FS
7	1		*REAR PARKING ADHESIVE	Necessary	15.00 FS	*14.50 FS
8	1		*AUDI LOGO	Necessary	108.00 FS	*107.50 FS
9	1		*REAR A3 EMBLEM	Necessary	83.00 FS	*82.70 FS
10	1		*REAR TFSI EMBLEM	Necessary	83.00 FS	*82.70 FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					Total Parts (S\$)	5,770.00 4,499.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.ALIGN TO POSITION.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,800.00	1,200.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	1,500.00	1,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,052.00	3,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >