

22/03/2018

ASS. REC. BY:

REF

CS/ QBE18005319/Kqd3er

Special Instructions:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Jenny Toh

of

QBE

Date/Time:

20/3/18 @ 4:30pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 7313 H

Insured:

at Workshop m/s:

SMRT (Sin Ming)

Tel:

6858 1234

of

176 Sin Ming Drive #04-16

Policy No:

Claim No:

VCO11280

Sum Insured:

Excess:

NIL

Make of Veh:

D.O.A.

15/03/2018

(Client's Record)

CA / ☒ REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:50am @ 21/3/18

Person Contacted:

Susan

Vehicle:

☒ IN / ☐ OUT

Date/Time

Action/Instruction

☒

Estimate

SJS 7313 H-X

21/3/18 @ 5:36pm revert to Jenny Toh by email. (repairer asking 68K P/P).

21/3/18 @ 2:18pm Joyce too informed C/A at 7K by email.

21/3/18 @ 4:39pm Informed Rajan C/A not more than 7K P/P & Ex: NIL by email.

finalised final fig 7000, 6 days. (Red 814153, 67%).

REF:

QBE

ASSIGNMENT

From:

Date: 21/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJS 7313 H

at Workshop m/s

SMRT (Sin Ming)

of

176 Sin Ming Drive #04-16

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

NIL

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

8 25k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS 7313 H

Yr Regn:

08 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo C30

C.C.

1999

Colour:

M. Blue

A/C

Insured / Std / NI / NA

Sp. Reading

122300

T/Radio: Insured / Std / NI / NA

Eng/No:

YV1MK 434BA 2173808

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 ER18

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

4 mm

L/Bal.

6 mm

L/Bal.

4 mm

D.O.A.

15/3/18

D.O.I.

21/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/3 13k parts Costumer

RECEIVED 20 JUN 2018

Date/Time: File Pass to?

☐

: Preli. Report

1) 20/6 13k parts

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + RS: SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Report Format :

00

Lump Sum / I.B.I. (\$)

7000

300

300

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE18005319/Kqd3

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 21-03-2018



Code : QBE

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJS 7313H
Policy No.	Coverage (\$)	0.00
Claim No. VC011280	Excess (\$)	0.00
Assign From JENNY TOH	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 15/03/2018	Inspection Date 21/03/2018
Survey held at 176 SIN MING DRIVE # 04-16	
Repairer SMRT AUTOMOTIVE SERVICES PTE LTD	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Tuesday, 20 March 2018 4:30 PM
To: assignments
Cc: Jenny Toh
Subject: SJS 7313H - 8-V0014375-MVA
Attachments: SAS2374632 (1).pdf; SJS7313H VOLVO.PDF

Our ref: VC011280

Dear Sir

Kindly survey the OD Claim


Insured: SJS7313H
2009 Volvo C30 2.0
Date of accident: 15/03/2018
Comprehensive
Excess: NIL

Survey & revert

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:TanSohChern@smrt.com.sg]
Sent: Tuesday, 20 March, 2018 4:09 PM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <theagarajan@smrt.com.sg>
Subject: SJS 7313H - 8-V0014375-MVA

Dear Jenny

We spoke earlier.

Our Reference : SJS7313H
DOA : 15 March 2018

✓ RE: Accident involving motor vehicle No. SJS7313H
ON 15/03/2018 ALONG LOYANG AVENUE

Attached is our client's SAS report and estimates for vehicle SJS 7313H for your perusal.

We would like to request for a Pre-Repair Survey of the vehicle. Vehicle is at premises of:

176 Sin Ming Drive
Sin Ming Autocare
#04-16
Singapore 575721.

We thank you in advance for your assistance in this matter.

Regards,

Susan Tan
Senior Admin Supervisor
Auto Svcs / Ext Biz Svcs / AR & SC
Email : tansohchern@smrt.com.sg
DID : +65 6858 1234



IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 23 March 2018 4:39 PM
To: theagarajan@smrt.com.sg
Cc: SUR
Subject: VEHICLE SJS 7313H (DOA: 15/03/2018)

Dear Rajan,

As spoken with you.

As instructed by our client QBE Insurance, please proceed to repair the insured vehicle **SJS 7313H** at repair cost not more than **\$7,000.00 on part by part basis (excess \$NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Friday, 23 March 2018 2:18 PM
To: Shiau Chan (LKKAuto)
Cc: assignments; SUR
Subject: FW: SJS 7313H - 8-V0014375-MVA

Our Ref. VC011280

Hi Shiau Chan

Please proceed to authorise repair at \$7000/-.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Jenny Toh
Sent: Friday, 23 March, 2018 2:03 PM
To: Joyce Foo <joyce.foo@qbe.com>
Subject: FW: SJS 7313H - 8-V0014375-MVA

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Friday, 23 March, 2018 11:20 AM
To: Jenny Toh <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJS 7313H - 8-V0014375-MVA

Dear Jenny,

Please be informed that according to the repairer, they willing to under the repair cost at \$7,000.00 (minimum) on part by part basis.

Kindly advise and noted the margin of repair is \$5,876.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 22 March 2018 5:36 PM
To: 'Jenny Toh' <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJS 7313H - 8-V0014375-MVA

Dear Jenny,

Enclosed herewith preliminary advice of SJS 7313H.
Repairer asking for repair cost at \$8,000.00 on part by part basis.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 21 March 2018 9:54 AM
To: 'Jenny Toh' <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJS 7313H - 8-V0014375-MVA

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh [<mailto:jenny.toh@qbe.com>]

Sent: Tuesday, 20 March 2018 4:30 PM

To: assignments <assignments@lkkauto.com>

Cc: Jenny Toh <jenny.toh@qbe.com>

Subject: SJS 7313H - 8-V0014375-MVA

Our ref: VC011280

Dear Sir

Kindly survey the OD Claim

Insured: SJS7313H

2009 Volvo C30 2.0

Date of accident: 15/03/2018

Comprehensive


Excess: NIL

Survey & revert

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [<mailto:TanSohChern@smrt.com.sg>]

Sent: Tuesday, 20 March, 2018 4:09 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <theagarajan@smrt.com.sg>

Subject: SJS 7313H - 8-V0014375-MVA

Dear Jenny

We spoke earlier.

Our Reference : SJS7313H

DOA : 15 March 2018

RE: Accident involving motor vehicle No. SJS7313H
ON 15/03/2018 ALONG LOYANG AVENUE

Attached is our client's SAS report and estimates for vehicle SJS 7313H for your perusal.

We would like to request for a Pre-Repair Survey of the vehicle. Vehicle is at premises of:

176 Sin Ming Drive
Sin Ming Autocare
#04-16
Singapore 575721.

We thank you in advance for your assistance in this matter.

Regards,

Susan Tan
Senior Admin Supervisor
Auto Svcs / Ext Biz Svcs / AR & SC
Email : tansohchern@smrt.com.sg
DID : +65 6858 1234



IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 22 March 2018 5:36 PM
To: 'Jenny Toh'; assignments
Cc: SUR
Subject: RE: SJS 7313H - 8-V0014375-MVA
Attachments: SJS7313H EST.pdf; CSQBE18005319Kqd3.pdf

Dear Jenny,

Enclosed herewith preliminary advice of SJS 7313H.
Repairer asking for repair cost at \$8,000.00 on part by part basis.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 21 March 2018 9:54 AM
To: 'Jenny Toh' <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJS 7313H - 8-V0014375-MVA

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh [<mailto:jenny.toh@qbe.com>]
Sent: Tuesday, 20 March 2018 4:30 PM
To: assignments <assignments@lkkauto.com>
Cc: Jenny Toh <jenny.toh@qbe.com>
Subject: SJS 7313H - 8-V0014375-MVA

Our ref: VC011280

Dear Sir

Kindly survey the OD Claim

Insured: SJS7313H
2009 Volvo C30 2.0



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: VC011280

Date: 22nd March 2018

Our Ref: CS/QBE18005319/Kqd3

Without Prejudice

The Motor Claims Department
QBE Insurance

Attn: Jenny

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SJS 7313H

We thank you for the instruction on 20/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/03/2018 at the premises of M/s SMRT (SIN MING) and have the following to report:-

Workshop Estimate Amount	: S\$ <u>21,153.00</u>
Revised Estimate Amount	: S\$ <u>7,987.00</u>
"Check" Items Amount	: S\$ <u>5,161.00</u>
Market Value	: S\$ <u>25,000.00</u>
LTA Reimbursement Value	: S\$ <u>19,124.00</u>
Nett Value	: S\$ <u>5,876.00</u>

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages consistent.
Repair cost not economical.
Repairer asking for repair cost at \$8,000.00 on part by part basis.
Days of repair: 6 days.
We have not authorized repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6627G
Vehicle Details	
Vehicle No.:	SJS7313H
Vehicle to be Exported:	No
Intended De-registration Date:	22 Mar 2018
Vehicle Make:	VOLVO
Vehicle Model:	C30 2.0L AT ABD D/AB 2WD 3DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	B4204S3170383
Chassis No.:	YV1MK434BA2173808
Maximum Power Output:	107.0 kW (143 bhp)
Open Market Value:	\$30,514.00
Original Registration Date:	31 Aug 2009
First Registration Date:	31 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$30,514.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2019
PARF Rebate Amount:	\$16,782.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$16,290.00
COE Rebate Amount:	\$2,342.00
Total Rebate Amount:	\$19,124.00

The information contained herein is correct as at 22 Mar 2018

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Hyundai Verna 1.4M (COE Till 12/22) At Only \$23,388



Cheapest (In Mkt) Lowest Depreciation! Best Condition! Don't Miss! Car Auto Connection StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)






Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

5 vehicles

VOLVO C30

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	VOLVO C30		Any	Any	2009	Any	Any	Any	Available
	Volvo C30 2.0A		\$25,888	\$8,490 /yr	22-Jun-2009	1,999 cc	82,000 km	Sports	Available
Comes With Free Front And Rear Camera! Free 1 x Servicing. Very Sporty And Unique Volvo C30 Coupe Hatchback! Very Well Maintained By Previous Owner With Major Servicing Been Done. Low Mileage. Acciden...									
Euro Performance Asia Pte Ltd									
Posted: 21-Mar-2018 Tags: 2009 Volvo C30, Volvo C30, Volvo, C30, Used Volvo									
	Volvo C30 T5		\$29,800	\$9,580 /yr	04-Aug-2009	2,521 cc	-	Sports	Available
Just Renewed Road Tax, 100% Genuine Mileage! Accident Free! Sparkling New Paint! Regular Maintenance And Servicing, Tip Top, Excellent Showroom Condition, No Repairs Required, Free 3 In-House Servicing...									
Posted: 16-Mar-2018 Tags: 2009 Volvo C30, Volvo C30, Volvo, C30, Used Volvo									
	Volvo C30 2.0A		\$26,588	\$7,970 /yr	25-Aug-2009	1,999 cc	100,000 km	Sports	Available
Graded B by STA									
Cheapest Coupe That You Can Find In The Market! Free 6 Or 12 Months Warranty Plus 1 Free Servicing! Very Well Maintained By Previous Owner With Major Servicing Been Done. Come With Free STA Elevation!...									
Posted: 09-Mar-2018 Tags: 2009 Volvo C30, Volvo C30, Volvo, C30, Used Volvo									
	Volvo C30 2.0A		\$28,688	\$8,590 /yr	16-Oct-2009	1,999 cc	-	Sports	Available
1 Owner Since Day 1, Car Is In Good Condition. Selling At Low Depreciation For A Sporty Continental Car.									
Posted: 04-Mar-2018 Tags: 2009 Volvo C30, Volvo C30, Volvo, C30, Used Volvo									
<div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> <div>Buy Tyres Online!</div> <div>Latest Special Offers from Tyrepack!</div> </div>									
	Volvo C30 T5		\$31,000	\$10,820 /yr	24-Jul-2009	2,521 cc	120,000 km	Sports	Available
Low-profile Hatchback That's One Of The Best Looking But It's Able To Carry It's Weight Well With MTE Stage 1 Tune. As Long As On Highway It's A Joy To Drive. Rewrapped Black Headliner, New Control Ar...									
Posted: 05-Feb-2018 Tags: 2009 Volvo C30, Volvo C30, Volvo, C30, Used Volvo									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used VOLVO C30, VOLVO C30 Singapore, used VOLVO C30 Singapore, used VOLVO C30, used vehicles Singapore or even buy used VOLVO C30 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- [Home](#)
- [New Car](#)
- [Used Car](#)
- [Sell Car](#)
- [Motoring Directory](#)
- [Products Guide](#)
- [Article](#)
- [Forum](#)
- [Tool & Tip](#)

- [About Us](#)
- [Careers](#)
- [Contact Us](#)
- [Sitemap](#)

© 2004-2018 sgCarMart. All rights reserved.

- [Terms of Service](#)
- [Privacy Policy](#)
- [Personal Data Protection Statement](#)

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/03/2018 15:37
Date Of Accident	15/03/2018 08:40
Exact Location Of Accident	LOYANG AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS7313H
Insured/Policyholder	
Name Of Registered Owner	EUGENE PHOEN YU JUN
NRIC No	S9006627G
Email Address	E.PHOEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91013035
Alternative Phone No	OFFICE-91013035

Vehicle Particulars	
Manufacturer	VOLVO
Model	C30-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0014375-MVA
Cover Note Number	

Driver	
Name of Driver	EUGENE PHOEN YU JUN
NRIC No	S9006627G
Date Of Birth	28/02/1990
Occupation	INDOOR
Date Of Driving Pass	28/02/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91013035
Fax Number	
Contact Number	OFFICE-91013035
EEmail Address	E.PHOEN@GMAIL.COM

Address 15E JALAN BERJAYA
Postcode 578634
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

WHILE I WAS DRIVING ALONG LOYANG AVE AT ABOUT 0840 HRS ON 15 MARCH 2018, THE VEHICLE INFRONT OF ME MADE AN EMERGENCY BRAKE. MY VEHICLE FRNT SJS7313H HIT ON TO THE REAR OF THE OTHER VEHICLE SKQ9589PAT APPROXIMATELY 20 KMH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ9589P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repeal/void policy liability.
4. The sole and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will be made available upon application of interested parties.
7. The judgement of the court is the insurers' responsibility. It is not the responsibility of the report at the centre and it does not constitute any liability to the parties.
8. I understand under the Personal Data Protection Act (PDPA) that I acknowledge, agree and consent that:
 - a. Any insurer, its workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and process my personal data/personal information set out in this (form) and any other personal information provided by me or assessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"; the insurers' lawyers/law firms; the Monetary Authority of Singapore and any relevant government agencies, such as the police, for the purpose of or
 - b. taking, handling, and processing my claims, including the settlement of the claims and any necessary investigations relating to my claims;
 - c. settling the accident and/or my claims;
 - d. carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - e. administering my claims (including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and packages); and/or
 - f. complying with applicable law, in administering, processing, handling, and/or releasing my claims.
9. I understand and agree that the Insurers and/or GIA may be permitted to collect, use, disclose and process my Personal Information for one or more of the above purposes, and my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above purposes.

Policyholder's Signature: [Signature] Date: 15 Mar 2018

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel [Signature]

please refer to the attached

Describe Circumstances of the Accident:


While driving along Layang Avenue at 0840am on 15 Mar 2018, the vehicle in front of me made an emergency brake. My vehicle front (SJ37313H) hit on to the rear of the other vehicle (SKQ9589P) at approximately 20km/h.

I declare the foregoing particulars are true in every respect.

125pm
15 Mar 2018

Signature of driver & vehicle owner

Witnessed by Reporting Officer
[Signature]



SMRT Vehicle Repair Estimate

Group : Buses / Taxis / **Commercial**

Reg. No. : SJS7313H

Make / Model : VOLVO C30

Chassis No : YV1MK434BA2173808

Name of Driver : EUGENE PHOEN YU JUN

Date/Time of Accident : 15/03/18 08.40

Surveyor is Required ? **YES**

If Yes, VICOM / LKK / AIS / Other MSIG : QBE

Vehicle is Towed Back YES

Date / Time :

Accident reporting date 15/3/2018

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / **Others**

Special Instruction to ARC, if any :

176 Sin Ming Drive, Sin Ming Autocare, #04-13,16, S(575721)


Ref. No. :

Reg. Date :

Mileage :

Rental/Replacement Vehicle : Yes / No

The damages on the vehicle are as indicated in the following diagram :



Signed :

Date :

Accident Repair Job Card I :

Date Prepared :

Summary of Repair Estimates

Repair Complete :

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charge : \$ 2,520.00

\$ -

Total Spray Painting Charge \$ 1,800.00

\$ -

Total Material Charge : \$ 16,833.00

\$ -

Other Charges :

\$ -

TOTAL : \$ 21,153.00

\$ -

Lump Sum Repair, if any :

No. of Repair Days : [7] days

[] days

Signature :

Prepared by:

Adjusted by:

QN No. :

Invoice No. :

Invoice Date :

Signed :

Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To apply rust proofing on affected area	\$ 102 200.00	X
To top up air cond gas	\$ 150.00	1000
To reset & diagnose system function	\$ 250.00	XMM ?
To check wiring system function	\$ 120.00	200
To remove & refix air con condenser , inner cooler , radiator assy & engine fan air cleaner	\$ 300.00	800
Labour to cutting knocking accident front bonnet , front bumper , fender rh & lh , support panel & wheel house rh & lh	\$ 1,500.00	800
Total Labour	\$2,520.00	\$0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray front bonnet , front bumper , front fender lh & rh , support panel & wheel house rh & lh	\$ 1,800.00	1100
Total Spray Painting & Panel Beating	\$1,800.00	\$0.00

Fax: 62564315

Not Asker
Presony B4 Nam
Ex MLR4
18

6 days

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	
Total Other Costs	\$0.00	\$0.00

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	cost price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	FRONT BONNET <i>Bu</i>	1	\$ 1,280.00				✓
	FRONT BONNET INSULATOR <i>Sn</i>	1	\$ 450.00				X
	FRONT BONNET HINGE LH	1	\$ 83.00			<i>R</i>	X
	FRONT BONNET HINGE RH	1	\$ 83.00			<i>R</i>	X
	FRONT BONNET SPRING HOO GAS <i>Sn</i>	1	\$ 138.00				X
	FRONT BONNET LOCK <i>Dis</i>	1	\$ 125.00				✓
	FRONT BONNET CABLE <i>SR</i>	1	\$ 90.00				X
	FRONT BUMPER <i>Bu</i>	1	\$ 1,980.00				✓
	FRONT BUMPER REINFORCMENT	1	\$ 465.00			<i>R</i>	X
	FRONT BUMPER ABSORBER	1	\$ 122.00			<i>Sn</i>	X
	FRONT BUMPER TOWING COVER LH <i>Sn</i>	1	\$ 43.00				X
	FRONT GRILLE <i>CM</i>	1	\$ 438.00				✓
	FRONT BUMPER CLIP <i>me</i>	10	\$ 40.00				✓
	FRONT BUMPER LOWER LIP <i>Sn</i>	1	\$ 295.00				X
	FRONT BUMPER FOG LAMP COVER RH <i>Sn</i>	1	\$ 50.00				X
	FORNT BUMPER FOG LAMP COVER LH <i>Sn</i>	1	\$ 50.00				X
	FRONT FOG LAMP LH <i>Sn</i>	1	\$ 195.00				X
	FRONT FOG LAMP RH <i>Sn</i>	1	\$ 195.00				X
	FRONT HEADLAMP LH	1	\$ 595.00			<i>Sn</i>	X
	FRONT HEAD LAMP RH <i>CM</i>	1	\$ 595.00				✓
	FRONT SUPPORT PANAL <i>R</i>	1	\$ 1,160.00				✓
	FRONT SUPPORT PANAL TOP GARNISH	1	\$ 42.00	<i>CM</i>			✓
	FRONT AIR DUCT	1	\$ 65.00			<i>Sn</i>	X
	AIR CLEANER ASSY	1	\$ 372.00			<i>Sn</i>	X
	FRONT FENDER LH <i>R</i>	1	\$ 665.00				X
	FRONT FENDER RH <i>R</i>	1	\$ 665.00				X

Part Number	Parts Description	Qty	cost price	(%)	(\$)	Replace(/)	Replace(/)
	FRONT FENDER GARNISH LH <i>Sn</i>	1	\$ 232.00				X
	FRONT FENDER GARNISH RH <i>Sn</i>	1	\$ 232.00				X
	SUPPORT PANAL GARNISH <i>CR</i>	1	\$ 182.00				✓
	HORN HI PITCH RH	1	\$ 78.00			<i>Sn</i>	X
	HORN LOW PITCH LH	1	\$ 65.00			<i>Sn</i>	X
	RADIATOR AIR GRILLE	1	\$ 178.00			<i>Sn</i>	X
	AIR COND CONDENSER	1	\$ 838.00			<i>Sn</i>	X
	RADIATOR ASSY	1	\$ 516.00			<i>Sn</i>	X
	RADIATOR FAN ASSY	1	\$ 950.00			<i>Sn</i>	X
	AIR COND SUNCTION HOSE <i>Sn</i>	1	\$ 138.00				X
	AIR COND DISCHARGE HOSE <i>Sn</i>	1	\$ 232.00				X
	ENGINE MOUNTING LH	1	\$ 200.00			<i>Sn</i>	X
	ENGINE MOUNTING RH	1	\$ 138.00			<i>Sn</i>	X
	ENGINE MOUNTING REAR	1	\$ 163.00			<i>Sn</i>	X
	EXHAUST MANIFOLD ASSY <i>Sn</i>	1	\$ 2,330.00				X
	NUMBER PLATE <i>CM</i>	1SET	\$ 80.00				<i>45Sn</i>
TOTAL MATERIALS			\$ 16,833.00		\$ -		

Surveyor Remark:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21153



Customer Code: 3000505

Accident Repair Customer (Upper Bukit Timah)
QBE INSURANCE PTE LTD
Block Unit 29-10
SOUTH TOWER
1 RAFFLES QUAY
SINGAPORE 048583

SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : EV180600353
Date : 20.06.2018
Vehicle No. : SJS7313H
Your Ref No. :
UBT/MARCH2018/002
Our Ref No. : 21008312

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount,
Others					
REPAIR COST AS APPROVED BY SURVEYOR 1	1.00	\$7000.00	0.00	\$ 0.00	\$ 7000.00

TOTAL BEFORE GST \$	7,000.00
ADD GST @ 07 % \$	490.00
GRAND TOTAL \$	7,490.00

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Computer generated
no signature requires

Authorised Signature
for SMRT Automotive Services Pte Ltd

SATISFACTION FORM

I, EUGENE PHOEN YU JUN, hereby acknowledge having received from SMRT Automotive Services Pte Ltd my vehicle bearing registration number SJS 7313H which has been repaired to my satisfaction and acceptance. And I agree that the payment of the account for such repairs to SMRT Automotive Services Pte Ltd. shall be in full discharge of all claims under policy number 8-V0014375 in respect of the damage caused in the accident which occurred on LOYANG AVENUE


31062961

Signature, NRIC No. & Date

Co. Stamp (if applicable)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE18005319/Kqd3e2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 21-06-2018



Code : QBE

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJS 7313H
Policy No. 8-V0014375-MVA	Coverage (\$)	0.00
Claim No. VC011280	Excess (\$)	0.00
Assign From JENNY TOH	Assign Date	20/03/2018

2. Vehicle Particulars & Condition

Make & Model	VOLVO C30 (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YV1MK434BA2173808	Colour	METALLIC BLUE
Odometer	122300	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	DUNLOP	6 mm
L/H Front Tyre	225/40Z R18	DUNLOP	6 mm
R/H Rear Tyre	225/40Z R18	DUNLOP	4 mm
L/H Rear Tyre	225/40Z R18	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/03/2018	Inspection Date	21/03/2018
Survey held at	176 SIN MING DRIVE # 04-16		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$25,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7313H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BUCKLED	1,280.00	1,280.00
1	FRONT BONNET INSULATOR	SERVICEABLE	450.00	-
1	FRONT BONNET HINGE LH	TO REPAIR SEE LABOUR	83.00	-
1	FRONT BONNET HINGE RH	TO REPAIR SEE LABOUR	83.00	-
1	FRONT BONNET SPRING HOO GAS	SERVICEABLE	138.00	-
1	FRONT BONNET LOCK	DISTORTED	125.00	125.00
1	FRONT BONNET CABLE	SERVICEABLE	90.00	-
1	FRONT BUMPER	BUCKLED	1,980.00	1,980.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	465.00	-
1	FRONT BUMPER ABSORBER	SERVICEABLE	122.00	-
1	FRONT BUMPER TOWING COVER LH	SERVICEABLE	43.00	-
1	FRONT GRILLE	CRACKED	438.00	438.00
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER LOWER LIP	SERVICEABLE	295.00	-
1	FRONT BUMPER FOG LAMP COVER RH	SERVICEABLE	50.00	-
1	FRONT BUMPER FOG LAMP COVER LH	SERVICEABLE	50.00	-
1	FRONT FOG LAMP LH	SERVICEABLE	195.00	-
1	FRONT FOG LAMP RH	SERVICEABLE	195.00	-
1	FRONT HEADLAMP LH	SERVICEABLE	595.00	-
1	FRONT HEADLAMP RH	CRACKED	595.00	595.00
1	FRONT SUPPORT PANEL	BENT	1,160.00	1,160.00
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	42.00	42.00
1	FRONT AIR DUCT	SERVICEABLE	65.00	-
1	AIR CLEANER ASSY	SERVICEABLE	372.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	665.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	665.00	-
1	FRONT FENDER GARNISH LH	SERVICEABLE	232.00	-

Report Ref No. CS/QBE18005319/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER GARNISH RH	SERVICEABLE	232.00	-
1	SUPPORT PANEL GARNISH	CRACKED	182.00	182.00
1	HORN HI PITCH RH	SERVICEABLE	78.00	-
1	HORN LOW PITCH LH	SERVICEABLE	65.00	-
1	RADIATOR AIR GRILLE	SERVICEABLE	178.00	-
1	AIR COND CONDENSER	SERVICEABLE	838.00	-
1	RADIATOR ASSY	SERVICEABLE	516.00	-
1	RADIATOR FAN ASSY	SERVICEABLE	950.00	-
1	AIR COND SUCTION HOSE	SERVICEABLE	138.00	-
1	AIR COND DISCHARGE HOSE	SERVICEABLE	232.00	-
1	ENGINE MOUNTING LH	SERVICEABLE	200.00	-
1	ENGINE MOUNTING RH	SERVICEABLE	138.00	-
1	ENGINE MOUNTING REAR	SERVICEABLE	163.00	-
1	EXHAUST MANIFOLD ASSY	SERVICEABLE	2,330.00	-
			16,753.00	5,842.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	CRACKED	80.00	45.00
			80.00	45.00
	<u>LABOUR</u>			
	TO APPLY RUST PROOFING ON AFFECTED AREA.	NOT INSURED	200.00	-
	TO TOP UP AIR COND GAS.		150.00	100.00
	TO RESET & DIAGNOSE SYSTEM FUNCTION.	NOT NECESSARY	250.00	-
	TO CHECK WIRING SYSTEM FUNCTION.		120.00	20.00
	TO REMOVE & REFIX AIR CON CONDENSER, INNER COOLER, RADIATOR ASSY & ENGINE FAN AIR CLEANER.		300.00	80.00
	LABOUR FOR CUTTING KNOCKING ACCIDENT FRONT BONNET, FRONT BUMPER, FENDER RH & LH, SUPPORT PANEL & WHEEL HOUSE RH & LH. INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGE LH, FRONT BONNET HINGE RH, FRONT BUMPER REINFORCEMENT, FRONT FENDER LH AND FRONT FENDER RH.		1,500.00	800.00
	TO RESPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH. SUPPORT PANEL & WHEEL HOUSE RH & LH.		1,800.00	1,100.00
			4,320.00	2,100.00

Report Ref No. CS/QBE18005319/Kqd3e2



GRAND TOTAL		21,153.00	7,987.00
RECOMMENDED COST OF REPAIRS (DUE TO INSURANCE AUTHORISED REPAIR AT \$7,000.00)			7,000.00

Report Ref No. CS/QBE18005319/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.