

SembWaste Pte Ltd  
CO REGN NO 199507280G  
30 Hill Street #02-01  
Singapore 179360  
Tel (65) 6723 3200  
Fax (65) 6822 3201  
www.sembcorp.com

Our Ref. JC/SW ACC/190/18

20 March 2018

India International Insurance Pte Ltd  
64 Cecil Street  
#04/#05 IOB Building  
Singapore 049711

By Post & Email  
(motorclaim@iii.com.sg)

Attention: Motor Claims Department

Dear Sirs

**ACCIDENT INVOLVING XD8801Y AND SHC8973D ALONG YISHUN AVE 7 JUNCTION**  
**YISHUN AVE 2 ON 17<sup>TH</sup> DECEMBER 2017**

We refer to the above subject.

We are the owner of the vehicle number XD8801Y which was involved in an accident with the vehicle number SHC8973D. We understand that you are the insurer of vehicle number SHC8973D at the material time of accident.

We are in view that the accident was caused by the negligence of the driver of vehicle number SHC8973D.

We enclose copies of the following documents for your attention:

1. Volvo East Asia (Pte) Ltd Quotation No. 13006362 dated 03.01.2018 for repair of our vehicle at \$2,425.80 inclusive of GST;
2. Singapore Accident Statement of our vehicle;
3. Vehicle Registration Details of our vehicle;
4. Copy of colour photos of our vehicle before repair.
5. LTA search of your insured vehicle no. SHC8973D.

Please contact our fleet management, Mr Azman at 9186-4590 to make the necessary arrangement to conduct a survey of our damaged vehicle which is located at SembWaste Senoko Depot, 20 Attap Valley Road, Singapore 759909 within three (3) days from the date of this letter, failing which we shall proceed with the repairs and all cost of repairs shall be borne by you, being the insurer of vehicle no. SHC8973D.

Yours faithfully



Joanne Chew  
Senior Executive  
Group Legal

Encls: