23/03/2002	, 1	1
SES. REC. BY: REF. CS ASM 1800	5362 / Tlvd?	9 Special Instruction:
Surveyor Igunkh Assignment	ENT (Office)	
From (Person): Yvonn And of		Date/Time: 21/3/2018
Estimated Cost:	Bill to:	
Ob) TP + WS + TP RES / OD RES / EVA / INV / MV 7 C	'S	
To Inspect Vehicle No: 3kw 442	au _{to}	sured:
at Workshop m/s Chum's Custom	crut	Tel: 6272 5492
of BIKIDIU BLOT Merch Lyne 3 # 0	11-105	
Policy No:	Claim No:	S&MOOB9C
Sum Insured:		
Make of Veh: (Client's Record)	·	D.O.A. 19/3/2018
CA / REV / REP. / REV 24 HRS		, ,
CLESON CO L L	اه	H.O.D. Endorsement:
Date/Time: 9.55am @ 22 3/18 Person Contacted:	sharon	Vehicle IN OUT
Date/Time Action/Instruction () Estimate		
- SKW 4294-7		
)3 3 18 Send preli revised by	SMART C	laim
Res (R) > 418		
15/18 Fingl fig \$ 20, 993 (Red 1316 5	16 N 15/5
confumed by email		

AXA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

VΧΑ	INSURANCE PTI	Affiliated to Federation Internation	Ref : CS/ASM180053	The state of the s
			THE . CONTONTIONS	102/1 TVQ5
	ENTON WAY #24		D-1- 00 00 0040	
\XA	TOWERSINGAPO	ORE 068811	Date: 22-03-2018	
			Code: ASM	
	CT CATALYS OF	Policy Particula	ars :- OWN DAMAGE	
	insured Veh.		Veh. Inspected	SKW 4429U
_	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M00B9C	Excess (\$)	400.00
	Assign From	SMARTCLAIM (YVONNE ANG)	Assign Date	22/03/2018
		Vehicle Partic	culars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
24 10 13 1		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
Ŷ		Ve Description	on of Damages	
				A continued a second continued as the co
	Characallic Co	作製造なる (A General	Information	
	Accident Date	19/03/2018	Inspection Date	22/03/2018
	Survey held at	CHARN'S CUSTOMCRAFT	<u> </u>	
		BLK 1010 BUKIT MERAH LANE #01-105 SINGAPORE 159724	3	
l.		Re	marks weeks	

LKK AUTO CONSULTANTS PTE LTD (OD) ▼

Menu

Re:SKW 4429U-SUPPLEMENTARY

Туре	
? Question	
Message	
Please advise final revise repair cost inclusive the supplementary	
Reply *	No. 1. In the control of the control
Dear Sir/Madam,	
Final revised repair cost \$22,993 (inclusive the supplementary) Thar	anks Veron Chen
: 	
	Cancel Reply Reply Now

Menu



SKW 4429U-SUPPLEMENTARY

Type

Question

Message

Dear Sir/Madam, We have received supplementary from repairer,Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.Please refer to IA. Best Regards Veron Chen

Reply

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date:15/5/2018

Survey details

Date of loss	19/3/2018	
Date of appointment	21/3/2018	
Date of survey	22/3/2018	
Location of survey	CHARN'S CUSTOMCRAFT	

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKW 4429U
Make and Model	MERCEDES BENZ ML350
Date of registration	26/11/2010
Excess	\$400
Market Value	\$85,000.00
Parf Rebate	\$52,288.00
Nett Loss	\$32,712.00

Repair details

Initial Estimate	\$24,309 (incl.supplementary \$2767)	

Proposed/Revised repair cost:

Parts	\$20,303.00
"Check items (Estimated)	
Labour	\$2,690.00
Total	\$22,993.00 (incl.supplementary \$2767)
Lump Sum (Estimated)	

Number of days of repair	8 days (est)	

Remarks:

The vehicle sustained damages at the front n/s portion and undercarriage

Damages Consistent Repair Cost Economical LKK AUTO CONSULTANTS PTE LTD (OD) ▼

Menu



IA SUBMITTED SKW 4429U

Type

Question

Message

Dear Yvonne, Please be informed that IA submitted. We have authorize repair.Repairer's Estimate (Gross): \$\$ 21,462.00 Revised Estimate Amount: \$\$ 14,876.00 "Check" Items Amount: \$\$ 6,065.00 Total: \$\$ 20,941.00 Market Value : S\$ 85,000.00 COE/PARF Rebate : S\$ 52,288.00 Nett Value : S\$ 32,712.00 Thanks Veron Chen

Reply



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

S8M00B9C

Our ref:

CS/ASM18005362/T1vd3

Date: 23/3/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKW 4429U

Repairer's Estimate (Gross)	: S\$	21,462.00
Revised Estimate Amount	: S\$	14,876.00
"Check" Items Amount	: S\$	6,065.00
Total	: S\$	20,941.00
Market Value	: S\$	85,000.00
COE/PARF Rebate	: S\$	52,288.00
Nett Value	: S\$	32,712.00


Description of Damage:
The vehicle sustained damage

The vehicle sustained damages at the front n/s portion and undercarriage

Survey date and time: 22/3/2018 at 5pm

No of days: 8 days

We have authorise repair.



front

Yours faithfully,

MOHAMAD TAUFIKH M.MATAI, AMSAE-A Automobile Assessor





Service Request Details

Claim

S8M00B9C

Reference

None 🧳

Loss Date

March 19, 2018

Request Date

March 21, 2018

Due Date

March 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration # SKW4429U

Make

MERCEDES

Menu

Service Address

Blk 1010 Bukit Merah, , , 159724

Primary Contact/Insured

ONG POH LYE BLK 111 MCNAIR ROAD, #03-229, 320111, Singapore

Claim Handler

ANG Yvonne 6568804461 yvonne.ang@axa.com.sg Additional Instructions

Additional Instruction

EXCESS 400

Messages Invoices History Documents Assessment Metrics Notes

New Message



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4685F

Vehicle Details

Vehicle No.: SKW4429U

Vehicle to be Exported: No

Intended De-registration Date: 22 Mar 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model:ML350Primary Colour:SilverManufacturing Year:2010

Engine No.: 27296731527028

Chassis No.: WDC1641862A614219
Maximum Power Output: 200.0 kW (268 bhp)

Open Market Value: \$65,798.00
Original Registration Date: 26 Nov 2010
First Registration Date: 26 Nov 2010

Transfer Count: 3

Actual ARF Paid: \$65,798.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Nov 2020 PARF Rebate Amount: \$39,478.00

Intended COE Rebate Details

COE Expiry Date: 25 Nov 2020

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

 QP Paid:
 \$47,890.00

 COE Rebate Amount:
 \$12,810.00

 Total Rebate Amount:
 \$52,288.00

The information contained herein is correct as at 22 Mar 2018

OK



Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



SELL YOUR CAR BY BIDDING HIGHEST SELLING PRICE GUARANTEED! \$100 CASH!

me	rcedes	henz	m1350	

Price Range

Depreciation

2010

Vehicle Type

Map

More Actions

Search

Share

Post a StarAd

Home » Used Cars » Shine Connect » Mercedes-Benz M-Class ML350 4MATIC

Features

Accessories


Resources

Mercedes-Benz M-Class ML350 4MATIC

Car Buying	Overview	Financial	Accessories	Similar	Research	Photos
Car Selling	Add to Short	list Ad	d to Compare	Add a Note	Report	Error
Car Ownership	Car Details					
	Price	\$79,00	0			
Car Aftermarket	Depreciation	\$19,530	} /yr			0
On The Move		View m	odels with similar	depreciation		
	Reg Date	15-Jul-2	2010			
Lifestyle		(2yrs 3i	nths 22days COE	left)		
	Manufacture	d 2010				0
yres	Mileage	134,402	2 km (17.5k /yr)			



cui becans		
Price	\$79,000	
Depreciation	\$19,530 /yr View models with similar depreciation	0
Reg Date	15-Jul-2010 (2yrs 3mths 22days COE left)	
Manufactured	2010	0
Mileage	134,402 km (17.5k /yr)	
Transmission	Auto	
Engine Cap	3,498 cc	
Road Tax	\$3,164 /yr	0
Power	200.0 kW (268 bhp)	



Description	ML350 Give You The Monster Drive, Impressive
	Outlooks & A Workhouse That Is Beautiful & Safe To
	Transport Your Family In. Perfect For Family Usage.
	Regularly Serviced And Well Maintained, Past Servicing
	Record Invoices And Description Works Done
	Available.New Tyres.Flexible Loans Available, Call For A
	Viewing Today.
COE	¢45 501

Availability	Available
Category	PARF Car
Type of Veh	SUV
No. of Owners	3
Dereg Value	\$51,067 as of today (change)
ARF	\$67,555
ому	\$67,555
COE	\$45,501
	Viewing Today.

Jul 10 Mercedes Benz ML350 4MA Maintained.

Regularly Serviced With Past Servicing Tyres.High ARF\$67,555.CallNow!











0

Seller Information	Seller Information		
Company	Shine Conne » dealer's pricel » 9 vehs sold		
Address	31 West Coast I Search cars nea		
Location	West Coast Car		
Office No	64640963		
Contact Person(s)	Serene David		
Heaful Samisas			

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	19/03/2018 15:07	
Date Of Accident	19/03/2018 10:00	
Exact Location Of Accident	TUAS VIEW CIRCUIT	
Country/State of Loss	SINGAPORE	

	DETAILS OF	OWN VEHICLE

Vehicle Registration Number SKW4429U

Insured/Policyholder

Name Of Registered Owner ONG POH LYE
NRIC No S1364685F
Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-98157590
Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model ML350

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA082800/1

Cover Note Number

Driver

Name of Driver ONG POH LYE
NRIC No S1364685F
Date Of Birth 18/07/1959
Occupation INDOOR
Date Of Driving Pass 28/02/1985

Driving Experience 33 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98157590

Fax Number

Contact Number OFFICE-NOPHONE

EMail Address NOEMAIL

Address

BLK 111 MCNAIR ROAD #03-229

Postcode

320111

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XB9794M

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

ZHANG ZHIQIANG

NRIC/Passport Number

G5479405W

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan Pq. 1

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: SKW 4429U ACCIDENT DATE: 19(3)18

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Oriver.

(0'.00am

- Information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

) understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY, PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policy folder's Signature
Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

CHARN'

CUSTOMCRAFT

Reporting Contre Rersonnel's Signature

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKW 44294

ETCH PLAN	
	TUAS VIEW CIRCUIT,
SCRIBE CIRCUMSTANCES OF T	HE ACCIDENT
WHILE DI	RIVING FROMT PRODENDLY
JAMMED	BRAKE WE ROTH COLLIDED
OWN DAMAGE () 3RI	O PARTY CLAIM () REPORTING ONLY () OWN WORKSHOP ()
ECLARATION We declare the foregoing particular	charge's Customcraft
olicyholder's Seriature ate & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: NRIC/FIN No.:
2.20 19/3/18	

Sketch Plan #3 Pg. 1

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$1364685F



Name

ONG POH LYE



王宝耒 Rece CHINESE



Date of birth

18-07-1959

Country/Place of birth
SINGAPORE



813**6468**5 °



Stew 4429 4 A 19/3/11

5829464



20-11-2017

APT BLK 111 MCNAIR ROAD #03-228 SINGAPORE 320111

Sketch Plan #4 Pg. 1





AXA Insurance Pte Ltd

1809 880 4883 (Within Singapore)
(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

account number

Certificate of Insurance

Motor Venicles (ford Party Pisks and Compensation (Pkt. (Chapter 139)). Motor Venicles , Third Party Risks and Compensation Rules. 1960. Road Fransport Act. 1931 (Malaysia). Motor venicles : Tord-Party Risks. (Rules. 1959 (Malaysia).

Pelicy details

Policytolder name Cover Plan name NCD applicable Vehicle registration number

ONG POH LYE Comprehensive Essential 50% SKW4429U Certificate number Chassis number Engine number GA082800 / 1 WD01641862A614219 27296731527028

Period of Insurance from 22/12/2017 to 21/12/2018 (both dates inclusive)
Finance loas company

MAY BANK

ia The Policyholder

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been 50 permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Light affine for the latest and the

Use only for social, domestic and pleasure purposes and for the Policyholder's business

The policy does not cover-use for hire or reward, racing pace-making reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name, called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered incursiative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transcort Act 1987 (Malaysia), are not to be included under these headings.

EXCESS

Basic Own Damage Excess Windscreen Excess



An Additional Excess is applicable as follows

- 1 \$\$500 for unnamed Authorised Driver
- 2 S\$500 for declared Young and Inexperienced Driver
- 3 \$\$5,000 for undeclared Young and inexperienced Drivers. This additional excess is reduced to \$\$2,500 if You have chosen ANA Premium. Workshops.

Νil

IzWe hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act. (Chapter 189) and Part IV of the Road Transport Act. 1987 (Malaysia)

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are wanted that on the sale of a motor rehicle they must surrender the Certificate of insurance and the Policy to the inarrance company of the Certificate of insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Mictor Vehicle (Party Risks and Compensation Act; Cap. 139).

The Premium Warranty Clause requires the premium to be paid in full within a specific period taking which there is not do no habitity under the policy renewal certificate and opening above.

1 of 3



CHARN'S CUSTOMORAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE †59723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

	OWN DAMAC	E CLAIM			
ESTIMATE COST	OF REPAIR FOR	VEHICLE NO	<u>SKW4429U</u>		
Make/Model	Make/Model DOA Policy No Chassis No.				
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)		

Qty	Unit	Description	Amount
1.00	pc	Front Bonnet	1,950.00 67
1.00	рc	Front Bonnet Logo	55.00 ner
13.00	pc	Front Bonnet Sponge Clips @ \$5	65.00 % × No
1.00	pc	Front Fender LH	55.00 ner / 65.00 ? × ner 1,045.00 buc /
1.00	pc	Front Fender Inner Shield (FRONT)	280 00 24
1.00	pc	Front Fender Inner Shield (REAR)	230.00 ~ 4
8.00	рc	Front Fender Inner Shield Clips @ \$5	40 00 nec
1.00	pc	Front Bumper	1,610.00
1.00	pc	Front Bumper Retainer LH	42.00 dis 500.00 dis 60.00 usi
1.00	pc	Front Bumper Inner Garnish/Tray	500.00 Ai
12.00	pc	Front Bumper Inner Garnish/Tray rivets @ \$5	باقد 60.00
1.00	pc	Front Bumper Foglight LH	23(),()()~47/
1.00	pc	Front Bumper Sponge LH	165.00 ang
1.00	pc	Front Bumper Lower Garnish	205 00 40 /
1.00	pc	Front Bumper Lower Metal Cover	000 00 60/
1.00	pc	Front Bumper Sensor Far LH	160.00 di>
1.00	pc	Front Bumper Sensor Far CTR LH	160.00 di>
1.00	pc	Front Bumper Sensor Wiring	120 00 115 /
1.00	pc	Front Bumper Nozzle LH	160.00 d/3 60.00 M/3
1.00	рс	Front Bumper Nozzle Cover LH	60.00
1.00	pc	Front Bumper Nozzle Hose	85 (10.74
1.00	pc	Front Grille	800.00 cut
1.00	pc	Front Headlamp LH	2,800.00 cus 2,800.00 cus
1.00	pc	Front Headlamp Balast LH	1,240.00
1.00	pc	Front Headlamp Top Panel LH	715.00
1.00	рc	Wiper Tank	والمراكبة 200.00
1.00	pc	Wiper Tank Sensor	30.00 7

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



Accident Claim Repair. Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 6273304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKW4429U	Make/Model DOA Policy No Chassis No.			
	ESTIMATE COST	OF REPAIR FOR	VEHICLE NO:	<u>SKW4429U</u>

Qty	Unit	Description	Amount
1.00	рс	Front W/S wiper nozzle hose	Amount 160.00 7 200.00 7 1,570.00 7 230.00 7 1,150.00 7 550.00 8
1.00	pc	Radiator Spare Tank	200.00
1.00	рс	Front Kunckle LH	1,570.00 ?
1.00	рс	Front Kunckle Bearing LH	230.00?
1.00	рс	Front Lower Arm LH	1,150.00
1.00	рс	Front Top Arm LH	550.00 s
1.00	рc	Front Shock Absorber LH	590.00 <
		Subtotal - PARTS ONLY	18,467.00
			old b
1.00	pc	Front No. Plate (S/NETT)	⊿ 35.00 ×
1.00	pc	Front Tyre LH (S/NETT)	380.00pm
1.00	pc	Front Rim LH (S/NETT) - TBA \$80	0.00 d
		·	35.00 × 35.00 × 380.00pu 0.00 d 40.00 3 60.00 × 280.00 /
		Check wiring function	40.00 5
		Alignment	60.00
		Labour to remove and replace undercarriage front LH	280.00 /
		Remove necessary parts: jacking, panel beating, repair	
		and straighten front inner panel, front headlamp top	,
		panel LH, front headlamp side panel LH, front bonnet	
		front fender LH/RH, front bumper, front door LH, from	
		wsside pillar and wheel housing LH (BULKHEAD	
		SHIFTED)	
		,	900
		Putty and respray front inner panel, front bonnet, front	1,000.00
		fender LH/RH, front bumper, front door LH, front ws	

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total

side pillar and wheel housing LH.



Charn's Customerapt

Accident Claim Repair, Corrosion Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

OWN DAMAGE CLAIM					
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKW4429U					
Make/Model	DOA	Policy No	Chassis No.		
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)		

Qty	Unit	Description	Amount

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylle 97495749

Ex 9400

Removey before point

22/5/18@ 1700

Surc (hearto was
Joleys

Arthonised:

(s) 7767

CHARN'S CUSTOMCRAFT

Subtotal
GST 7%
Total

\$21,462.00 \$1,502.34 \$22,964.34

24, 309

Page 3



A CHARM'S CUSTOMERAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736876 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

	OWN DAMAC	E CLAIM	
ESTIMATE COS	T OF REPAIR FOR	VEHICLE NO	: <u>SKW4429U</u>
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)

2. 4. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.			
Qty	ty Unit Description		Amount
1.00	рс	Front Bonnet	√ 1,950.00 bi
1.00	рс	Front Bonnet Logo	ر 55.00م
13.00	p c	Front-Bonnet Sponge Clips @ \$5	65.00
1.00	рс	Front Fender LH	1,045.00 h
1.00	рc	Front Fender Inner Shield (FRONT)	280.00
1.00	рс	Front Fender Inner Shield (REAR)	230.00
8.00	рc	Front Fender Inner Shield Clips @ \$5	/ 40.00 M
1.00	рс	Front Bumper	, 1,610.00
1.00	рc	Front Bumper Retainer LH	.42 nn al
1.00	рc	Front Bumper Inner Garnish/Tray	500.00
12.00	pc	Front Bumper Inner Garnish/Tray rivets @ \$5	60.00
1.00	pc	Front Bumper Foglight LH	230.00
1.00	pc	Front Bumper Sponge LH	
1.00	pc	Front Bumper Lower Garnish	285.00
1.00	рс	Front Bumper Lower Metal Cover	920.00
1.00	рс	Front Bumper Sensor Far LH	160.00 d
1.00	рс	Front Bumper Sensor Far CTR LH	, 160.00
1.00	рс	Front Bumper Sensor Wiring	130.00
1.00	рc	Front Bumper Nozzle LH	160 00 &
1.00	pc	Front Bumper Nozzle Cover LH	.60.00
1.00	рс	Front Bumper Nozzle Hose	_85.00か
1.00	рc	Front Grille	ے 800.00 سے
1.00	рс	Front Headlamp LH	2,800.00
1.00	рс	Front Headlamp Balast LH	_1,240.00 _. ;
1.00	pc	Front Headlamp Top Panel LH	715.00 ₹
1.00	рc	Wiper Tank	200.00
1.00	рс	Wiper Tank Sensor	30.00

CHARN'S CUSTOMCRAFT

Subtotal
GST 7%
Total



A Gearm's Gustomerapt

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

Make/Model	DOA	Policy No	Circuit in the circui
		Policy No	Chassis No.
ESTIMATE COS	ST OF REPAIR FOR		<u>SKW4429U</u>
	OWN DAMAG	E CLAIM	

	 Unit	Description	Amount
	рс	Front W/S wiper nozzle hose	×160.00
_	pc	Radiator Spare Tank	200 00 . 9
	-	Front Same kie 144	
^	pc	Front Kunckle Bearing Lift	23 0.00 (*
_	pc	Front Lower Arm LH	/ 1,150.00 }
_	pc	Front Lower Arm LH Front Top Arm LH	550.00 ัร
_	pc	Front Shock Absorber LH	590.00
0	pc	Substal PARTS ONLY	18,467.00
		SHORE PARTY ON DE	old b
^		E AND Diet (CATETT)	25.00 K
0	-pe	Front No. Plate (S/NETT) Front Tyre LH (S/NETT) Front Rim LH (S/NETT) - TBA - VERAN - 480 30	80% 380.00pm
	pc	Front Tyte LH (S/NETT) TDA - 1800/ - 480	0.00 d
0	pc	Front Rim LH (S/NETT) - TBA	0.00
			40.00 3
		Check wiring function	60.00
		Alignment	28000
		Labour to remove and replace undercarriage front LH	**************************************
			1,200.00
		Remove necessary parts: jacking, panel beating, repair	1,200.00
		and straighten front inner panel, front headlamp top	
		panel LH, front headlamp side panel LH, front bonnet,	
		front fender LH/RH, front bumper, front door LH, front	
		wsside pillar and wheel housing LH (BULKHEAD	
		SHIFTED)	~
		VIII 100)	90
		Putty and respray front inner panel, front bonnet, front	1,000.00
		fender LH/RH, front bumper, front door LH, front ws	
		side pillar and wheel housing LH.	
		Side piliar and wheel housing Dri.	

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736876 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

			WDC1641862A614219 (2010)
Make/Model	DOA	Policy No	Chassis No.
ESTIMATE COS	T OF REPAIR FOR		<u>SKW4429U</u>
	OWN DAMAG	E CLAIM	

			Amount
Qty	Unit	Description	Amount

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

Taylor 97495749
Ep \$400

Benevey before point

22/5/18 C 1700

Sur C (hearto was
Joleys

Adamsed.


CHARN'S CUSTOMCRAFT

Subtotal
GST 7%
Total

\$21,462.00 \$1,502.34

\$22,964.34

Page 3



Accident Claim Repair, Corrosion Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.	
14/5/2018	Supp 2	41980	

	OWN DAMAC	E CLAIM	
ESTIMATE COS	T OF REPAIR FOR	VEHICLE NO	: <u>SKW4429U</u>
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)

Qty	Unit	Description	Amount
•		·	

SUPPLEMENTRY

Front Bumper Foglight Grille LH 1.00 pc

80.00 der

CHARN'S CUS TOMCRAFT

Subtotal **GST 7%**

Total

\$80.00 \$5.60 \$85.60

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

FRT SUPPORT

Tel: 67476016 Fax: 67449644 Email:surpasslim@gmail.com

Co & Gst Reg No:199904808E

CHARN'S CUSTOMCRAFT

BLK 1010 BUKIT MERAH LANE 3

#01-105

SINGAPORE 159724

28 A1646201234

TAX INVOICE

Inv No.

: 18040001

700.00^X

700.00

1

Date Page : 03/04/2018 : 1 of 3

S/N	Item No.	Description		Qty	U/ Price	Amount
1	A1648800557	BONNET		1	1,950.00	1,950.00
2	A2078170316	COMPANY SIGN		1	55.00	55.00
3	A1648810101	FENDER		1	1,045.00	1,045.00
4	A1648802705	FRT LH COVER I		1	280.00	280.00
5	A1648840922	FRT LH COVER 1 I		1	230.00	230.00
6	A1249900492	RIVET		8	5.00	40.00
7	A16488033409999	FRT BUMPER	.54	1	1,610.00	1,610.00
8	A1648800314	SIDE BRACKET LH		1	42.00	42.00
9	A1648851865	BASIC MOUNTING FOR BUMPER		1	500.00	500.00
0	A2019900292 E	CLIP		12	5.00	60.00
11	A1698201556	FOGLAMP		1	230.00	230.00
12	A1648800235	ENERGY-ABSORBING UNIT		1	165.00	165.00
El	A1648857325	BUMPER LOW COVER		1	285.00	285.00
14	A1648855223	METAL COVER	`	1	920.00	920.00
15	A1648600547	NOZZLE		1	160.00	160.00
	A16486009089999	NOZZLE COVER PLATE		1	60.00	60.00
17		NOZZLE HOSE		1	85.00	85.00
17 18		FRT GRILLE		1	800.00	800.00
19		HEADLAMP LH		1	2,800.00	2,800.00
20		HEADLAMP PANEL LH		1	715.00	715.00
21		WP TANK		1	200.00	200.00
22		WINDOW NIZZLE HOSE		1	160.00	160.00
22 23		RADIATOR EXPANSION TANK		1	200.00	200.00
حب 24		FRT KNUCKLE LH		1	1,570.00	1,570.00
27 25		FRT LOWER ARM LH		1	1,150.00	1,150.00
25 26		TOP ARM		1	550.00	550.00
20 27		FRT S/ABSORBER		1	5 9 0.00	590.00
-/	VIOLITEONIUM.			•	200.00	700.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67475016 Fax: 67449644 Email:surpasslim@gmail.com

Co & Gst Reg No:199904808E

CHARN'S CUSTOMCRAFT

BLK 1010 BUKIT MERAH LANE 3

#01-105

SINGAPORE 159724

TAX INVOICE

Inv No.

: 18040001


Date

03/04/2018

Page

; 3 of 3

Description	Qty	U/ Price	Amount
LH SUPPORT BRACKET	1	252.00	252.00 X
SIDE PANELLING	1	345.00	345.00 X
SIDE PANELLING TOP STEP LH	1	290.00	290.00 ^X
	2	30.00	60.00×
GUIDE	1	20.00	20.00 Å
BUMPER FOGLAMP LH GRILLE	1	80.00	80.08
	LH SUPPORT BRACKET SIDE PANELLING SIDE PANELLING TOP STEP LH RUBBER MOUNTING GUIDE	LH SUPPORT BRACKET SIDE PANELLING SIDE PANELLING TOP STEP LH RUBBER MOUNTING GUIDE 1	LH SUPPORT BRACKET 1 252.00 SIDE PANELLING 5IDE PANELLING TOP STEP LH 1 290.00 RUBBER MOUNTING 2 30.00 GUIDE 1 20.00



Sub Total GST 7% Total 18,199.00 1,273.93 19,472.93

Customer's Signature

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67478016 Fax: 67449644 Email:surpasslim@gmail.com

Co & Gst Reg No:199904808E

CHARN'S CUSTOMCRAFT

BLK 1010 BUKIT MERAH LANE 3

#01-105

SINGAPORE 159724

TAX INVOICE

Inv No.

18040175

Date

10/04/2018

Page

: 1 of 1

S/N Item No.	Description	Qty	U/ Price	Amount
1 A0009052402	2215420417 BUMPER SENDER	2	160.00	320.00
2 A1644400837	ELECTRICAL WIRING HARNESS	1	130.00	130.00 🗡
3 A1648704126	SWITCH	1	1,240.00	1,240.00
4 A1648600021	SWITCH	1	30.00	30.00

Customer's Signature

Sub Total GST 7% Total 1,720.00 120.40 1,840.40

∀eron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 17 May 2018 10:01 AM

To:

'Charn's Customcraft'; Taufikh (LKKAuto)

Cc:

SUR

Subject:

RE: Finalization - SKW 4429 U - Mer Benz

Sensitivity:

Confidential

Dear Sharon,

Confirmed \$22,993.00 before excess \$400 and GST @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft [mailto:charns@singnet.com.sg]

Sent: Monday, 14 May 2018 1:53 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Finalization - SKW 4429 U - Mer Benz

Importance: High

Sensitivity: Confidential

Hi

Kindly find attached for finalization.

Parts: \$19,919 S/N: \$304.00 Lab: \$2690.00 Repair rim: \$80

Total: \$22,993.00 (befoe GST/Excess)

Please confirm

Thanks & Regards,

Sharon Lee

Charn's Customeraft

Tel: 6272 5429 Fax: 6273 6676 Email: charns@singnet.com.sg GST Reg. No: M90367863L Company Reg No: 25151300M



Accident Claim Repair, Corrosion Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus, Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.	
28/3/2018	SUPP 1	41980	

	OWN DAMAG	E CLAIM	
ESTIMATE COS	ST OF REPAIR FOR	VEHICLE NO	: <u>SKW4429U</u>
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)

Amount Description Unit Qty SUPPLEMENTRY 700.00 Bf X Front Bumper Reinforcement 1.00 pc 252.00 KHX Front Bumper Reinforcement Bracket LH 1.00 pc 345.00 Cut X Rocker Panel Garnish/Trim Step 1.00 р¢ 290.00 cut > Rocker Panel Garnish Top Plate/Step insert 290.00 200 280.00 200 280.00 200 380.00 200 300.00 200 1.00 pc Anti Roll Bar Bush @ \$30 *4*.00 pc Front Bumper Side Bush рс Vehicle on Bench

Putty and respray front chassis LH/RH.

To repair front chassis LH & RH

Parts-19.919 SIN-304 SIN-3690 Lab-80 Tim-80

TOMCRAFT CHARN'\$

Subtotal **GST 7%** Total

\$2,687.00 \$188.09 \$2,875.09