

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 22 Mar 2018

Preliminary Advice

Vehicle No	: SLQ2959P	Accident Date	: 17/03/2018
Make	: OPEL ASTRA	Policy No.	: MPC17A00420800
Assignment Date	: 22/03/2018	Excess	: S\$0.00
Date of Inspection	: 22/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,897.55
Revised Amount	:S\$	9,862.05
Check Items (Estimated)	:S\$	2,785.50
Total	:S\$	12,647.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	27,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,306.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :