

REGENT MOTORS

(A Division of Vantage Automotive Limited)


Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3610

Page No. : 1 of 3

Date Estimated : 21/03/2018

Prepared By : Mohamed Shabir Abdul Hamid

- ESTIMATE REPAIR FOR -

Yeo Lik Seng
606 Senja Road
#26-55

Singapore 670606

- ACCOUNT - 24748

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

DESCRIPTION

VALUE

SUNDRIES

✓ 30 150.00

ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)

✓ / 120.00

TO REMOVE AND REFIX REAR REVERSE SENSOR (NETT)

✓ / 120.00

TO REMOVE AND REFIX REAR REVERSE CAMERA (NETT)

✓ / 150.00

TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER (NETT)

NN X 70.00

TOWING CHARGES (NETT)

✓ / 120.00

TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL

✓ 60 180.00

SEALANT FOR BODY PANELS (NETT) @ \$90.00 PER PANELS

✓ 80 270.00

TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIRS (NETT)

✓ / 500.00

SEALANT FOR REAR WINDSCREEN (NETT)

✓ / 60.00

INNER SEAL FOR REAR WINDSCREEN (NETT)

✓ / 50.00

TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN (NETT)

✓ / 350.00

TO REMOVE AND REFIX REAR Q QUARTER GLASS TO FACILITATE REPAIRS (NETT)

✓ / 260.00

SEALANT FOR QUARTER GLASS (NETT)

✓ / 60.00

INNER SEAL FOR QUARTER GLASS (NETT)

✓ / 50.00

TO REMOVE AND REFIX REAR SPARE TYRE COMPARTMENT, TIRMS BAORDS TO FACILITATE REPAIRS (NETT)

✓ / 450.00

TO REMOVE AND REFIX FUEL TANK INCLUDING CHECK FOR LEAKS TO FACILITATE REPAIRS (NETT)

✓ / 280.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3610
Date Estimated : 21/03/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

DESCRIPTION

VALUE

TO TRANSFER REAR BOOT MECHANIS LOCKS, TRIMS TO FACILITATE REPAIRS (NET)

✓ / 280.00

TO REMOVE AND REFIX REAR SPEAKER / RADIO PANEL TO FACILITATE REPAIRS (NETT)

NN X 280.00

TO REPAIR, REPALCE REAR BUMPER REAR BOOT, REINFORCEMENT, REAR END PANEL, REAR LH FENDER, TO REPAIR LH ROCKER PANEL, BOO LID HINGE AND ALL OTHER AFFECTED AREAS

(560) 2500 2800 3,360.00

TO SPRAY PAINT REAR BOOT, BOOT LID HINGER, REAR BUMPER REAR END PANEL, REAR LH FENDER LH ROCKER PANEL AND ALL OTHER AFFECTED AREAS

(560) 3.5 1764 1960 3,640.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES (NETT)

✓ / 280.00

Total Labour 1: 11,080.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS73F40110EB	DOOR-LUGG. COMP but ? x net guc	1	1,955.00	25.00	1,466.25
DS73F438A00B	WEATHERSTRIP, RR BONNET ? x guc	1	170.00	25.00	127.50
DS73F423A40B	PANEL ASSY - LWR BACK FINISHER re	1	1,284.00	25.00	963.00
MXWAA					
BT16R310A58A	RR LIC.PLATE INSULATOR net	1	62.00	25.00	46.50
A					
DS7317K835KA	BUMPER ASSY - REAR, PRIMED re	1	1,750.00	25.00	1,312.50
XWAA					
DS7317E899BC	RR BUMPER ISOLATOR <BB> ? x guc	1	95.00	25.00	71.25
DG9317970DC	RR REINFORCEMENT ? x guc	1	582.00	25.00	436.50
DS7317B861BC	BRACKET - BUMPER MOUNTING ? x guc	1	120.00	25.00	90.00
DS7317E911ME	RR MOULDING cut	1	580.00	25.00	435.00
5UAW					
DS7317A894MD	RR BUMPER - EXTENSION, PRIMED re	1	560.00	25.00	420.00
XWAA					
DS7317G771BA	INSERT,LH (MUFFLER W/DUAL EXHAUST) cut	1	285.00	25.00	213.75
DS7317F767JC5RR	BRACKET - BUMPER MOUNTING, LH ? x guc	1	45.00	25.00	33.75
JA6					
DS7317A882BF	RR BRACKET - BUMPER MTG, LH ? x guc	1	107.00	25.00	80.25
DS7317E851BG	RR BPR SIDE MTG BRACKET LH <BB> ? x re	1	109.00	25.00	81.75
DS73F40320RA	PANEL ASSY BACK re	1	190.00	25.00	142.50
DS73F40320SA	PANEL ASSY BACK re	1	190.00	25.00	142.50
DS73F278A93C	PANEL - QUARTER - OUTER LH net	1	1,435.00	25.00	1,076.25
E					
DS73F42004BK	GLASS, REAR net	1	956.00	25.00	717.00
DS73F29701GA	GLASS - QUARTER WINDOW, LHR net	1	481.00	25.00	360.75

REGENT MOTORS


(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road
159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3610
Date Estimated : 21/03/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS73F253A10A	RR WEATHERSTRIP ON BODY,RH/LH <i>? X SVC</i>	1	138.00	25.00	103.50
DS73402A16AD	EMBLEM, FORD OVAL, REAR <i>=</i>	1	69.00	25.00	51.75
DS7343156AA	NAME PLATE, ECOBOOST <i>= 1 pc.</i>	1	59.00	25.00	44.25
DS7342528BA	NAME PLATE, MONDEO BADGE <i>=</i>	1	30.00	25.00	22.50
EM2T15K859AA	SENSOR PARKING AID SYS.RUBY RED TC <i>1 pc - DM</i>	2	85.00	25.00	127.50
5DST					
DG9T15K868HG	RR JUMPER WIRE ASSY - PARKING AID <i>X NN</i>	1	180.00	25.00	135.00
DS7313405DJ	LAMP ASSY - LHR OUTER <i>= 1 pc.</i>	1	1,348.00	25.00	1,011.00
DS7313A603KD	LAMP ASSY - LHR INNER <i>=</i>	1	1,408.00	25.00	1,056.00
DS73515C0BA	REFLECTOR ASSY, LH <i>=</i>	1	82.00	25.00	61.50
6M2A13550AC	LAMP-LIC.PLATE <i>X NN</i>	2	75.00	25.00	112.50

Total Parts : 10,942.50

8 Days.
Not Authorized.
before paint photos.
Excess \$700
23/3/18
Gmo@ianp

Li.K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No final modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

22,048.50

Customer Service Officer

Contact

Labour 1	:	11,080.00
Parts	:	10,942.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,541.58
Grand Total	:	23,564.08

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.