

ASS. REC. BY:

REF: CS/MSH18005428 / Urbn2 Special Instruction:

SURVAYOR: Maxus ASSIGNMENT (Office)

From (Person): Elaine Ngu of MSH Date/Time: 23/03/2018 1:09 pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 3254A Insured: FV 6970Z

at Workshop m/s Hup Motor Tel: \_\_\_\_\_

of Blok 9004 Tampines St 93 #01-120

Policy No: MSD/YMT/17-9831KS-WTT Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22032018  
(Client's Record)

CA / REV / REP. / REV 24 HRS w/p H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23/03/2018 1:11 pm Person Contacted: David Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SJD 3254A - CS/TP 0702 8563 / Uch DCA: 15122009
	FV 6970Z - CS/TP 11006056 / Rig DCA: 16032011
	Sent preli the menmen





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005428/Urb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FV 6970Z	Veh. Inspected	SJD 3254A
Policy No.	MSD/VMT/17-983145-WTT	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	23/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/03/2018	Inspection Date	23/03/2018
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 04 Apr 2018

## Preliminary Advice

Insured Vehicle : FV6970Z

No

TP Vehicle No : SJD3254A

Make : HONDA FIT

Date of : 23/03/2018

Inspection

Inspection At : Hup Motor Trading & Service (HQ)  
Blk 9004 Tampines Street 93, #01-120  
Singapore 528838

Accident Date : 22/03/2018

Assignment Date : 23/03/2018

Est. Duration of  
Repair : 5 days

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,102.68
Revised Amount	:S\$	3,785.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,785.20

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2018		23 Mar 2018 12:09 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	MUHAMAD YUSUF BIN ISHAK, ID: S9602195Z		
<b>Main Claimant:</b>	TOO PUAY KEE, ID: S7707553D		
<b>Vehicle Reg. No.:</b>	SJD3254A	<b>Date of Loss:</b>	22/03/2018 09:00 - :59
<b>Claim Type:</b>	TP	<b>Policy/Cover Note No.:</b>	MSD/VMT/17-983145-WTT (Third Party Only) Coverage: 19/05/2017 - 18/05/2018
<b>Vehicle Reg. No. (Insured):</b>	FV6970Z	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/03/2018]		
<b>Adj Asg. Remarks:</b>	Kindly assign LKK auto consultants to survey client's (SJD 3254 A) damage vehicle, as LKK also one of our insurer (III) panel surveyor, Please revert & confirm the survey assignment on : 23/03/18 at 12pm to 2pm, as owner waiting,		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/03/2018 14:30
Date Of Accident	22/03/2018 09:00
Exact Location Of Accident	SLIP ROAD OF BUANGKOK VIEW INTO BUANGKOK GREEN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD3254A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOO PUAY KEE
NRIC No	S7707553D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97677346
Alternative Phone No	OTHERS-97677346

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.3 G (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M496155
Cover Note Number	

### Driver

Name of Driver	TOO PUAY KEE
NRIC No	S7707553D
Date Of Birth	18/03/1977
Occupation	INDOOR
Date Of Driving Pass	28/01/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97677346
Fax Number	
Contact Number	OTHERS-97677346
EMail Address	NOEMAIL

Address	BLK 200D SENGKANG EAST ROAD #03-36
Postcode	544200
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

KINDLY REFER TO SKETCH PLAN ATTACHED.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	FV6970Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMAD YUSUF BIN ISHAK
NRIC/Passport Number	S9602195Z
Contact Number	93834425
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: Sandy  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident occurred at filter road of Bangkok View into Bangkok Green, around the timing of 22 March 2018, 0900. While my vehicle is stationary at the stop line of the filter road, giving way for an oncoming motorcycle. Suddenly a motorcycle with vehicle plate of FV 6970Z, hit my vehicle - SJD 3234A from behind. After the accident, both party exchanged our particulars. In addition the rider - Muhamad Yusuf Bin Isahak (S96021952) admitted that it is his fault and he wrote a statement to me on this matter.

This accident resulted my back door unable to close properly, which lead to my whole vehicle unable to lock.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name: Sandy  
 NRIC/FIN No.:



ACCIDENT REPORTING CENTRE  
& AUTHORISED WORKSHOP:  
**HUP MOTOR TRADING & SERVICE**  
BLK 9004 TAMPINES STREET 93  
#01-120 SINGAPORE 528838  
TEL: 67840039 (24 hrs) HP: 98154655  
Email: hupmotor@gmail.com

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792K | GST. Reg. No. M2-0078806-X  
64 Cecil Street #04/ #05/ #06-02 IOB Building Singapore 049711  
Office (65) 63476100 Email insure@iil.com.sg  
Fax (65) 62244174 Website www.iil.com.sg

**CERTIFICATE OF INSURANCE**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory Insurance. The Certificate must be returned if the Insurance is suspended during its currency.

Agency Code: <b>61301SE</b> <b>Comprehensive</b>	Insured/ Named Drivers Excess: <b>\$600/- Sect I</b> Unnamed Drivers Excess: <b>\$1100/- Sect. I &amp; additional \$2500/- Sect. I for age &lt; 21 years or &gt;65 years &amp;/or S'pore D.L. &lt; 2 years</b> Windscreen Excess: <b>\$100/-</b>
<b>CERTIFICATE NO.</b>	<b>M496155</b>
1. <b>Index Mark and Registration Number of Vehicle</b>	<b>SJD 3254 A</b>
2. <b>Name of Policy Holder</b>	<b>Too Puay Kee</b>
3. <b>Effective date of the Commencement of Insurance for the purposes of the Act</b>	<b>08<sup>th</sup> March 2018</b>
4. <b>Date of Expiry of Insurance</b>	<b>17<sup>th</sup> March 2019</b>
5. <b>Person or Classes of Persons entitled to drive*</b>	
(a) <b>The Policyholder</b> The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.	
(b) <b>Any other person who is driving on the Policyholder's order or with his/her permission</b> Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6. <b>Limitations as to use*</b> Use only for social, domestic and pleasure purposes and for the Policyholder's business <b>The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</b>	
<small>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</small>	

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: **17/08.03.2018**

for India International Insurance Pte. Ltd.  
(APPROVED INSURERS)

M.X. 1 (PRIVATE CAR)  
INDIVIDUAL OWNERSHIP

Authorised Signatory

**IMPORTANT NOTICE**

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner they will endorse the policy accordingly and will issue a new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE COMPANY. FAILURE TO DO SO WILL RESULT IN UNDERWRITERS DECLINING LIABILITY.

Agent/Broker Name: **M Plus**

Hire Purchase Company: **Maybank**

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	SJD3254A
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	FIT 1.3G A
Chassis No. :	GE61042871
Propellant :	Petrol
Engine No.:	L13A4047109
Engine Capacity :	1339 cc
Maximum Power Output :	73.0 kW ( 97 bhp )
Maximum Laden Weight :	1285 kg
Unladen Weight :	1010 kg
Year Of Manufacture :	2008
Original Registration Date :	18 Mar 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
PQP Paid :	\$39,274.00
COE Expiry Date :	17 Mar 2028
Road Tax Expiry Date :	17 Sep 2018
Inspection Due Date :	17 Mar 2019
Intended Transfer Date :	22 Mar 2018
CO2 Emission :	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7553D

### Vehicle Details

Vehicle No.:	SJD3254A
Vehicle to be Exported:	No
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4047109
Chassis No.:	GE61042871
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,069.00
Original Registration Date:	18 Mar 2008
First Registration Date:	18 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$13,276.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	<u>17 Mar 2028</u>
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$39,274.00
COE Rebate Amount:	\$39,160.00
<b>Total Rebate Amount:</b>	<b>\$39,160.00</b>

The information contained herein is correct as at 26 Mar 2018

OK

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: bupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2896/03/18

Your Ref:

Date: 22nd March 2018

MR TOO PUAY KEE  
BLK 200D, #03-36  
SENGKANG EAST RD  
SINGAPORE 544200

*not Approved  
now  
2/s #3000/r  
5 day.*

Estimate cost of repair to HONDA FIT 1.3 (A) S/Wagon - SJD 3254 A *23/3/18*

1 pc tail gate door	<i>30300 784.80</i>	\$ 784.80	✓
1 pc tail gate door 'FIT' emblem	<i>neu</i>	31.90	✓
1 pc tail gate door inner lock	<i>2/s/stricker</i>	109.40	✓
1 pc tail gate door inner lock stricker	<i>11</i>	27.60	✓
16 pcs tail gate door trim board clips	<i>11 @ \$ 5.80</i>	92.80	✓
1 pc rear windscreen glass top seal	<i>neu</i>	29.70	✓
1 pc rear windscreen glass lower seal	<i>neu</i>	34.70	✓
2 pcs rear windscreen glass o/s & n/s seal	<i>neu neu</i>	49.40	✓
1 pc rear windscreen glass inner damper rubber	<i>neu</i>	28.30	✓
1 pc tail gate door n/s stopper	<i>11</i>	11.00	✓
4 pcs tail gate door licence garnish clips	<i>11 @ \$ 4.50</i>	18.00	✓
1 pc n/s tail lamp assy	<i>neu</i>	226.20	✓
2 pcs n/s tail lamp clips stopper	<i>11 @ \$ 5.50</i>	11.00	✓
1 pc n/s tail lamp panel	<i>neu</i>	143.90	✓
1 pc rear bumper	<i>303 496.60</i>	496.60	✓
8 pcs rear bumper clips	<i>neu</i>	31.20	✓
1 pc rear bumper n/s side retainer	<i>neu</i>	28.70	✓
1 pc rear bumper n/s top retainer	<i>neu</i>	17.50	✓
2 pcs rear bumper n/s top screw	<i>11 @ \$ 6.80</i>	13.60	✓
1 pc rear end panel	<i>neu</i>	296.60	✓
1 pc rear end panel top garnish	<i>11</i>	85.00	✓
5 pcs rear end panel top garnish clips	<i>11 @ \$ 5.50</i>	27.50	✓
6 pcs rear n/s fender inner garnish clips	<i>11 @ \$ 4.50</i>	27.00	✓
4 pcs rear n/s wheel guard clips	<i>11 @ \$ 4.00</i>	16.00	✓
		\$ 2,638.40	<i>2311.1</i>
	Less 20%	\$ 527.68	<i>1848.88</i>
		\$ 2,110.72	
1 pc rear windscreen glass sealant	<i>neu</i>	40 45.00	S.N
1 set rear bumper reverse sensor	<i>stricker</i>	200 200.00	S.N
To wiring check up & transfer affected wiring system.		70.00	<i>30</i>
To remove & refix rear windscreen glass & necessary parts.		150.00	<i>120</i>
To transfers tail gate door inner trim board cover, garnish, hinge shock absorber, spoiler, wiper motor & necessary parts.		150.00	<i>60</i>
		\$ 2,725.72	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Balance C/F.....

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Bik 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2896/03/18

Your Ref:

Date: 22nd March 2018

MR TOO PUAY KEE.,

Balance B/F... \$ 2,725.72

To remove & refix carpet, floor mat, garnish, floor board cover, tool set, rear n/s fender garnish & necessary parts. 120.00 60

To remove & refix fuel tank hose, pipe & necessary parts, ^ ^ 120.00 X

To respray Tuff-Kote on all affected accident parts. 120.00 50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender, tail lamp panel, rear end panel & necessary parts, to weld, renew & align above parts. 1,400.00 600

To putty & respray painting on all affected accident parts. 1,500.00 800

\$ 5,985.72

6102.68

1950

Dollars : Five Thousand Nine Hundred Eighty Five And Cents Seventy Two Only.

30488  
3047

HUP MOTOR TRADING & SERVICE

.....  
.....

哈 汽 車 貿 易 服 務

**HUP MOTOR TRADING & SERVICE**

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2896/03/18

Your Ref: \_\_\_\_\_

Date: 24th March 2018

MR TOO PUAY KEE  
BLK 200D, #03-36  
SENGKANG EAST RD  
SINGAPORE 544200


SUPPLEMENTARY Bill for HONDA FIT 1.3 (A) S/Wagon - SJD 3254 A

1 pc tail gate door weatherstrip

<i>Total</i>	\$ 146.20 ✓
Less 20%	\$ 29.24
	<u>\$ 116.96</u>
	=====

Dollars : One Hundred Sixteen Dollars And Cents Ninety Six Only.

HUP MOTOR TRADING & SERVICE

.....  


<u>LIST ITEMS</u>		<u>NETT ITEMS</u>		<u>LABOUR</u>	
<u>PAY</u>	<u>UNPAID</u>	<u>PAY</u>	<u>UNPAID</u>	<u>PAY</u>	<u>UNPAID</u>
		40.00	5985.72	30.00	
784.80		200.00	116.96	120.00	
31.90				60.00	
109.40				60.00	
34.70				50.00	
49.40				600.00	
28.30				800.00	
226.20					
496.60					
31.20					
28.70					
17.50		240.00			
296.60					
146.20	+29.70		6102.68		
<u>2281.50</u>				1720.00	
2,311.20	0.00				0.00
0.00		0.00		0.00	
0.00		0.00		0.00	
0.00		0.00		0.00	

2281.50    2,311.20  
 456.30 (20% DISC)    462.24  
 1825.20 LIST ITEM AFTER DISC (PAY)    1,848.96  
 240.00 NETT ITEM (PAY)  
 1720.00 LABOUR (PAY)

3785.20    3,808.96

3,808.96  
 3785.20 } LUMP SUM

~~3785.20~~    3,808.96  
 757.04    761.79  
 3028.16    3,047.17



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF  
SINGAPORE**

**RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-18-043606

Date of Request: 22/03/2018

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 22/03/2018

Enquiry By David Ang Beng Yeow

TP Vehicle No. FV6970Z

Accident Date 22/03/2018

### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FV6970Z	MSIG Insurance (Singapore) Pte. Ltd.	19/05/2017-18/05/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF  
SINGAPORE**

**RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-043606

Date of Request: 22/03/2018

Your Ref No:

Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 22/03/2018

Enquiry By David Ang Beng Yeow

TP Vehicle No. FV6970Z

Accident Date 22/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005428/URBN2

Date: 04/04/2018

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-983145-WTT
Claimant Vehicle No :	SJD3254A	Insured Vehicle No :	FV6970Z
Date of Loss:	22/03/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-000431

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SJD3254A	Engine No:	L13A4047109
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61042871
Reg. Date:	18/03/2008 (Man. Year: 2008)	Odometer:	260779 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	175/65R14	Rear Tyre Size:	175/65R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,472.68	2,088.96	383.72	15.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,720.00	1,910.00	52.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,102.68</b>	<b>3,808.96</b>	<b>2,293.72</b>	<b>37.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
(S\$)	6,102.68	3,000.00	3,102.68	50.84
+ GST 7.00/7.00% (S\$)	427.19	210.00	217.19	50.84
<b>Nett Amount (S\$)</b>	<b>6,529.87</b>	<b>3,210.00</b>	<b>3,319.87</b>	<b>50.84</b>

**INSPECTION**

Date of Assignment:	23/03/2018	
Date Inspected:	23/03/2018	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2018)
<b>Parts:</b> 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJD3254A)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Badly Dented	784.80 FL	*784.80 FL
2	1		*TAIL GATE DOOR FIT EMBLEM	Necessary	31.90 FL	*31.90 FL
3	1		*TAIL GATE DOOR INNER LOCK	Dented/Shorted	109.40 FL	*109.40 FL
4	1		*TAIL GATE DOOR INNER LOCK STRICKER	Not Necessary	27.60 FL	*- FL
5	16		*TAIL GATE DOOR TRIM BOARD CLIPS	Not Necessary	92.80 FL	*- FL
6	1		*REAR WINDSCREEN GLASS TOP SEAL	Necessary	29.70 FL	*29.70 FL
7	1		*REAR WINDSCREEN GLASS LOWER SEAL	Necessary	34.70 FL	*34.70 FL
8	2		*REAR WINDSCREEN GLASS O/S & N/S SEAL	Necessary	49.40 FL	*49.40 FL
9	1		*REAR WINDSCREEN GLASS INNER DAMPER RUBBER	Necessary	28.30 FL	*28.30 FL
10	1		*TAIL GATE DOOR N/S STOPPER	Not Necessary	11.00 FL	*- FL
11	4		*TAIL GATE DOOR LICENCE GARNISH CLIPS	Not Necessary	18.00 FL	*- FL
12	1		*N/S TAIL LAMP ASSY	Cracked	226.20 FL	*226.20 FL
13	2		*N/S TAIL LAMP CLIPS STOPPER	Not Necessary	11.00 FL	*- FL
14	1		*N/S TAIL LAMP PANEL	Repair	143.90 FL	*- FL
15	1		*REAR BUMPER	Distorted	496.60 FL	*496.60 FL
16	8		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
17	1		*REAR BUMPER N/S SIDE RETAINER	Bent	28.70 FL	*28.70 FL
18	1		*REAR BUMPER N/S TOP RETAINER	Bent	17.50 FL	*17.50 FL
19	2		*REAR BUMPER N/S TOP SCREW	Not Necessary	13.60 FL	*- FL
20	1		*REAR END PANEL	Dented	296.60 FL	*296.60 FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	85.00 FL	*- FL
22	5		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	27.50 FL	*- FL
23	6		*REAR N/S FENDER INNER GARNISH CLIPS	Not Necessary	27.00 FL	*- FL
24	4		*REAR N/S WHEEL GUARD CLIPS	Not Necessary	16.00 FL	*- FL
25	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	45.00 FS	*40.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
27	1		*TAIL GATE DOOR WEATHERSTRIP	Torn	146.20 FL	*146.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,029.60</b>	<b>2,551.20</b>
- List Item Discount on L Items 20.00/20.00% (\$\$)	556.92	462.24
<b>Total Parts (\$\$)</b>	<b>2,472.68</b>	<b>2,088.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM	New	70.00	30.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	120.00
3	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD COVER,GARNISH,HINGE SHOCK ABSORBER,SPOILER,WIPER MOTOR & NECESSARY PARTS	New	150.00	60.00
4	TO REMOVE & REFIX CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,TOOL SET,REAR N/S FENDER GARNISH & NECESSARY PARTS	New	120.00	60.00
5	TO REMOVE & REFIX FUEL TANK HOSE,PIPE & NECESSARY PARTS	New	120.00	-
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	50.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT REAR N/S FENDER,TAIL LAMP PANEL,REAR END PANEL & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	1,400.00	600.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,630.00</b>	<b>1,720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >