

email on 22/03/2018
@1050hours

PEGASUS
ENGINEERING & TRADING PTE LTD
GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS 2 PTE LTD
28, SIN MING LANE,
#07-71 MIDVIEW CITY
SINGAPORE 573969

Attn :
Tel :
Fax :

Quotation No : QO18/03-1201	Quotation Date : 21/03/2018	Terms : 30 DAYS
Vehicle No : SLP8719G	Chassis No : JM6BN22A8H0154789	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: III, INSURED'S VEH NO: SHA7925K, DATE OF ACCIDENT: 21.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR N/S	1	1,062.0000	1,062.00 X
2	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	77.0000	77.00 X
3	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000	165.00 X
4	FRONT DOOR SIDE MIRROR COVER	1	123.0000	123.00 X
5	LESS 20% (ITEM 1 - 4)	1	-285.4000	-285.40
6	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	350.0000	350.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	480.0000	480.00
8	TO RUST-PROOFING OF THE AFFECTED PORTION		60.0000	60.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 2,031.60
GST(7.00%) 142.21
Total (SGD) 2,173.81

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216