



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY

SINGAPORE 079120

Contact : 996322096

Fax No. : 68357416

Estimate : QUOT201803-000627(00)

Date : 23/03/2018

Vehicle No. : SLR8331E

Make/Model : HONDA VEZEL HYBRID 1.5X AUTO

Mileage (km) : 0

Chassis No. : RU31253177

Accident Date : 22/03/2018 00:00:00

Claim No. : SLL1967Z

Reference : SLR8331E

Policy No. : 5094243790

*Not withairtel
1. B1
Presurvey B4 part 14 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bonnet	1.0	785.20	785.20 ✓
2	Front bonnet hinge	2.0	48.50	97.00 ✓
3	Front bonnet insulator	1.0	122.30	122.30 ✓
4	front bonnet lock	1.0	87.70	87.70 ?
5	Front bonnet LH side rubber moulding	1.0	23.40	23.40 ✓
6	Front grille base	1.0	351.80	351.80 ?
7	Front grille cover	1.0	421.00	421.00 ?
8	Front grille logo	1.0	34.00	34.00 ?
9	Front grille basket LH	1.0	19.60	19.60 ?
10	front grille basket RH	1.0	19.60	19.60 X
11	Front grille basket ctr	1.0	38.70	38.70 X
12	Headlamp	1.0	1,784.50	1,784.50 ✓
13	Front bumper	1.0	801.70	801.70 ✓
14	Front bumper reinforcement	1.0	321.00	321.00 ?
15	Front bumper side retainer	1.0	20.60	20.60 ✓
16	Front bumper - lower	1.0	381.00	381.00 ✓
17	Headlamp lower bracket	1.0	35.00	35.00 ?
18	Foglamp LH	1.0	327.70	327.70 ?
19	Foglamp cover LH	1.0	45.00	45.00 ?
20	Foglamp base LH	1.0	50.00	50.00 ?
21	Front LH fender	1.0	558.70	558.70 ✓
22	Front LH fender wheel arch garnish	1.0	195.00	195.00 ✓
23	Front LH fender innershield	1.0	135.00	135.00 ✓
24	Front LH fender shield guard	1.0	65.00	65.00 ✓
25	Front LH fender emblem - Hybrid	1.0	62.90	62.90 ✓
26	Wiper garnish	1.0	580.00	580.00 ✓
27	Wiper garnish side moulding	2.0	75.00	150.00 ✓
28	Air resonator box	1.0	180.00	180.00 ✓
29	LH ^{in wheel} rim	1.0	765.80	765.80 ✓
30	Front LH wheel bearing	1.0	181.40	181.40 ?
31	Front LH wheel hub	1.0	245.00	245.00 ?
32	Front LH shock absorber	1.0	337.90	337.90 ?
33	Front LH knuckle arm	1.0	390.00	390.00 ?
34	Front LH lower arm	1.0	374.10	374.10 ?
35	Front LH stabilizer bar linkage	1.0	65.00	65.00 X

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000627(00)

Date : 23/03/2018

Vehicle No. : SLR8331E

Make/Model : HONDA VEZEL HYBRID 1.5X AUTO

Mileage (km) : 0

Chassis No. : RU31253177

Accident Date : 22/03/2018 00:00:00

Claim No. : SLL1967Z

Reference : SLR8331E

Policy No. : 5094243790

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY

SINGAPORE 079120

Contact : 996322096

Fax No. : 68357416

S/No	Particular	Quantity	Unit Price	Amount S\$
36	Front LH wheel house extension panel	1.0	115.00	115.00 ✓
37	Front LH wheel house upper member	1.0	165.00	165.00 ✓
38	Front LH wheel house beam bracket	1.0	65.00	65.00 ?
39	Front LH side frame gusset	1.0	56.50	56.50 ?
40	Front LH side frame plate	1.0	105.50	105.50 ?
41	LH wing mirror stay	1.0	794.50	794.50 X
42	LH wing mirror cover	1.0	80.00	80.00 X
43	Front LH door	1.0	985.60	985.60 ✓
44	Front LH door hinge	2.0 <i>1 over B1</i>	45.00	90.00 ✓
45	Front LH door arrestor	1.0	55.00	55.00 ?
46	Front LH door lock	1.0	262.30	262.30 X
47	Front LH door catch	1.0	38.00	38.00 X
48	Front LH door rubber	1.0	81.40	81.40 ?
49	Front LH door frame sticker	1.0	30.00	30.00 ✓
50	Front LH door outer moulding	1.0	60.00	60.00 X
51	Front LH door glass regulator with motor	1.0	382.90	382.90 ?
52	Rear LH door	1.0	930.60	930.60 ✓
53	Rear LH door hinge	2.0 <i>1 over B1</i>	45.00	90.00 ✓
54	Rear LH door arrestor	1.0	55.00	55.00 X
55	Rear LH door lock	1.0	220.00	220.00 X
56	Rear LH door catch	1.0	38.00	38.00 X
57	Rear LH door rubber strip	1.0	29.20	29.20 ✓
58	Rear LH door stone guard	1.0	75.00	75.00 ✓
59	Front LH door pillar A	1.0	933.50	933.50 ?
60	Fuse box top cover	1.0	23.00	23.00 ✓
61	Fuse box (with harness)	1.0	1,200.00	1,200.00 ✓
62	Fuse box bracket	2.0	35.00	70.00 ?
63	Fuse box tray	1.0	55.00	55.00 ?
64	Battery	1.0	195.00	195.00 ✓
65	Rear LH wheel bearing	1.0	263.50	263.50 ?
66	Rear LH door frame sticker	1.0	28.00	28.00 ✓
67	Rear LH door glass regulator with motor	1.0	395.00	395.00 ?
68	Rear LH wheel arch garnish	1.0	195.00	195.00 ✓
69	LH side skuting	1.0	455.00	455.00 ?
70	LH side skuting stone guard	1.0	65.00	65.00 ?

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000627(00)

Date : 23/03/2018

Vehicle No. : SLR8331E

Make/Model : HONDA VEZEL HYBRID 1.5X AUTO

Mileage (km) : 0

Chassis No. : RU31253177

Accident Date : 22/03/2018 00:00:00

Claim No. : SLL1967Z

Reference : SLR8331E

Policy No. : 5094243790

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY

SINGAPORE 079120

Contact : 996322096

Fax No. : 68357416

S/No	Particular	Quantity	Unit Price	Amount S\$
	List Total :			18,735.10
	20% Discount S\$			3,747.02
				14,988.08
	SPECIAL NET :			
1	Tyre - Dunlop-EC300 -2015/60R16	1.0	285.00	285.00
	SPECIAL NET Total S\$:			228.00
	LABOUR :			
	*To transfer door mechanism	1.0	160.00	160.00
	*To change suspensions units	1.0	400.00	400.00
	*To conduct wheel alignment	1.0	65.00	65.00
	*To change fuse box unit, and check wiring	1.0	120.00	120.00
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,600.00	1,600.00
	- Spray painting on affected & replace parts	1.0	2,000.00	2,000.00
				4,345.00

E. & O.E.

Total S\$: 19,561.08

GST 7% S\$: 1,369.28

Amount Due S\$: 20,930.36

14A

for CITY AUTO PTE LTD