

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cynthia Loh

Date: 02 Apr 2018

## **Preliminary Advice**

Insured Vehicle No	: SHC5601Y	Accident Date	: 17/03/2018
TP Vehicle No	: SJW1885S	Assignment Date	: 22/03/2018
Make	: HONDA CIVIC 1.6 VTI CVT	Est. Duration of Repair	: 5 days
Date of Inspection	: 27/03/2018		
Inspection At	: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear o/s.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,488.43
Revised Amount	:S\$	4,003.60
Check Items (Estimated)	:S\$	4,829.60
Total	:S\$	8,833.20
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.