

ASS. REC. BY:

REF:

CS/EG18005465/Urd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

22/3/18 @ 4:57pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 8685D

Insured:

GBE 6781P

at Workshop m/s:

Bluwel Automotive

Tel:

6745 2088

of

1 Kaki Bkt Ave 6 #01-55 Blkc Autobay

Policy No:

Claim No:

GBE 6781 P / RH / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/03/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

5:26pm @ 22/3/18

Person Contacted:

Sally

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKG 8685D-CS / TP17013603 / Urd302
	GBE 6781P-X
4/4/18	Inform Pei Li pending workshop est by email
12/4/18	Email preli revised to Pei Li

D.O.A: 14/6/2017

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKG 868-Dat Workshop m/s Sum

of \_\_\_\_\_

Insured: G 13C 6781P

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 59k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: 6 Consistent?: Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKG 868-D Yr Regn: 10 / 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 4 /Make: Peugeot 508 SW c.c. 1598Colour: Black A/C: Insured / Std / NI / NASp. Reading: 154847 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF38E5FVACLO37810

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 40 R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ContinentalFront 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/3/18 D.O.I. 3/4/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & bal.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 50657claims. Rear section only.4yrs bnd. net 83431/4/18 confirmed 2/5 @ 8000 with kenny - (Red7886, sold

RECEIVED 12 APR 2018

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

12/4 - typistReport Format: TPLump Sum / I.B.I. (\$) 8000/2Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

350




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18005465/Uvd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 23-03-2018	
			Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 6781P	Veh. Inspected	SKG 8685D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBE 6781P/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	23/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	20/03/2018	Inspection Date		
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBE6781P/RH/pl  
Our Ref: CS/EG118005465/Uvd3

Date: 12/4/2018

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

*Without Prejudice*

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SKG 8685D**


We thank you for your instruction on 22/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/4/2018 at the premises of M/s BLUWEL AUTOMOTIVE SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,886.00
Revised Estimate Amount	: S\$8,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear and front portion



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 12 April 2018 9:23 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018  
**Attachments:** SKG 8685D PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SKG 8685D  
Date of survey: 3/4/2018  
Number of days:6 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 4 April 2018 2:30 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SKG 8685D on 3/4/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 22 March 2018 5:28 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

**Sent:** Thursday, 22 March 2018 4:57 PM

**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Subject:** OI : GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – CHUA KANG SENG** to be the "Single Joint Expert".

Please assist to conduct this survey from **M NEDUMARAN & CO.**

ADDRESS : BLUWEL AUTOMOTIVE SERVICE PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-55 BLK C AUTOBAY@KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : SALLY @ 6745 2088

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured's and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: [www.ergo.com.sg](http://www.ergo.com.sg)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 4 April 2018 2:30 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SKG 8685D on 3/4/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 22 March 2018 5:28 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Thursday, 22 March 2018 4:57 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – CHUA KANG SENG** to be the "Single Joint Expert".

Please assist to conduct this survey from **M NEDUMARAN & CO,**

ADDRESS : BLUWEL AUTOMOTIVE SERVICE PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-55 BLK C AUTOBAY@KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : SALLY @ 6745 2088

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured's and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Thursday, 22 March 2018 4:57 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : GBE6781P / TP : SKG8685D/LKK / DOA : 20/03/2018  
**Attachments:** GBE6781P - SAS.pdf; SKG8685D - SAS.pdf; SKG8685D - PRI NOTICE.pdf; SKG8685D - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – CHUA KANG SENG** to be the "Single Joint Expert".

Please assist to conduct this survey from **M NEDUMARAN & CO.**

ADDRESS : BLUWEL AUTOMOTIVE SERVICE PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-55 BLK C AUTOBAY@KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : SALLY @ 6745 2088

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured's and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**ERGO**

Date: 22.03.2018  
 Our Reference: GBE 6781P/RH/pl  
 Your Reference: MN/IG/B1/1812296/ST  
 To: M NEDUMARAN & CO

Sent via Fax 6509 8482  
 or  
 Email serene.tan@mneduco.com.sg

**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: SKG 8685D  
 Insured's Vehicle: GBE 6781P  
 Date Of Accident: 20.03.2018

We acknowledge receipt of your request for PRS on: 30.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from

the list below and indicate your selection in the box marked \*.

\* Chua Kang Seng  
(LKK Auto Consultants Pte Ltd)

AIS	Automobile Inspection Services Pte Ltd	LBS	LB.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's incomplete GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☐ Our Insured's driver has not reported the accident to us to date.  
☒ Others: OFFICER-IN-CHARGE - STEVE · Our client had selected Mr Chua Kang Seng from LKK Auto  
Consultant as a STE. However we have been instructed to deal with the claim. Our client  
and/or his workshop will not be keen on a direct settlement.

Prepared by: [Signature] Pei Li 6829 9194 claims@ergo.com.sg  
 Signature: [Signature] FAX: 6829 9247

**Assessor use only:**

Assignment Date: \_\_\_\_\_  
 Assignment Time: \_\_\_\_\_

Remarks:

**Workshop use only:****Assessor attended workshop on:**

Date: \_\_\_\_\_  
 Time: \_\_\_\_\_  
 Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

**M NEDUMARAN & CO**Advocates & Solicitors  
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan  
LLB (hons) [Buckingham]  
Barrister at Law (Lincoln's Inn)

*Please reply to our Branch Office for this matter*

  
 ⇨ Branch Office: 11 Sin Ming Road  
 #B2-09 (Unit 2) Thomson V Two  
 Singapore 575629  
 Tel : 6509-8480 / 6509-8481  
 Fax : 6509-8482  
 Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)  
[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)
Our Reference : MN/IG/B1/1812296/st  
Your Reference : GBE 6781PDate : 22<sup>nd</sup> March 2018ERGO INSURANCE PTE LTD  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

BY FAX 6829-9247 ONLY

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 20/03/2018 INVOLVING VEHICLE NOS. SKG 8685D, GBE 6781P & SHC 4303A ALONG ANG MO KIO AVENUE 3.

We are instructed by LIOW HOCK KENG (owner of motor vehicle no. SKG 8685D) and/or BLUWEL AUTOMOTIVE SERVICE PTE LTD (the motor workshop for SKG 8685D) to notify you of a road traffic accident on 20/03/2018 at about 1720 hours along ANG MO KIO AVE 3 involving our client's vehicle registration number [ SKG 8685D ] and [ GBE 6781P ] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
**M NEDUMARAN & CO - (Branch Office)**  
 Encl

c.c. 1) DRC Engineering Pte Ltd

(Vehicle : GBE 6781P )

- 2) NAME OF WORKSHOP :  
 Bluwel Automotive Service Pte Ltd  
 1 Kaki Bukit Avenue 6  
 #01-55 Blk C AutoBay@Kaki Bukit  
 Singapore 417883  
 Telephone : 6745-2088

(Vehicle : SKG 8685D )

(Attention : Ms Sally )

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- 2015 Forester 2.0
- 2016 BMW 2 Series Gran Tourer
- KIA Stinger GT

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Toyota Altis 1.6A



\$2800 Downpayment Monthly  
From \$688 Onwards. Lowest  
3.68% P.A @ Gv Cars Financing,  
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

Peugeot 508

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Peugeot 508		Any	Any	2012	Any	Any	Any	Available
	Peugeot 508	Peugeot 508 SW 1.6A Turbo Allure Plus	\$59,800	\$10,320 /yr	02-Jul-2012	1,598 cc	76,000 km	Stationwagon	Available
100% Quality Buy! With Full Service Record. Stylish Interior. Peace Of Mind With An Optional 1 Or 2 Years Warranty, Available In Showroom For Viewing Now.									
Posted: 30-Mar-2018 Tags: 2012 Peugeot 508, Peugeot 508, Peugeot, 508, Used Peugeot									
	Peugeot 508	Peugeot 508 1.6A Turbo Active	\$58,000	\$9,930 /yr	18-Oct-2012	1,598 cc	80,100 km	Luxury	Available
Elegant White, One Owner Only, Powerful Drive, High Paper Rebate Value "\$49400", Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available...									
Prime Motor & Leasing									
Posted: 30-Mar-2018 Tags: 2012 Peugeot 508, Peugeot 508, Peugeot, 508, Used Peugeot									
	Peugeot 508	Peugeot 508 1.6A Turbo Active	\$50,151	\$9,690 /yr	03-Jan-2012	1,598 cc	99,799 km	Luxury	Available
Just Arrived! Very Well Maintained By Ex Owner, 1 Year Extended Warranty, High Loan With High Trade In Available, Price Negotiable. Call Now Or Visit Our Showroom Today!									
Dosh Car									
Posted: 27-Mar-2018 Tags: 2012 Peugeot 508, Peugeot 508, Peugeot, 508, Used Peugeot									
	Peugeot 508	Peugeot 508 1.6A Turbo Allure Plus	\$52,800	\$9,590 /yr	22-Feb-2012	1,598 cc	109,818 km	Luxury	Available
Exclusive 1 Year Warranty & Free 3 Servicing Is Given To Our Value Customers At Our Very Own Workshop (VERMOGEN AUTO). The Peugeot 508 Actually Has A Conventional Design That Attracts Rather Than Alle...									
Posted: 17-Mar-2018 Tags: 2012 Peugeot 508, Peugeot 508, Peugeot, 508, Used Peugeot									
Car Buying	Car Selling	Car Ownership							
Car Aftermarket	On The Move	Lifestyle							
	Peugeot 508	Peugeot 508 SW 1.6A Allure Plus	\$62,000	\$10,500 /yr	14-Sep-2012	1,598 cc	88,700 km	Stationwagon	Available
1 Owner, Full Agent Maintained With Low Mileage Done At 16700KM Yearly, High COE, Accident Free. Free 1 Year QBE Extended Warranty, Lowest Dep In The Market, The Style And Comfort Of A Powerful Continen...									
Sng Auto Trading									
Posted: 04-Mar-2018 Tags: 2012 Peugeot 508, Peugeot 508, Peugeot, 508, Used Peugeot									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For advertisements, view Expired ads

20 results/page

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8057F

### Vehicle Details

Vehicle No.: SKG8685D  
Vehicle to be Exported: No  
Intended De-registration Date: 03 Apr 2018  
Vehicle Make: PEUGEOT  
Vehicle Model: 508 STATION WAGON 1.6 ALLURE PLUS  
HID  
Primary Colour: Brown  
Manufacturing Year: 2012  
Engine No.: 10FJBX1496553  
Chassis No.: VF38E5FVACL037810  
Maximum Power Output: 115.0 kW (154 bhp)  
Open Market Value: \$31,553.00  
Original Registration Date: 17 Oct 2012  
First Registration Date: 17 Oct 2012  
Transfer Count: 1  
Actual ARF Paid: \$31,553.00 15776

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 16 Oct 2022  
PARF Rebate Amount: \$22,087.00

### Intended COE Rebate Details

COE Expiry Date: 16 Oct 2022  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$63,000.00  
COE Rebate Amount: \$28,570.00  
**Total Rebate Amount: \$50,657.00**

The information contained herein is correct as at 03 Apr 2018

OK

BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6

#01-53/55

SINGAPORE 417883

VEHCILE NO:SKG 8685D

Not Authorized  
N/A  
3/4/18  
1/5 @ 8000/2  
6 day  
to keep photo after repair

QTY	PARTICULAR	AMOUNT
1 PCS	REAR WINDSCREEN MOULDING	rec \$110.00 ✓
1 PCS	TAILGATE	in/worpd \$1,820.00 ✓
1 PCS	TAILGATE REAR LOGO	rec \$68.00 ✓
1 PCS	TAILGATE PEUGEOT EMBLEM	rec \$69.00 ✓
1 PCS	TAILGATE '508SW' EMBLEM	rec \$65.00 ✓
1 PCS	TAILGATE REFLECTOR N/S	one \$285.00 ✓
1 PCS	TAILGATE WEATHERSTRIP	twi \$299.00 ✓
1 PCS	TAILGATE INNER TRIM BOARD	11 \$322.00 X
1 SET	TAILGATE INNER TRIM BORAD CLIPS	11 \$50.00 X
1 PCS	TAILGATE INNER LOCK	twi/shld \$299.00 ✓
1 PCS	TAILGATE OUTER GARNISH	one/worpd \$685.00 ✓
1 PCS	REAR BUMPER	in \$1,465.00 ✓
1 PCS	REAR BUMPER REINFORCEMENT	in \$495.00 ✓
1 PCS	REAR BUMPER INNER TOP RETAINER	one \$185.00 ✓
2 PCS	REAR BUMPER SIDE BRACKETS @\$105.00	set \$210.00 ✓
2 PCS	REAR BUMPER REFLECTORS @\$65.50	17 \$131.00 X
2 PCS	REAR BUMPER REVERSE SENSORS @\$245.00	shld \$490.00 ✓
2 PCS	TAILLAMPS @\$505.00	one \$1,010.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$320.00	2 \$640.00 X
1 PCS	REAR END PANEL	in \$982.00 ✓
1 PCS	REAR END PANEL TOP GARNISH	twi \$266.00 ✓
1 PCS	REAR FLOOR PANEL	2 \$1,480.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD	11 \$680.00 X
		8741
		7066.9
1 PCS	S.NETT	
1 PCS	REAR LICENSE PLATE W/HOLDER	set \$50.00 40
1 PCS	REAR WINDSCREEN SEALANT	rec \$50.00 40
1 PCS	REAR END PANEL SEALANT	rec \$50.00 ✓
1 SET	REAR FLOOR PANEL INSULATOR	11 \$200.00 X

TO CHECK WIRING	\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00 120
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$120.00 80

102

920

TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00 <sup>x</sup>
TO TRANSFER TAILGATE MECHANISM		\$100.00 <sup>80</sup>
TO SPRAY RUST PROOFING		\$100.00 <sup>50</sup>
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$1,200.00 <sup>680</sup>
REPLACING PARTS		
TO PUTTY & SPRAY PAINTING		\$1,500.00 <sup>980</sup>
TOTAL		\$15,886.00
		10066.9

Liability Insurance Company, hence notify the Rep. of the following:

- To resurvey body after ~~body~~ painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18005465/Uvd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 16-04-2018	
			Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 6781P	Veh. Inspected	SKG 8685D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBE 6781P/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	22/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PEUGEOT 508 SW (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	VF38E5FVACL037810	Colour	BLACK	
Odometer	154847	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/03/2018	Inspection Date	03/04/2018	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 8685D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN MOULDING	NECESSARY	110.00	110.00
1	TAILGATE	DENTED / WARPED	1,820.00	1,820.00
1	TAILGATE REAR LOGO	NECESSARY	68.00	68.00
1	TAILGATE PEUGEOT EMBLEM	NECESSARY	69.00	69.00
1	TAILGATE "508SW" EMBLEM	NECESSARY	65.00	65.00
1	TAILGATE REFLECTOR N/S	CRACKED	285.00	285.00
1	TAILGATE WEATHERSTRIP	TWISTED	299.00	299.00
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	322.00	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	TAILGATE INNER LOCK	TWISTED / SHORTED	299.00	299.00
1	TAILGATE OUTER GARNISH	CRACKED / WARPED	685.00	685.00
1	REAR BUMPER	DENTED	1,465.00	1,465.00
1	REAR BUMPER REINFORCEMENT	DENTED	495.00	495.00
1	REAR BUMPER INNER TOP RETAINER	CRACKED	185.00	185.00
2	REAR BUMPER SIDE BRACKETS @\$105.00	BENT	210.00	210.00
2	REAR BUMPER REFLECTORS @\$65.50	NOT NECESSARY	131.00	-
2	REAR BUMPER REVERSE SENSORS @\$245.00	SHORTED	490.00	490.00
2	TAILLAMPS @\$505.00	CRACKED	1,010.00	1,010.00
2	TAILLAMP HOUSING PANELS @\$320.00	TO REPAIR SEE LABOUR	640.00	-
1	REAR END PANEL	DENTED	982.00	920.00
1	REAR END PANEL TOP GARNISH	TWISTED	266.00	266.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,480.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	680.00	-
	LESS 10% DISCOUNT		-	-874.10
			12,106.00	7,866.90
<b>SPECIAL NETT ITEMS</b>				
1	REAR LICENSE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00

Report Ref No. CS/EGI18005465/Uvd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
			350.00	130.00
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO TRANSFER TAILGATE MECHANISM.		100.00	80.00
	TO SPRAY RUST PROOFING.		100.00	50.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS AND REAR FLOOR PANEL.		1,200.00	680.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	980.00
			3,430.00	2,070.00
<b>GRAND TOTAL</b>			<b>15,886.00</b>	<b>10,066.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,000.00</b>

Report Ref No. CS/EGI18005465/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.