

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5103Z
 Ref. No : TAX/03/18/2107
 Reg. Date : 19/02/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SEITOH HONG LOKE
 Type of Accident : OTHERS
 Date / Time of Accident : 21/03/2018 01:30:00 PM
 Accident Reported Date / Time : 21/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095142
 Special Instruction to ARC, if any :
 GBG2236M
 Prepared Date : 21/03/2018 03:13:25 PM



21/03/2018 e 1500ms

Hlt Antman

Lisura 5 dgo

ryan

2 KLC Ando

97237799

8

Photo after ryan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605767439

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,170.84	3,170.84
Other Charges	: 1,298.76	0.00
TOTAL	: 6,808.60	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00 5 days.
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 21/03/2018 05:15:05 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/03/2018 05:15:05 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67004-47080		6505487	DOOR RR/LH X	1	954.50	25.00	715.87	Replace	Replace	No <i>Vapeur</i>
75852-47900			MOULDING BODY, LH X	1	673.60	25.00	505.20	Replace	Replace	No <i>Rey</i>
61602-47091		6505476	FENDER RR/LH ✓	1	766.80	25.00	575.10	Replace	Replace	No <i>Painted</i>
62720-47031			QUARTER GLASS RR/LH X	1	168.10	25.00	126.07	Replace	Replace	No <i>SVL</i>
	COMMO N		SEALANT W/SCREEN ✓	1	37.00	0.00	37.00	Replace	Replace	No <i>Nke</i>
			STICKER DECAL SMRT ✓	1	7.80	0.00	7.80	Replace	Replace	No <i>Nke</i>
			STICKER DECAL 6555 8888 ✓	1	21.60	0.00	21.60	Replace	Replace	No <i>Nke</i>
42602-47060		6505676	CAP SUB-ASSY, WHEEL ✓	1	174.10	25.00	130.57	Replace	Replace	No <i>Cwt</i>
81561-47170		6505461	TAIL LAMP LH ✓	1	548.40	10.00	493.56	Replace	Replace	No <i>Crack</i>
52563-47010			TAIL LAMP BRACKET, LH X	1	30.70	25.00	23.02	Replace	Replace	No <i>SVL</i>
52159-47905		6505548	BUMPER REAR ✓	1	458.60	25.00	343.95	Replace	Replace	No <i>distorted</i>
			PIXEL STICKER ✓	2	60.00	0.00	120.00	Replace	Replace	No <i>Nke</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH X	1	94.80	25.00	71.10	Replace	Replace	No <i>SVL</i>
TOTAL MATERIALS								3,170.86	3,170.84	
TOTAL MATERIALS(Discounted)								3,170.84	3,170.84	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	845.00	0.00 600/-
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	0.00 200/-
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100/-
TO RESPRAY REAR FENDER LH	378.00	0.00 200/-
RESPRAY WHEEL CAP	180.00	0.00 X NH
TO REPSRAY REAR BUMPER	378.00	0.00 200/-
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X NH
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	<u>593.76</u>	0.00 ✓ WCL
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30/-
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40/-
TO TRANSFER DOOR MECHANISM	120.00	0.00 60/-
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 50/-
TO REPLACE SUNDRY PARTS	100.00	0.00 X NH
TO WASH AND VACUUM	60.00	0.00 X NH
Total Other Costs	1,298.76	0.00