

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ernest Tay

Date: 06 Apr 2018

**Preliminary Advice**

Insured Vehicle No : SHD9915K  
TP Vehicle No : XE2892T  
Make : UD TRUCKS GKB5ELDHNT ESCOT  
V  
Date of Inspection : 05/04/2018  
Inspection At : Volvo East Asia (pte) Ltd - Tuas (HQ)  
12 Tuas Avenue 10  
Singapore 639136  
Accident Date : 14/03/2018  
Assignment Date : 22/03/2018  
Est. Duration of Repair : 4 days

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...O/S front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,573.00
Revised Amount	:S\$	3,581.00
Check Items (Estimated)	:S\$	234.00
Total	:S\$	3,815.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.