

SMRT Accident Vehicle Repair Estimates


3-4-18 / 13:00

4-4-18 / 08:00

21-3-18 / 08:00

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5795B
 Ref. No : TAX/03/18/2095
 Reg. Date : 12/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : ISMAIL BIN ALI
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 18/03/2018 12:30:00 AM
 Accident Reported Date / Time : 19/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time : 18/03/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095106
 Special Instruction to ARC, if any :
 TOWED \$90 / SGH245K
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
 Prepared Date : 19/03/2018 12:08:01 PM



18:25

16-18

pass

37767

37733

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 20-3-18

2nd witness

Date 1-6-18

(R) rear camera not in the car

Front.

Supplementary
 to Report the Supplementary part 1/1/18

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 1/6/18

Vehicle Return Time: 1437

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU003575910

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,179.00	1,800.00
Total Spray Painting Charges :	5,886.00	1,800.00
Total Material Charges :	24,436.02	14,936.52
Other Charges :	2,785.00	975.00
TOTAL :	35,286.02	19,511.52
Lump Sum Total :	0.00	0.00
No. of Repair Days :	16.00	15.00
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	20/03/2018 11:21:06 AM	20/03/2018 04:11:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/03/2018 11:02:18 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	QN-1806-0125	Invoice No :	
Quotation Date :	6/6	Invoice Date :	
Invoice Amount :		Prepared Date :	

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	2,179.00	1,800.00
Total Labour	2,179.00	1,800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY REAR SPOILER	180.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00
TO RESPRAY FILLER RR BUMPER LH	180.00	50.00
TO RESPRAY FILLER RR BUMPER RH	180.00	50.00
TO RESPRAY ROOF TOP PANEL	378.00	0.00
TO RESPRAY RH RAIL ROOF SIDE	180.00	100.00
TO RESPRAY LH RAIL ROOF SIDE	180.00	100.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY REAR CHASSIS LH	180.00	50.00
TO RESPRAY REAR CHASSIS RH	180.00	50.00
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00
TO RESPRAY RH REAR WHEEL HOUSE	180.00	0.00
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00
TO RESPRAY REAR FENDER RH	378.00	200.00
TO RESPRAY REAR FENDER LH	378.00	200.00
TO RESPRAY REAR DOOR LH	378.00	200.00
TO RESPRAY REAR DOOR RH	378.00	200.00
TO RESPRAY MEMBER SUB-ASSY, CENTER FLOOR CROSS , NO.2	180.00	0.00
TO RESPRAY MEMBER, REAR FLOOR CROSS , NO.3	180.00	0.00
Total Spray Painting & Panel Beating	5,886.00	1,800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60.00
TO REMOVE / REFIT SEAT	120.00	0.00
TO ALIGN CHASSIS	350.00	200.00
TO REMOVE & REFIT EXHAUST	120.00	50.00
TO REMOVE & REFIT FUEL TANK	120.00	0.00
TO CHECK & RESET SYSTEM FUNCTION	350.00	200.00
TO TRANSFER DOOR MECHANISM	240.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	2,785.00	975.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No ✓
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No ✓
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No ✓
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No ✓
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No ✓
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No ✓
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace	No ✓
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No ✓
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No ✓
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No ✓
5259968030			STOPPER, RR BUMPER, RH & LH	2	4.30	25.00	6.45	Replace	Replace	No ✓
5259247040			SEAL, RR BUMPER , LH	1	85.20	25.00	63.90	Replace	Replace	No ✓
5259147050			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Check	No X
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No ✓
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No ✓
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No ✓
8158147010			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Replace	No ✓
8159147010			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	10.00	438.12	Replace	Replace	No ✓
9018906029			REAR BUMPER GROMMET SCREW	2	2.20	25.00	3.30	Replace	Replace	No ✓
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace	No ✓
5839947030			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.73	Replace	Replace	No ✓
5839847050			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.13	Replace	Check	No X
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No ✓
9046717026A0			CLIP , FLOOR UNDER COVER , NO.1	10	2.60	25.00	19.50	Replace	Replace	No ✓
9046717027C0			CLIP , FLOOR UNDER COVER , NO.2	10	3.20	25.00	24.00	Replace	Replace	No ✓
5832747040			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	25.00	102.75	Replace	Replace	No ✓

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
1743037730			PIPE ASSY, EXHAUST TAIL	1	1,173.90	25.00	880.42	Replace	Replace	No ✓
1756522040			SUPPORT, EXHAUST PIPE NO.5	2	41.10	25.00	61.65	Replace	Check	No X
1756528010			SUPPORT, EXHAUST PIPE NO.4	1	41.10	25.00	30.83	Replace	Check	No X
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No ✓
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No ✓
6881047061			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	25.00	88.65	Replace	Check	No X
6896147010			TAIL GATE BOLT, BACK DOOR STAY, RH & LH	2	11.80	25.00	17.70	Replace	Replace	No ✓
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No ✓
6932147010			TAIL GATE LOCK COVER, BACK DOOR	0	25.30	25.00	0.00	Replace	Not given	No X
689600W860			TAIL GATE STAY ASSY, BACK DOOR, LH	1	235.00	25.00	176.25	Replace	Check	No X
689500W860			TAIL GATE STAY ASSY, BACK DOOR, RH	1	235.00	25.00	176.25	Replace	Check	No X
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace	No ✓
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace	No ✓
6480147031			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace	No ✓
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No ✓
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No ✓
7557447040			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	25.00	22.42	Replace	Replace	No ✓
7557347110			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	25.00	22.42	Replace	Replace	No ✓
6481947080			TAIL GATE SPACER, BACK DOOR GLASS, LH	1	6.90	25.00	5.17	Replace	Replace	No ✓
6481847080			TAIL GATE SPACER, BACK DOOR GLASS, RH	1	6.90	25.00	5.17	Replace	Replace	No ✓
6278547010			TAIL GATE SPACER, QUARTER BACK DOOR GLASS	1	5.50	25.00	4.12	Replace	Replace	No ✓
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No ✓
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No ✓
6894552110			TAIL GATE STAY BRACKET, BACK DOOR, RH & LH	2	11.80	25.00	17.70	Replace	Check	No X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6472147050C0			TAILGATE BOARD , COVER	1	24.10	25.00	18.07	Replace	Replace	No ✓
7481147020C0			TAILGATE BOARD , HANDLE PULL	1	19.50	25.00	14.62	Replace	Replace	No ✓
6775047080C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.63	Replace	Replace S	No ✓
6793847060C0			TAILGATE TRIM , LH	1	92.10	25.00	69.08	Replace	Check	No X
6775147110C0			TAILGATE TRIM , LOWER	1	218.50	25.00	163.88	Replace	Check	No X
6793747060C0			TAILGATE TRIM , RH	1	92.10	25.00	69.08	Replace	Check	No X
6479047060C0			TAILGATE TRIM , UPPER	1	50.50	25.00	37.88	Replace	Check	No X
7512913020			TAIL GATE CUSHION, REAR LICENCE PLATE	2	2.10	25.00	3.15	Replace	Check	No X
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No ✓
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No ✓
8127033110			LAMP ASSY, LICENSE PLATE	2	63.70	10.00	114.66	Replace	Check	No X
867B047010			CAMERA REAR ASSY, TELEVISION	1	1,103.80	10.00	993.42	Replace	Check	No X
8484047040			SWITCH ASSY, BACK DOOR OPENER	1	149.40	10.00	134.46	Replace	Check	No X
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace	No ✓
8218447490			WIRE, TAIL GATE BACK DOOR,	1	246.80	10.00	222.12	Replace	Check	No X
8218547150			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	10.00	222.12	Replace	Check	No X
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.58	Replace	Replace S	No ✓
8100647030			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	Replace	Replace S	No ✓
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ✓
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ✓
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No ✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
6311147060			PANEL, ROOF	1	1,245.20	25.00	933.90	Repair	Check	No X
7560747010			MOULDING SUB-ASSY, ROOF TOP	1	637.40	25.00	478.05	Replace	Check	No X
7505647010			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	52.70	25.00	39.53	Replace	Check	No X
7505547010			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	1	52.70	25.00	39.53	Replace	Check	No X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6101847010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	100.00	0.00	Replace	Repair	No <i>R</i>
6101747010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	100.00	0.00	Replace	Repair	No <i>R</i>
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No <i>/</i>
6471847080C0			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Replace	No <i>/</i>
6471647130C0			END PANEL, COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace	No <i>/</i>
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	2	56.70	25.00	85.05	Replace	Check	No <i>X</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No <i>/</i>
5831147130			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace <i>S</i>	No <i>/</i>
5831647010			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	25.00	57.15	Replace	Check	No <i>X</i>
5831547020			EXTENSION, REAR FLOOR SIDE PANEL, RH	1	76.20	25.00	57.15	Replace	Check	No <i>X</i>
5760347060			MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR RH	1	268.60	25.00	201.45	Replace	Check	No <i>X</i>
5760447060			MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR LH	1	268.60	25.00	201.45	Replace	Replace <i>S</i>	No <i>/</i>
5765347040			MEMBER, REAR FLOOR CROSS, NO. 3	1	219.00	25.00	164.25	Replace	Check	No <i>X</i>
5740547010			MEMBER SUB-ASSY, CENTER FLOOR CROSS, NO.2	1	500.50	25.00	375.38	Replace	Check	No <i>X</i>
6160847900			PANEL QUARTER WHEEL HOUSE, INNER LH	1	527.00	25.00	395.25	Replace	Replace	No <i>/</i>
6160747900			PANEL QUARTER WHEEL HOUSE, INNER RH	1	527.00	100.00	0.00	Replace	Repair	No <i>R</i>
5841547110C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace <i>S</i>	No <i>/</i>
6499347110			BOX, DECK FLOOR, REAR	1	102.20	25.00	76.65	Replace	Check	No <i>X</i>
6499747060			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Replace <i>S</i>	No <i>/</i>
6499547050			BOX, DECK FLOOR, RH	1	304.00	25.00	228.00	Replace	Replace <i>S</i>	No <i>/</i>
6474047190C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace	No <i>/</i>
6473047240C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.52	Replace	Replace	No <i>/</i>
6491047060C0			COVER ASSY, TONNEAU	1	944.20	25.00	708.15	Replace	Check	No <i>X</i>
8216147N40			WIRE, FLOOR	1	3,860.00	10.00	3,474.00	Replace	Check	No <i>X</i>
5835112060			BRACKET, SPARE WHEEL CLAMP	1	21.30	25.00	15.98	Replace	Check	No <i>X</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No ✓
6162247060			TROUGH, BACK DOOR, LH	1	99.80	25.00	74.85	Replace	Replace S	No ✓
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace S	No ✓
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	25.00	48.75	Replace	Replace	No ✓
6563847060			LINER, REAR FENDER, LH	1	135.80	25.00	101.85	Replace	Check	No X
6700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	100.00	0.00	Replace	Repair	No R
6906052280			DOOR LOCK REAR, LH	1	544.70	10.00	490.23	Replace	Check	No X
6941020110			DOOR LOCK STRIKER	1	38.00	25.00	28.50	Replace	Check	No X
6878052031			HINGE ASSY, REAR DOOR, LOWER LH	1	73.30	25.00	54.98	Replace	Check	No X
6876020122			HINGE ASSY, REAR DOOR, UPPER LH	1	83.30	25.00	62.48	Replace	Check	No X
6863047050			CHECK ASSY, REAR DOOR	1	153.50	25.00	115.13	Replace	Check	No X
8155147281			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Replace	No ✓
6162147050			TROUGH, BACK DOOR, RH	1	99.80	25.00	74.85	Replace	Replace S	No ✓
6160147150			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	100.00	0.00	Replace	Repair	No R
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	0	65.00	25.00	0.00	Replace	Not given	No X
6563747060			LINER, REAR FENDER, RH	1	135.80	25.00	101.85	Replace	Check	No X
6700347210			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	100.00	0.00	Replace	Repair	No R
6905052250			DOOR LOCK REAR, RH	0	544.70	10.00	0.00	Replace	Not given	No X
6941020110			DOOR LOCK STRIKER	0	38.00	25.00	0.00	Replace	Not given	No X
6877052031			HINGE ASSY, REAR DOOR, LOWER RH	0	73.30	25.00	0.00	Replace	Not given	No X
6875020122			HINGE ASSY, REAR DOOR, UPPER RH	0	83.30	25.00	0.00	Replace	Not given	No X
6863047050			CHECK ASSY, REAR DOOR	0	153.50	25.00	0.00	Replace	Not given	No X
5193147030			CARRIER, SPARE WHEEL	1	20.00	25.00	15.00	Replace	Replace S	No ✓
5120647012			REAR MEMBER SUB-ASSY, RR	1	2,171.70	25.00	1,628.77	Replace	Replace S	No ✓
			INSULATOR SHEET	1	41.48	10.00	37.33	Replace	Replace S	No ✓
TOTAL MATERIALS							24,436.15	14,936.54		
TOTAL MATERIALS(Discounted)							24,436.02	14,936.52		

Added Spare Parts / Material Usage After Surveyor Signed off

14,936.52
 + 1,800.00
 + 2,775.00
 19,511.52