

ASS. REC. BY: Adrian Ling

REF:

C03/ALH18005592 / Afb JV

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100480111Claims No. 382159360186

Sum Insured: _____

Excess: \$800/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 130K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04/8/18 days

Res: Yes or No

Lum Sum: _____ %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGM81816Yr Regn: 2016Aug 24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6.c.c. 1984Colour: Black.

A/C: Insured / Std / NI / NA

Sp. Reading: 18728.

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4G3HND13183Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R18.R: 245/45R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 23/03/18Survey held at: Premium.Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A16

RECEIVED 27 JUL 2018

SGM 81816

26032018 Received estimate and GIA report

Part by Part \$13,493.08 (Red. 1752892 : 56%)

Date/Time, File Pass to?



Prel. Report

1) 27/7/18 Typist

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)

Photos

Others

TOTAL

Report Format: DDLump Sum / B.I. (\$) 13493.08



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18005592/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 26-03-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGM 8181G
Policy No. 2100480111	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	23/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 22/03/2018	Inspection Date 23/03/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8181I
Vehicle Details	
Vehicle No.:	SGM8181G
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI (PI)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CYP031331
Chassis No.:	WAUZZZ4G3HN013183
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$47,533.00
Original Registration Date:	24 Aug 2016
First Registration Date:	24 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$58,547.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2026
PARF Rebate Amount:	\$43,910.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$47,100.00
Total Rebate Amount:	\$91,010.00

The information contained herein is correct as at 04 Jul 2018

OK

VDR: 22/2/18

PARF: 43910

$$\begin{aligned}
 \text{COE} &= \text{QP} \times \frac{\text{km/mile}}{\text{QP}} \\
 &= 57903 \times \frac{101}{120} \\
 &= 48735.03
 \end{aligned}$$

$$\begin{aligned}
 \text{VTA} &= \text{PARF} + \text{COE} \\
 &= 92645.03
 \end{aligned}$$

$$\approx \text{VTA} = 92645$$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/03/2018 12:23
Date Of Accident	22/03/2018 19:35
Exact Location Of Accident	PIE ALJUNIED FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM8181G
Insured/Policyholder	
Name Of Registered Owner	LOH WEE JUAN
NRIC No	S1288181I
Email Address	MAURITZ@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96325579
Alternative Phone No	OTHERS-96325579

Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.0 TFSI S-TRO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100480111-01
Cover Note Number	

Driver

Name of Driver	LOH WEE JUAN
NRIC No	S1288181I
Date Of Birth	08/06/1958
Occupation	INDOOR
Date Of Driving Pass	03/06/1978
Driving Experience	39 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96325579
Fax Number	
Contact Number	OTHERS-96325579
Email Address	MAURITZ@SINGNET.COM.SG

Address	993 BUKIT TIMAH ROAD #07-14
Postcode	589631
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 22 MARCH 2018, AT 19:34 HR, WHILE DRIVING ON PIE ALJUNIED FLYOVER TO TUAS. THERE WAS A CAR (HONDA JAZZ SLE4860A), APPLYING EMERGENCY BRAKE AND STOPPED AT DOWN SLOPE. I ALSO APPLIED EMERGENCY BRAKE BUT COULD NOT STOP ON TIME AND TOUCH THE CAR IN FRONT OF ME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE4660A
Vehicle Make/Model/Colour	HONDA / JAZZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tan Fong
NRIC/TIN No.: 624407

Sketch Plan #2

SKETCH PLAN



A=SGM8181G

B=SLK 4660A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22 March 2018 @ 19-34hr while driving on PIE Aligned to over to Tuas. There was a car (HONDA JAZZ SLK 4660A) applying emergency brake and stopped at down slope. I also applied emergency brake but could not stop on time and ~~coll~~ touch the car in front of me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Mavy

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/NTN No: G20401079

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S12881811



LOH WEE JUAN

羅惠源

Race

CHINESE

Date of Birth

08-06-1958

Sex

M

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S12881811

Name

LOH WEE JUAN

Birth Date: 08 Jun 1958

Valid Date: 10 May 2003



1783415



NRIC No: S12881811

Blood Group

Date of Issue

B+

11-03-1994

NRIC No:

S12881811

Date:

27-07-1993

No:

2360779


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

03 Jun 1978



Licence No: S12881811

NP 428A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Loh Wee Juan
Period of Insurance : 24 Aug 2017 To 23 Aug 2018
Engine No. : CYP031331
Chassis No. : WAUZZZ4G3HN013183

Vehicle No. : SGM8181G
Policy No. : 2100480111-01
Endorsement No. :
Issued Date : 15 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A6 2.0 TFSI S TRONIC (PI)
Engine Capacity/Tonnage : 1,984.00 CC
Sum Insured : Market Value
Driver Restriction : NA
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Loh Wee Juan - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
 Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore. You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1999 (Malaysia).

0356008000

TAN KAY JOO CHARLIE

46A TOH TUCK ROAD #04-02 SIGNATURE PARK

SINGAPORE 396738

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SGPDCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0366/2018/GW
Date	:	24-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Loh Wee Juan
Address	:	Blk 932 Bukit Timah road #07-14 Singapore 589631
Telephone	:	HP +65 96325579
Type of Claim	:	Own Damage Claims
Policy No.	:	2100480111-01
Vehicle No	:	SGM 8181 G
Model Code	:	Audi A6 2.0 TFSI S-Tronic
Model / Year	:	Aug-16
Engine No	:	CYP 031331
Chassis No	:	WAUZZZ463HN013193
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Mar-18
Place of Accident	:	PIE Aljunied Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGM 8181 G.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper assy and both headlights. Re-organise front crash management components. Inspect bonnet for damages. Reinstall all parts removed.	\$ 2,100.00 500 750	
3	To respray front bumper and bonnet.	\$ 1,700.00 550 ✓	✓
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 4,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 8181 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>2pc of</i>	\$ 2,915.00 X	2204
3	FRONT BUMPER SPOILER <i>Repair</i>	\$ 817.00 X	Pricing ???
4	RADIATOR GRILLE <i>cracked</i>	\$ 3,101.00	248080
5	FRONT RADIATOR GRILLE <i>not in</i>	\$ 32.00 X	
6	LICENCE PLATE HOLDER <i>Not New</i>	\$ 1,074.00 ?	
7	FRONT PARKING AID SENSOR <i>not in</i>	2 \$ 392.00 X	
8	FOAM FILLER PIECE <i>Not New</i>	\$ 203.00 ?	
8	FRONT SIDE REINFORCEMENT <i>Not New</i>	\$ 702.00 X	
9	FRONT BUMPER COVER <i>Del</i>	\$ 105.00 ✓	84
9	SIGN " CAUTION "	\$ 12.00 ✓	9.28
10	HEADLIGHT-LH/RH <i>At home LH cracked</i>	2 \$ 16,772.00 X	670880
11	FRONT NO.PLATE <i>New</i>	S/N \$ 25.00 ✓	25
12	SUNDRIES <i>Pen</i>	\$ 400.00 ?	9.20
TOTAL SPARE PARTS CHARGES		: \$ 26,550.00	
TOTAL LABOUR CHARGES		: \$ 4,472.00	
GRAND TOTAL		: \$ 31,022.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian Lim
23/03/18.

Authorised repairs, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts; during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0366/2018/GW
Date : 24-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 20 Jun 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loh Wee Juan
Address : Blk 932 Bukit Timah road
#07-14
Singapore 589631
Telephone : HP +65 96325579
Type of Claim : Own Damage Claims
Policy No. : 2100480111-01
Vehicle No : **SGM 8181 G**
Model Code : Audi A6 2.0 TFSI S-Tronic
Model / Year : Aug-16
Engine No : CYP 031331
Chassis No : WAUZZZ463HN013193
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Mar-18
Place of Accident : PIE Aljunied Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGM 8181 G.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper assy and both headlights. Re-organise front crash management components. Inspect bonnet for damages. Reinstall all parts removed. (Headlamp replaced)	\$	2,100.00	\$ 750.00
3	To respray front bumper and bonnet.	\$	1,700.00	\$ 550.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,472.00</u>	<u>\$ 1,972.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 8181 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,915.00	\$ 2,204.00
3	FRONT BUMPER SPOILER	\$ 817.00	
4	RADIATOR GRILLE	\$ 3,101.00	\$ 2,480.80
5	FRONT RADIATOR GRILLE	\$ 32.00	
6	LICENCE PLATE HOLDER	\$ 1,074.00	
7	FRONT PARKING AID SENSOR	2 \$ 392.00	
8	FOAM FILLER PIECE	\$ 203.00	
8	FRONT SIDE REINFORCEMENT	\$ 702.00	
9	FRONT BUMPER COVER	\$ 105.00	\$ 84.00
9	SIGN " CAUTION "	\$ 12.00	\$ 9.28
10	HEADLIGHT-LH/RH	2 \$ 16,772.00	\$ 6,708.80
11	FRONT NO.PLATE	S/N \$ 25.00	\$ 25.00
12	SUNDRIES	\$ 400.00	\$ 9.20
TOTAL SPARE PARTS CHARGES		: \$ 26,550.00	\$ 11,521.08
TOTAL LABOUR CHARGES		: \$ 4,472.00	\$ 1,972.00
GRAND TOTAL		: \$ 31,022.00	\$ 13,493.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGM 8181 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0366/2018/MAS

26 July 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGM 8181 G, Audi A6 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no **SGM 8181 G**, claimant, **Mr. Loh Wee Juan**, please find the related document per attached.

1. A copy of the Original invoice no. 85012755 – S\$14,009.60
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGM 8181 G

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1288181I



LOH WEE JUAN

羅惠源

Race

CHINESE

Date of Birth

08-06-1958

Country of Birth

SINGAPORE

Sex

M

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S1288181I

LOH WEE JUAN

Birth Date 08 Jun 1958

Issue Date 10 May 2003



1783415

NRIC No. S1288181I



Blood Group

B+

Date of issue

11-03-1994

614 882 BUKIT TIMAH ROAD #01-14
SINGAPORE 596371

NRIC No.

Date:

01-07-1981

No:

2360779

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

03 Jun 1978



Licence No: S1288181I

NP 428A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Loh Wee Juan
Period of Insurance : 24 Aug 2017 To 23 Aug 2018
Engine No. : CYP031331
Chassis No. : WAUZZZ4G3HN013183

Vehicle No. : SGM8181G
Policy No. : 2100480111-01
Endorsement No. :
Issued Date : 15 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A6 2.0 TFSI S TRONIC (PI)
Engine Capacity/Tonnage : 1.984.00 CC Sum Insured : Market Value First Year of Registration : 2016
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Loh Wee Juan - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs):

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0356008000

TAN KAY JOO CHARLIE

46A TOH TUCK ROAD #04-02 SIGNATURE PARK

SINGAPORE 596738

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPDCP



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733
Page 1 17:59

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408823
Telephone: 6386 2223
Telefax: 6475 1023

Customer Service
Service Appointment: 6386 2323
24-hour Breakdown Service: 6828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012755 Date : 19/07/2018 Order : SGM81816 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGM81816 (V 31094) Regn Date: 24/08/2016 Mileage: 19510 WIP No.: 59882
Model: AG 2.0 TFSI S tronic 4GC086 (N Chassis: WAUZZZ4G3HN013103 Engine: CYP 031331 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-400.00	1.00	-400.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER ASSY AND RHS HEADLIGHTS. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS	192.00	1.00	192.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 8733
Page 2 17:59

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6386 2223
Telefax 6475 1023

Ubi Service Centre
95 Ubi Road 1
Singapore 408699
Telephone 6386 2223
Telefax 6475 1023

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2323
9828 1233

INS TAX INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012755 Date : 19/07/2016 Order : SGM81816 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGM81816 (V 31094) Regn Date: 24/08/2016 Mileage: 19510 WIP No.: 59882
Model: A6 2.0 TFSI S tronic 4GC086 (N Chassis: WAUZZZ4G3HN013163 Engine: CYP 031331 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A460853651BTKFQ	GRILLE (G) (V)	1.00	3101.00	2,480.80
X	A460941774J	HEADLIGHT	1.00	8386.00	6,786.80
X	A460807081D	COVER	1.00	105.00	84.00
X	A46080706588GRU	COVER	1.00	2755.00	2,284.00
X	ABK0010520A	PLATE	1.00	11.60	9.28
X	AN 10528301	SUNDRY	1.00	11.50	9.20

Parts 11,496.08	Sub-Total	13,093.68
Labour 0.00	7% GST	916.52
Sublet 1,997.00	Grand Total	14,009.60
Menus 0.00		
Lubricant 0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGM 8181 G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0366/2018/GC
17 April 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 2.0 TFSI S-TRONIC
Vehicle Chassis No. : WAUZZZ4G3HN013183
Vehicle Regn No. : SGM 8181 G
Vehicle Mileage : 19510 km
Vehicle Owner : Mr. Loh Wee Juan
Certificate No : 2100480111-01
Policy Excess : S\$428.00(inclusive 7% GST)
Accident Date : 22/03/2018
Place : PIE Aljunied Flyover
Repair Cost : \$ 14,009.60
WIP No. : 59882
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

_____ 21/4/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018		26 Mar 2018 16:30 Edit Adj Rpt	S\$13,493.08 Edit Estimates	S\$13,493.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LOH WEE JUAN, ID: S12881811, Tel: +6596325579, Email: MAURITZ@SINGNET.COM.SG								
Vehicle Reg. No.:	SGM8181G		Date of Loss:	22/03/2018 19:00 - :59 [18 Months and 26 Days From LTA Reg Date (Man Yr)]					
Claim Type:	OD / 3821593601SG		Policy/Cover Note No.:	2100480111 (Comprehensive)					
			Excess:	S\$400.00					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/04/2018]								
Driver/Custodian:	LOH WEE JUAN (59 / Male), NRIC: S12881811, Tel: +6596325579								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (05/07/2018): Alert - Adj Mandate Approved (S\$13493.08) - SGM8181G - Claim Handler: Tr, Tinesh - AIG_SG (29/03/2018): SGM8181G / OD / 22/03/2018 / Coverage & Excess update - AIG_SG (27/03/2018): SGM8181G / OD / 22/03/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGM8181G (3821593601SG)
 OD
 Mar 22 2018 7:00PM
 [LOH WEE JUAN]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Video														1 per page v		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	29/03/18 15:35	Video - Accident											Load MP4				
Assessment Reports														1 per page v		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	04/07/18 17:54	Adjuster Immediate Advice											Load HTM				
Photos/Images														3 per page v		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	29/06/18 17:55	General View											Load JPG	☒			
2	29/06/18 17:55	General View											Load JPG	☒			
3	29/06/18 17:55	General View											Load JPG	☒			
4	29/06/18 17:55	General View											Load JPG	☒			
5	29/06/18 17:55	General View											Load JPG	☒			
6	29/06/18 17:55	General View											Load JPG	☒			
7	29/06/18 17:55	General View											Load JPG	☒			
8	29/06/18 17:55	General View											Load JPG	☒			
9	29/06/18 17:55	General View											Load JPG	☒			
10	29/06/18 17:55	General View											Load JPG	☒			
11	29/06/18 17:55	General View											Load JPG	☒			
12	29/06/18 17:55	General View											Load JPG	☒			
13	29/06/18 17:55	General View											Load JPG	☒			
14	29/06/18 17:55	General View											Load JPG	☒			
15	29/06/18 17:55	General View											Load JPG	☒			
16	29/06/18 17:55	General View											Load JPG	☒			
17	29/06/18 17:55	General View											Load JPG	☒			
18	29/06/18 17:55	General View											Load JPG	☒			
19	29/06/18 17:55	General View											Load JPG	☒			
20	29/06/18 17:55	General View											Load JPG	☒			
21	29/06/18 17:55	General View											Load JPG	☒			
22	29/06/18 17:55	General View											Load JPG	☒			
23	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
24	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
25	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
26	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
27	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
28	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
29	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
30	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
31	29/06/18 17:55	Reinspection Photo											Load JPG	☒			
32	29/06/18 17:55	Reinspection Photo											Load JPG	☒			

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	29/06/18 17:55	Reinspection Photo	 Load JPG	☒
34	29/06/18 17:55	Reinspection Photo	 Load JPG	☒
35	29/06/18 17:55	Reinspection Photo	 Load JPG	☒
36	29/06/18 17:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/18 15:09	Certificate of Insurance	 Load PDF	
2	27/03/18 15:09	Driver's Driving License	 Load PDF	
3	27/03/18 15:09	Singapore Accident Statement	 Load PDF	
4	27/03/18 15:09	ESTIMATE	 Load PDF	
5	02/07/18 15:18	ESTIMATE 1	 Load PDF	
6	30/07/18 09:48	WORKSHOP INVOICE	 Load PDF	
7	30/07/18 09:48	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/03/18 13:30	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/03/18 13:22	Accident Photo	 Load JPG	☒
2	23/03/18 13:22	Accident Photo	 Load JPG	☒
3	23/03/18 13:22	Accident Photo	 Load JPG	☒
4	23/03/18 13:22	Accident Photo	 Load JPG	☒
5	23/03/18 13:22	Accident Photo	 Load JPG	☒
6	23/03/18 13:22	Accident Photo	 Load JPG	☒
7	23/03/18 13:22	Accident Photo	 Load JPG	☒
8	23/03/18 13:22	Accident Photo	 Load JPG	☒
9	23/03/18 13:22	Accident Photo	 Load JPG	☒
10	23/03/18 13:22	Accident Photo	 Load JPG	☒
11	23/03/18 13:22	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/03/18 13:29	Sketch Plan	 Load JPG	☒
2	23/03/18 13:29	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18005592/ATBQ2

Date: 30/07/2018

REFERENCE

Insured/Claimant: LOH WEE JUAN Policy No: 2100480111
Date of Loss: 22/03/2018 Nature of Claim: OD Claim No: 3821593601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM8181G**
Make & Model: AUDI A6, 2.0 TFSI (A) Engine No: CYP031331
Reg. Date: 24/08/2016 (Man. Year: 2016) Chassis No: WAUZZZ4G3HN013183
Colour: Black Odometer: 18728 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,550.00	11,521.08	15,028.92	56.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,472.00	1,972.00	2,500.00	55.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,022.00	13,493.08	17,528.92	56.50
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	30,622.00	13,093.08	17,528.92	57.24
+ GST 7.00/7.00% (\$\$)	2,143.54	916.52	1,227.02	57.24
Nett Amount (\$\$)	32,765.54	14,009.60	18,755.94	57.24

INSPECTION

Date of Assignment: 26/03/2018
Date Inspected: 23/03/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,915.00 FS	*2,204.00 FS
2	1		*FRONT BUMPER SPOILER	Repair	817.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	3,101.00 FS	*2,480.80 FS
4	1		*FRONT RADIATOR GRILLE	Not Necessary	32.00 FS	*- FS
5	1		*LECECE PLATE HOLDER	Not Necessary	1,074.00 FS	*- FS
6	2		*FRONT PARKING AIR SENSOR	Not Necessary	392.00 FS	*- FS
7	1		*FOAM FILLER PIECE	Not Necessary	203.00 FS	*- FS
8	1		*FRONT SIDE REINFORCEMENT	Not Necessary	702.00 FS	*- FS
9	1		*FRONT BUMPER COVER	Deformed	105.00 FS	*84.00 FS
10	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
11	1		*HEADLIGHT -LH/RH	N/S Cracked	16,772.00 FS	*6,708.80 FS
12	1		*FRONT NO.PLATE	Necessary	25.00 FS	*25.00 FS
13	1		*SUNDRIES	Necessary	400.00 FS	*9.20 FS
Total Parts (S\$)					26,550.00	11,521.08

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY AND BOTH HEADLIGHTS .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .INSPECT BONNET FOR DAMAGES .REINSTALL ALL PARTS REMOVED	New	2,100.00	750.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,700.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,472.00	1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >