

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
ECICS LTD				CS3/ICS18005612/Sc	d3e2	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987				24-05-2018		
			Code:	ICS		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SLF 8109U	Veh. Inspected		SGC 9067A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	DMPU1800037H	Excess (\$)		0.00	
	Assign From	JANICE GOH	Assign Date		26/03/2018	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	ZNE100285454	Colour		SILVER	
	Odometer	188667 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55Z R16	MICHEI	LIN	6 mm	
	L/H Front Tyre	205/55Z R16	MICHELIN		6 mm	
	R/H Rear Tyre	205/55Z R16	MICHELIN		6 mm	
	L/H Rear Tyre	205/55Z R16	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	23/03/2018	Inspec	t Date / Time	29/03/2018 ( 11:18 AM )	
	Survey held at	KENT SENG VEHICLE REPAIRER				
		BLOCK 1016, YISHUN IND. PARK A #01-238 SINGAPORE 768758				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					

Report Ref No. CS3/ICS18005612/Sd3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

YEANG WAI KEEN

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons), B. Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.