

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 02.04.2018
 VEH NO : SJT8567E
 MODEL : Nissan Latio
 D O A : 20.03.2018
 YR REF : SCU5544T

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJT8567E (NISSAN LATIO)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>deland</i>	1193 1	436.00 ✓
2	Front Bumper Side Holder - LH <i>m</i>	835.10 1	35.20 ✓
3	Front Fender - LH <i>deland</i>	1	623.20 ✓
4	Front Fender Inner Shield - LH <i>deland</i>	1	98.60 ✓
			1,193.00
	Less 30%		(357.90)
			\$ 835.10

NETT ITEMS

1	Front Bumper Clips <i>new</i>	1 set	\$ 30.00 ✓
2	Headlamp - LH <i>cracked</i>	1	\$ 344.30 ✓
3	Front Fender Signal Lamp - LH <i>ut</i>	1	\$ 53.10 ✓
4	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	\$ 30.00 ✓
5	Front Knuckle Arm - LH	1	\$ 376.80 ✗
6	Front Wheel Hub c/w Bearing - LH	1	\$ 221.60 ✗
7	Front Shock Absorber - LH	1	\$ 347.60 ✗
8	Front Lower Arm - LH	1	\$ 216.80 ✗
9	Rocker Panel Outer Side Skirt	1	\$ 373.20 ✗
10	Rocker Panel Outer Side Skirt Clips <i>new</i>	1 set	\$ 30.00 ✗
			2,023.40
	Less 10%		(202.34)
			\$ 1,821.06

S/NET ITEMS

1	Front Wheel Rim - LH <i>ut</i>	1	\$ 680.00 400
2	Front Tyre - LH <i>new</i>	1	\$ 280.00 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SJT8567E (NISSAN LATIO)

Total Parts		\$	3,616.16
<u>LABOUR CHARGE</u>			
1	To knocking & pull out front portion & renew above parts	\$	600.00 400
2	To putty & spray up paint works	\$	600.00 400
3	To check wiring	\$	50.00 30
4	To underseal	\$	100.00 X
5	To remove front undercarriage	\$	350.00 X
6	To perform wheel alignment	\$	150.00 80
Total Labour		\$	1,850.00
Grand Total		\$	5,466.16

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2556.76.
A/s: 2050.
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: