

2/03/2010

ASS. REC. BY:

REF: CS/FCI18005682/ Uvd3n2 Special Instruction:

Surveyor

Marius

ASSIGNMENT (Office)

CWS

From (Person): Karen Tan

of FCI

Date/Time: 27/3/18 @ 3:34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 7518C

Insured:

SHD 3666T

at Workshop m/s

Progressive Automotive

Tel:

G741 5336

of BLK 3022 A, Ubi Rd 1 #01-45/46

Policy No:

Claim No:

D18002403MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'ds'

25.04.2018 @ Morning

H.O.D. Endorsement:

Date/Time:

3:58pm @ 27/3/18

Person Contacted:

S00

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH 7518C - X

SHD 3666T - CS/FCI17015523/Kqbn2

D.O.A: 08/8/17

6/4/18

Email preli revised to FCI

REF: FCI

ASSIGNMENT

From: Date: 25/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 7518C
at Workshop m/s: Progression
of: Blk 302A Ubi Rd 1 #01-45

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 27k.

IAC Accident Report: Consistent? : Yes or No

G/A / PR Seen: 26 Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 2W % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS' DS: 20/6/2024
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMH 7518C Yr Regn: 6 / 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or C41

Make: Toyota picnic CC 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 235-724 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTEGH23B600021902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Champion

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/3/18 D.O.I. 25/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body.
The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction LTA 15295 3yrs 3mths.
Dep B500 net 11705

9/5/18 confirmed n/s & 4900 with Ray (Red 4675.30, 4990)

Note: mv: \$27K (Est) LTA: \$15,295 NV: \$11,705

RECEIVED 09 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 9/5- typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)☐ : S + RS \$☐ : Photos☐ : Others

TOTAL

Report Format: CWS

Lump Sum / I.B.I: (\$ 4900/2)

170

50

50

54

324



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002403MFSH

Our ref: CS/FCI18005682/Uvd3

DATE: 26/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SGH 7518C


We thank for your instruction on 27/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 25/4/2018 at the premises of M/s PROGRESSIVE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$9,575.30
Revised Estimate Amount	: S\$6,148.78
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-03-2018	Our Ref No. D18002403MFSH
Accident Date	14-03-2018	Claim Type. Third Party
Insured Vehicle	SHD3666T	Third Party Vehicle. SGH7518C
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	SOO	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236310)



PRI Documents



Close



PRI Header Details

Claim No	D18002403MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PROGRES
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : SOO)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-45/46 Mobile: 0 , Phone: 67415336 , Fax: 67417208 EmailId: LKSOO@PROGAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3666T	TP Vehicle No	SGH7518C
PRI Recieved Date	26-03-2018 04:49:44 PM	Surveyor Appointed Date	27-03-2018 03:32:52 PM	Surveyor Accept Date	27-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 April 2018 9:41 AM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002403MFSH/1, SGH 7518C
Attachments: SGH 7518C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGH 7518C
Date of survey: 25/4/2018
Number of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 March 2018 4:01 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002403MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 March 2018 3:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002403MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing.
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

14 vehicles

Toyota Picnic

Advanced Search

Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota Picnic		Any	Any	> 10 year(s) old	Any	Any	Any	Available



Toyota Picnic 2.0A (COE till
07/2021)

\$30,800

\$9,460 /yr

28-Jul-2006

1,998 cc

210,000 km

MPV

Available

Well Maintained. One Of The Most Spacious MPV In The Market. Sheltered Parking. No Repaired Needed. Consignment Unit. Viewing By Appointment Only.

Posted: 24-Apr-2018 Tags: 2006 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A (COE till
04/2023)

\$40,800

\$8,170 /yr

23-Apr-2008

1,998 cc

-

MPV

Available

\$2800 Down Payment, Lowest Monthly From \$788 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty/Service By GV In House Workshop. New Full Pure Leather...

GV Credit Pte Ltd

Posted: 23-Apr-2018 Tags: 2008 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A (COE till
02/2022)

\$35,800

\$9,430 /yr

09-Feb-2007

1,998 cc

132,000 km

MPV

Available

Drive Away From \$5000 Onwards, \$785 Low Monthly Installment Bank In House Loan Available "One Year In-House Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Pal...

Carway

Posted: 22-Apr-2018 Tags: 2007 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A (COE till
03/2023)

\$40,800

\$8,300 /yr

26-Mar-2008

1,998 cc

60,000 km

MPV

Available

Graded B by **STP**

\$2800 Down Payment, Lowest Monthly From \$788 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty/Service By GV In House Workshop. New Full Pure Leather...

GV Credit Pte Ltd

Posted: 21-Apr-2018 Tags: 2008 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Toyota Picnic 2.0A (COE till
08/2027)

\$61,800

\$6,620 /yr

22-Aug-2007

1,998 cc

153,000 km

MPV

Available

Trade In Most Welcome! Bank/In House Loan Available! Don't Miss It, View To Believe!

Posted: 20-Apr-2018 Tags: 2007 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota



Toyota Picnic 2.0A (COE till
03/2025)

\$57,500

\$8,320 /yr

23-Mar-2005

1,998 cc

102,000 km

MPV

Available

Low Depreciation. Very Good Condition.

Posted: 11-Apr-2018 Tags: 2005 Toyota Picnic, Toyota Picnic, Toyota, Picnic, Used Toyota

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2952J
Vehicle Details	
Vehicle No.:	SGH7518C
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1AZ5415277
Chassis No.:	JTEGH23B600021902
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$26,212.00
Original Registration Date:	21 Jun 2006
First Registration Date:	21 Jun 2006
Transfer Count:	3
Actual ARF Paid:	\$28,834.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$15,295.00
Total Rebate Amount:	\$15,295.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Apr 2018

OK

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

To be shld after exp

1/59 Not authorised Lhr
6 Days 25/4/18 nocent.

M/S : HALIZAH BINTE KASSIM
BLK 109 HOUGANG AVENUE 1 #03-1000
SINGAPORE 530109

Estimate No: EST1503450
Date: 22 Mar 2018
Policy No: GA041929/1
Veh Reg No: SGH7518C
Make/Model: TOYOTA PICNIC AUTO
Chassis No: JTEGH23B600021902
Engine No: 1AZ5415277
Reg. Date: 21/06/2006

ATTN:
Your Ref No: TP 0318-4999
Claim Type: Third Party
Accident Date: 14/03/2018
TP Veh Reg No: SHD3666T

Estimate Repair Cost to Vehicle No :SGH7518C

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>Repcut</i>	498.6000	1 PC <i>deep cut</i>	498.60	✓
2 REAR BUMPER SIDE HOLDER - LH	60.8000	1 PCS <i>cut</i>	60.80	✓
3 REAR BUMPER SIDE HOLDER - RH	60.8000	1 PCS <i>nn</i>	60.80	X
4 REAR BUMPER CLIPS <i>GO</i>	9.8000	10 PC <i>ner</i>	98.00	✓
5 ROCKER PANEL - LH	410.5000	1 PC <i>badly d/d</i>	410.50	✓
6 REAR FENDER - LH	1,080.500	1 PC <i>R</i>	1,080.50	X
7 REAR WINDSCREEN MOULDING	149.7000	1 PCS <i>11</i>	149.70	X
8 REAR FENDER GLASS MOULDING - LH	360.5000	1 PCS <i>11</i>	360.50	X
9 REAR DOOR - LH	1,190.500	1 PC <i>sent</i>	1,190.50	✓
10 REAR DOOR STRIKER - LH	150.5000	1 PC <i>nn</i>	150.50	X
11 REAR DOOR RUBBER - LH	380.6000	1 PC <i>ner</i>	380.60	✓
12 REAR DOOR OUTER CHANNEL MOULDING - LH	129.7000	1 PCS <i>11</i>	129.70	X
13 REAR DOOR PROTECTOR - LH	185.6000	1 PC <i>ner</i>	185.60	✓
14 FRONT DOOR - LH	1,120.500	1 PC <i>Badly d/d</i>	1,120.50	✓ <i>1120.50</i>
15 FRONT DOOR STRIKER - LH	150.5000	1 PC <i>11</i>	150.50	X
16 FRONT DOOR RUBBER - LH	160.8000	1 PC <i>ner</i>	160.80	✓
17 FRONT DOOR OUTER CHANNEL MOULDING - LH	129.7000	1 PCS <i>11</i>	129.70	X
18 REAR DOOR PROTECTOR - LH	170.5000	1 PC <i>ner</i>	170.50	✓
19 FRONT FENDER VVTI WORDING - LH	96.8000	1 PCS <i>11</i>	96.80	X
20 REAR TYRE RIM - LH <i>cut</i>	855.3000	1 PCS <i>cut</i>	855.30	✓ <i>5093.7</i>
			7,440.40	
		Less 25%	1,860.10	5,580.30
Special Net				
21 REAR BUMPER SENSOR	330.0000	1 SET	330.00	X <i>Src</i>
			330.00	330.00
Labour				
22 TO KNOCK OUT DENTS,CUT/ WELD, LHR FENDER, LH ROCKER PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,200.000	1 JOB <i>\$900</i>	1,200.00	✓ <i>900</i>
23 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,500.000	1 JOB <i>\$1000</i>	1,500.00	✓ <i>1000</i>
24 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
25 TO REMOVE, TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB <i>\$50</i>	100.00	✓
26 TO TRANSFER 2 DOOR AND DOOR FITTING	160.0000	1 JOB <i>\$120</i>	160.00	✓
27 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB <i>\$80</i>	100.00	✓
28 TO TUFF-KOTE	100.0000	1 JOB <i>\$90</i>	100.00	✓
29 TO REMOVE, REPLACE LHR TYRE RIM & BALANCING	45.0000	1 JOB	45.00	X
30 TO REMOVE, REFIT LHR FENDER GLASS	60.0000	1 JOB	60.00	X
31 TO REMOVE, REFIT PETROL TANK	80.0000	1 JOB <i>\$60</i>	80.00	X

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : HALIZAH BINTE KASSIM
BLK 109 HOUGANG AVENUE 1 #03-1000
SINGAPORE 530109

Estimate No: EST1503450
Date: 22 Mar 2018
Policy No: GA041929/1
Veh Reg No: SGH7518C
Make/Model: TOYOTA PICNIC AUTO
Chassis No: JTEGH23B600021902
Engine No: 1AZ5415277
Reg. Date: 21/06/2006

ATTN:
Your Ref No: TP 0318-4999
Claim Type: Third Party
Accident Date: 14/03/2018
TP Veh Reg No: SHD3666T

Estimate Repair Cost to Vehicle No :SGH7518C

Description	U/Price	Quantity	Price	Amount
32 TO REMOVE, REFIT REAR UNDERCARRIAGE	300.0000	1 JOB	300.00 ^{SS} 3,665.00	300.00 ^{SS} 3,665.00
Total				SS 9,575.30
Add GST @ 7%				670.27
Total Amount Payable				SS 10,245.57

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED FORTY FIVE AND CENTS FIFTY SEVEN ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005682/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3666T	Veh. Inspected	SGH 7518C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002403MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PICNIC (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JTEGH23B600021902	Colour	SILVER	
Odometer	235724	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	CHAMPIRO	6 mm	
L/H Front Tyre	215/65 R16	CHAMPIRO	6 mm	
R/H Rear Tyre	215/65 R16	CHAMPIRO	6 mm	
L/H Rear Tyre	215/65 R16	CHAMPIRO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2018	Inspection Date	25/04/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 7518C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEEP CUT	498.60	498.60
1	REAR BUMPER SIDE HOLDER-LH	BENT	60.80	60.80
1	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	60.80	-
10	REAR BUMPER CLIPS @\$9.80	NECESSARY	98.00	60.00
1	ROCKER PANEL-LH	BADLY DENTED	410.50	410.50
1	REAR FENDER-LH	TO REPAIR SEE LABOUR	1,080.50	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	149.70	-
1	REAR FENDER GLASS MOULDING-LH	NOT NECESSARY	360.50	-
1	REAR DOOR-LH	DENTED / BENT	1,190.50	1,190.50
1	REAR DOOR STRIKER-LH	NOT NECESSARY	150.50	-
1	REAR DOOR RUBBER-LH	NECESSARY	380.60	380.60
1	REAR DOOR OUTER CHANNEL MOULDING-LH	NOT NECESSARY	129.70	-
1	REAR DOOR PROTECTOR-LH	BENT	185.60	185.60
1	FRONT DOOR-LH	BADLY DENTED	1,120.50	1,120.50
1	FRONT DOOR STRIKER-LH	NOT NECESSARY	150.50	-
1	FRONT DOOR RUBBER-LH	NECESSARY	160.80	160.80
1	FRONT DOOR OUTER CHANNEL MOULDING-LH	NOT NECESSARY	129.70	-
1	REAR DOOR PROTECTOR-LH	NECESSARY	170.50	170.50
1	FRONT FENDER VVTI WORDING-LH	NOT NECESSARY	96.80	-
1	REAR TYRE RIM-LH	CUT	855.30	855.30
	LESS 25% DISCOUNT		-1,860.10	-1,273.43
			5,580.30	3,820.27
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	330.00	-
			330.00	-
LABOUR				
	TO KNOCK OUT DENTS.CUT/WELD,LHR FENDER,LH ROCKER PANEL.REMOVE.REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER- LH.		1,200.00	900.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,500.00	1,000.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE,TRANSFER REAR BUMPER SENSOR.		100.00	50.00
	TO TRANSFER 2 DOOR AND DOOR FITTING.		160.00	120.00
	TO 4 WHEEL ALIGNMENT.		100.00	80.00
	TO TUFF-KOTE.		100.00	90.00
	TO REMOVE,REPLACE LHR TYRE RIM & BALANCING.	NOT NECESSARY	45.00	-
	TO REMOVE,REFIT LHR FENDER GLASS.	NOT NECESSARY	60.00	-
	TO REMOVE,REFIT PETROL TANK.		80.00	60.00
	TO REMOVE,REFIT REAR UNDERCARRIAGE.	NOT NECESSARY	300.00	-
			3,665.00	2,320.00
GRAND TOTAL			9,575.30	6,140.27

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00
---	--	--	----------

Report Ref No. CS/FCI18005682/Uvd3n2

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,295.00=NETT VALUE: \$11,705.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.