



UNI AUTOMOTIVE PTE LTD

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

EMAIL: unimotorco@singnet.com.sg

Registration No.: 200920121W

LKK

TPALG.

Vivian

DATE: 03/04/2018

REF: UAPL1099

REPAIR ESTIMATE TO THE KIA FORTE NO: SLW3251J

1 FRONT L/H DOOR PILLAR <i>Bye</i>	\$ 1,319.00 X
1 FRONT L/H DOOR ASSY <i>Distorted</i>	\$ 981.00 ✓
2 FRONT L/H DOOR HINGES <i>Not me</i>	\$ 116.00 X
1 FRONT L/H DOOR LOCK <i>Not me</i>	\$ 312.00 X
1 FRONT L/H DOOR GUARD GARNISH <i>Deformed</i>	\$ 48.00 ✓
1 FRONT L/H DOOR WEATHERSTRIP <i>Not me</i>	\$ 176.00 X
1 FRONT L/H DOOR REGULATOR <i>Not me</i>	\$ 382.00 ✓
1 FRONT L/H DOOR REGULATOR MOTOR <i>Not me</i>	\$ 412.00 X
1 FRONT L/H DOOR INNER TRIM BOARD <i>cracked</i>	\$ 613.00 ✓
1 FRONT L/H DOOR TOP BLACK STICKER <i>Not me</i>	\$ 40.00 ✓
1 FRONT L/H DOOR CENTRE BLACK STICKER <i>Not me</i>	\$ 40.00 ✓
1 FRONT L/H FENDER ASSY <i>Deformed</i>	\$ 411.00 ✓
1 FRONT L/H FENDER INNER SHIELD <i>Deformed</i>	\$ 115.00 ✓
6 FRONT L/H FENDER INNER SHIELD CLIPS <i>Not me</i>	\$ 30.00 ✓
1 FRONT L/H FENDER LAMP <i>Not me</i>	\$ 38.00 X
1 FRONT L/H SPORT RIM <i>Not me</i>	\$ 1,044.00 <i>500 (SW)</i>
1 FRONT L/H SHOCK ABSORBER <i>Not me</i>	\$ 387.00 ✓
1 FRONT L/H SHOCK ABSORBER BASE <i>Not me</i>	\$ 108.00 X
1 FRONT L/H LOWER ARM <i>Not me</i>	\$ 398.00 ✓
1 FRONT L/H KNUCKLE ARM <i>Not me</i>	\$ 552.00 ✓
1 FRONT L/H KNUCKLE BEARING <i>Not me</i>	\$ 187.00 ✓
1 FRONT L/H LINKAGE <i>Not me</i>	\$ 96.00 X
	\$ 7,805.00
LESS 10%.....	\$ 780.50
	\$ 7,024.50

LABOUR CHARGES:-

TO DISM/RENEW FRONT UNDERCARRIER	\$ 400.00 <i>220</i>
TO SPRAY UNDERCOATING IN REPAIR	\$ 100.00 X
TO DISM/REWIRE DAMAGED PORTION	\$ 80.00 <i>30</i>
TO RENEW DOOR BLACK STICKER	\$ 40.00 X
TO COMPLETE WHEEL ALIGNMENT	\$ 120.00 <i>80</i>
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$ 1,000.00 <i>500</i>
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 1,200.00 <i>600</i>
	\$ 9,964.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5695.60

A/S: 4.51C

05 Days