



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631-1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQ11	Mdm Salomah Binte Osman 253 Compassvale Street #10-27 Singapore 540253 Mobile: 96507064
	Document No 0	
	Document Date 01/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	23/02/2017	SLL3904S	12545	15971 :7DS/SLL3904S/30011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104556013	1ZRY324671	30	Sam San Joi	31/01/2018	15.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBD1657D ACC DATE:30/01/2018 DRIVE IN:31/01/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				154.00
3	S	BP-SUBLET CHECK WIRING & CONDUCT WATER LEAK TEST				154.00
4	S	BP-SUBLET REMOVE & INSTALL BOOTLID COMPARTMENT, CAR PET, GARNIS AND TRIMMING TO ASSIST REPAIR				308.00
5	S	BP-SUBLET REPLACE REAR BUMPER, BOOTLID GARNISH, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				3080.00
6	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				2530.00
7	1	S52159-02904 COVER, RR BUMPER	1.00	539.90		539.90
8	2	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		58.30
9	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		105.70
10	4	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30		58.30
11	5	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70		105.70
12	6	S52023-02190 REINFORCEMENT, RR	1.00	386.60		386.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607067

3607067

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 01/02/2018
TIME 09:37

VEHICLE NO SLL3904S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**Borneo Motors (Singapore) Pte Ltd**

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Mdm Salomah Binte Osman 253 Compassvale Street #10-27 Singapore 540253 Mobile: 96507064
	Document No	
	Document Date	
	0	
	01/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	23/02/2017	SLL3904S	12545	15971 :7DS/SLL3904S/30011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104556013	1ZRY324671	30	Sam San Joi	31/01/2018 15.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	7	S52182-02160	1.00	66.20		66.20
14	8	S52181-02190	1.00	66.20		66.20
15	9	S52161-0K040	10.00	3.90		39.00
16	0	S58307-02380	1.00	649.20		649.20
17	1	S76801-02E30	1.00	236.10		236.10
18	2	S75431-02090	1.00	59.70		59.70
19	3	S75442-02330	1.00	39.70		39.70
20	4	S75442-02340	1.00	44.10		44.10
21	5	SP2061-12021 76	1.00	159.75		159.75
		ARM, RR BUMPER, OUTE				
		ARM, RR BUMPER, OUTE				
		CLIPS				
		PANEL, LAMP LOWER				
		GARNISH SUB-ASSY				
		LUGGAGE COMP EMBLEM,				
		EMBLEM, SYMBOL				
		EMBLEM, SYMBOL				
		BACK SENSOR 1F9 310A				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	8,870.45
		Labour	2,614.45
		Materials	30.00
		Lubrication/Fluid	6,226.00
		Others	0.00
		0.00	GST 7.00%
			Less
			0.00
			Amount Due
			9,491.38

PLEASE TEAR ALONG PERFORATED LINE

3607068

3607068

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 01/02/2018
TIME 09:37

VEHICLE NO SLL3904S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**