

REPAIR ESTIMATE*

MAKE :

DATE 26/3/2018 17:04

DOA: 26.03.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Rep			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips X			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ?			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Rubber Mat /			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 250.00 200
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 50.00 X
	R/Refix Reverse Sensor			\$ 120.00 X
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,381.58
	Larry Ng 1/Cal-2 10/11/14 27/3/18 10 & 1/2 PIP After Repair p4			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before after spray painting • To display damaged parts for inspection • Parts prices are subject to final approval • Third party survey is on a "no dispute" basis • No illegal modifications • Supplementary items must be provided and is subject to final approval by LKK Auto Consultants Company			
	Acknowledged by Repairer Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			