

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 16 Apr 2018)**Parts:** 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/GBG8402K/16/04/2018 12:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*COVER RR BRACKET TOP RH 7.5	0.00	0.00	*40.00 F
2	1		*RETAINER RR BUMPER TOP RH 6.25	0.00	0.00	*15.00 F

F=Franchise part.

Total Parts (S\$)	55.00
-------------------	-------

Jin Auto Services Pte Ltd/GBG8402K/16/04/2018 12:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS