

COMFORTDELGRO ENGINEERING PTE LTD

AIG

REPAIR ESTIMATE\*

DATE 3/24/2018 10:04

VEHICLE NO : SHA 7720J

MAKE :

DOA: 23.03.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH)			\$ 980.50
	Front Wheel Hub Cap (RH)			\$ 150.70
	<b>SUB TOTAL</b>			<b>\$ 1,131.20</b>
	<b>LESS 20%</b>			<b>\$ 226.24</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 904.96</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>250.00</del> 200
	Spray Painting Charge (Mirror/Fender/Bumper)			\$ <del>600.00</del> 440
	Tuff Kote			\$ <del>50.00</del> 30
	FRT Wheel Alignment			\$ <del>80.00</del> 60
	<b>TOTAL LABOUR</b>			<b>\$ 980.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,884.96</b>

R  
SA

200  
440  
30  
60

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
Hj 20012018  
4 days  
P/P  
26/03/18 @ 1210  
Reg by part

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.