

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

Not Authorized
Mark
2/585600/2
Take photo After Repo
28/3/18
Gdy

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 539216
 Officer in Charge : WEE TZE FAH
 Tel :
 Email :

Customer :
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
 Attn :
 Tel :
 Fax :

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	<i>20/suc</i> 1	1,662.4000	1,662.40
2	BOOTLID LOCK	<i>1m</i> 1	90.4000	90.40
3	BOOTLID LOCK STRIKER	<i>11</i> 1	18.5000	18.50
4	BOOTLID WEATHERSTRIP	<i>1m</i> 1	188.8000	188.80
5	BOOTLID CENTRE LOGO BADGE	<i>rec</i> 1	59.8000	59.80
6	BOOTLID E BADGE	<i>rec</i> 1	34.4000	34.40
7	BOOTLID VIOS BADGE	<i>rec</i> 1	44.1000	44.10
8	BOOTLID OUTER GARNISH	<i>11</i> 1	234.3000	234.30
9	BOOTLID INNER TRIM	<i>11</i> 1	234.3000	234.30
10	BOOTLID INNER TRIM CLIPS	<i>11</i> 5	4.5000	22.50
11	BOOTLID HINGE	<i>11</i> 2	57.8000	115.60
12	BOOTLID LOCK CABLE CLIPS	<i>11</i> 3	4.5000	13.50
13	REAR END PANEL	<i>Sel/gid</i> 1	694.7000	694.70
14	REAR END PANEL INNER TRIM	<i>1m</i> 1	234.3000	234.30
15	REAR LICENSE PLATE LAMP	<i>11</i> 2	64.1000	128.20
16	REAR LUGGAGE FLOOR FOAM	<i>11</i> 1	108.2000	108.20
17	REAR BUMPER	<i>Dis</i> 1	502.1000	502.10
18	REAR BUMPER REINFORCEMENT	<i>Dis</i> 1	379.2000	379.20
19	REAR BUMPER REFLECTOR	<i>11</i> 2	130.8000	261.60
20	REAR BUMPER SIDE RETAINER	<i>1m</i> 2	115.1000	230.20
21	REAR BUMPER SIDE HOLDER	<i>1m</i> 2	42.0000	84.00
22	REAR BUMPER CLIPS	<i>rec</i> 10	4.5000	45.00
23	REAR BUMPER END SPLASHIELD COVER	<i>11</i> 2	57.5000	115.00

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LAMP	2 <i>CM</i>	375.8000	751.60 <i>✓</i>
25	REAR LAMP CLIP HOLDER	4 <i>nn</i>	4.3000	17.20 <i>X</i>
26	REAR LAMP PANEL	2 <i>nk34</i>	124.0000	248.00 <i>nc</i>
27	REAR FENDER <i>als</i>	20/1 <i>Ref</i>	969.1000	969.10 <i>✓</i>
28	REAR FENDER INNER TRIM	<i>Ref to 1</i>	235.0000	235.00 <i>✓</i>
29	REAR FENDER INNER TRIM CLIPS	8 <i>nn</i>	4.3000	34.40 <i>X</i>
30	REAR EXHAUST BOX	1 <i>1</i>	638.8000	638.80 <i>X</i>
31	REAR EXHAUST BOX MOUNT	1 <i>1-1</i>	33.0000	33.00 <i>X</i>
32	REAR EXHAUST BOX HEAT SHIELD	1 <i>11</i>	59.9000	59.90 <i>X</i>
33	LESS 20% (ITEM 1 - 32) <i>25%</i>	1	-1,697.6200	-1,697.62
34	REAR LICENSE PLATE	1 <i>Ref</i>	80.0000	80.00 <i>40</i>
35	REAR LUGGAGE FLOOR PANEL INSULATOR	1 <i>11</i>	250.0000	250.00 <i>X</i>
36	REAR WINDSHIELD GLASS SEALANT	1 <i>nn</i>	200.0000	200.00 <i>40</i>
37	REAR WINDSHIELD GLASS SPONGE	1 <i>nn</i>	100.0000	100.00 <i>30</i>
38	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00 <i>20</i>
39	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 <i>50</i>
40	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00 <i>90</i>
41	TO TRANSFER BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	120.00 <i>60</i>
42	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	160.0000	160.00 <i>80</i>
43	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00 <i>120</i>
44	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	1	150.0000	150.00 <i>11 X</i>

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
45	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	2,000.0000	1400 2,000.00
46	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000	1100 1,600.00

7101.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	11,990.48
GST(7.00%)	839.33
Total (SGD)	12,829.81

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216