

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 46422**
Date Estimated : **28/03/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : **1 of 2**

- ESTIMATE REPAIR FOR -

Anurag Nema
130 Tanjong Rhu Road
#02-15

Singapore 436918

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP4928H	LL18567	25/01/2013	X3 xDrive28i	0

DESCRIPTION

To replace rear bumper upp, bumper ctr trim , bumper lower
and all attachments cause by accident.

VALUE
1275 ~~2,550.00~~

Painting on rear bumper assembly & tail gate

1805 ~~2,006.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~177.00~~

Sundries.

40 ~~80.00~~

Total Labour 1: **4,813.00**

DESCRIPTION

CLAMP
SET TRIM TOWING LUG
Set of mount
RR BUMPER CARRIER ECE
COVERING BOTTOM REAR
COVER TRIM REAR BLACK (PDC)
RR BUMPER (PRIMED)
MODEL LETTERING X3
COVER BUMPER REAR (X-LINE)
COVER BUMPER REAR (X-LINE)
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
5	1.60	8.00
1	69.70	69.70
1	35.10	35.10
1	738.05	738.05
1	79.80	79.80
1	197.35	197.35
1	1,342.35	1,342.35
1	62.55	62.55
1	63.40	63.40
1	63.40	63.40
4	5.05	20.20

Total Parts : **2,679.90**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46422
Date Estimated : 28/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP4928H	LL18567	25/01/2013	X3 xDrive28i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>08/05/18 @ 1135</u>	Excess S\$ _____
Surveyor's Name <u>P. R. M.</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>4 days</u>	

Labour 1	:	4,813.00
Parts	:	2,679.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	524.50
Grand Total	:	8,017.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **