

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3411L

DATE 27/3/2018 16:51

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (RH) <i>X repair</i>			\$ 2,020.10	
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 164.40	
	Rear Windscreen Moulding <i>X</i>			\$ 60.00	
	<i>Para Repair - Replaced</i>				
	SUB TOTAL		<i>\$603.60</i>	\$ 2,244.50	
	LESS 20%			\$ 448.90	
	DISCOUNTED TOTAL			\$ 1,795.60	
	Rear Bumper Advertisement Logo <i>— ne</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (RH) <i>— ne</i>			\$ 100.00	Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00	Nett
	Rear Door Advertisement Logo (RH) <i>— ne</i>			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>— ne</i>			\$ 80.00	Nett
	<i>Rear Bumper Protector Mat - \$50 ne</i>			\$ 376.00	
	Labour Charge				
	Panel Beating			\$ 500.00	<i>300</i>
	Spray Painting Charge			\$ 500.00	<i>400</i>
	Tuff Kote			\$ 50.00	<i>X</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00	<i>20</i>
	TOTAL LABOUR			\$ 1,440.00	
	<i>Ka Li' Nam</i>				
	ESTIMATE TOTAL			\$ 3,611.60	
	<i>V 28/3/18 11:15h</i> <i>3 Bys</i> <i>P/K</i> <i>Before Part pht</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company This is an initial estimate based on a visual inspection of the damaged vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Signature: _____ Date: _____				