COMFORTDELGRO ENGINEERING PTE LTD

CHINA-LKK

REPAIR ESTIMATE*

VEHICLE NO: SH 7204R

DATE 26/3/2018 11:41

Jumani

MAKE

MODEL . HVINDALSONAT

Qty	Parts Description/ Labour		Unit Price	Amount		
	Rear Bumper		111	\$	578.40	DE
	Rear Bumper Protector (RH)		a beside in	\$	38.00	20
						-
	SUB TOTAL			\$	616.40	
	LESS 20%			\$	123.28	-
	DISCOUNTED TOTAL		H HH	\$	493.12	
	Rear Bumper Advertisement Logo			\$	50.00	
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$	200.00	Ne
				\$	250.00	
	Labour Charge		-1.12: 1011.6		250	
	Panel Beating		P - 27 - 11 - 10	\$	250.00 250.00	11
	Spray Painting Charge			\$		1
	Wiring Charge			\$	50.00	X
	Remove/Refix Reverse Sensor			\$	120.00	6
	TOTAL LABOUR		Kasul 40 900 10063	\$	670.00	1
	TOTAL LABOUR		11.00	, ,	070.00	1
	ESTIMATE TOTAL		H) 10010003	S	1,413.12	1
			1		2,120122	1
			2 days			
	LKK Auto Consultants hence notify		1/3			
	the Repairer of the following:		26/03/18@ 3 alturny			
	To resurvey before/after spray painting To display damaged part(s) during resurvey		21/2/20	140	FX	
	Parts prices are subject to confirmation		26/03/18	. (()	
	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed.		U			
	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and	0	Chi ne	w		
	is subject to final approval from Insurance Company	No	el aria			
	Acknowledged by Repairer		9			
	Signature:					
	Date:					
	This is an initial estimate based on a visual inspection of the	above ve	chicle. The final repair	uantu	m will	1