

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
 Defu Industrial Park C, Singapore 539186  
 Tel : 6343-0934 Fax : 6343-0921  
 Email : jmartauto@gmail.com  
 Registration No: 201400246D  
 GST Reg. No: 201400246D

27-Mar-18

Our ref : TP/4433/18

TPALG Xiao Tang.

Lalitha D/O Krishnan

RE : estimate cost for vehicle no : SKE 2742B

1 pc	frt bumper	Repair	\$	662.00	x.
1 pc	rear bumper	Rehnd		701.00	✓
4 pcs	rear bumper reverse sensor	found 1 piece.		904.00	<del>74</del> 226
2 pcs	rear bumper retainer	on RH		44.00	<del>22</del>
1 pc	rear bumper sponge	reduced		120.00	✓
1 pc	rear bumper reinforcement	reduced		395.00	✓
10 pcs	rear bumper clips	on	1788	30.00	✓
1 pc	end panel	240	1609.20	482.00	x.
1 pc	rh taillamp	reduced.		294.00	✓
1 pc	Kia emblem	found		53.00	x
1 pc	Cerato emblem			26.00	x
				<u>3,711.00</u>	
less 10%				371.10	
				<u>3,339.90</u>	
1 pc	CC emblem	on		40.00	snett x.
1 pc	frt bumper lower spoiler	Rehnd		1,500.00	750. 1500
1 pc	rear bumper lower spoiler	reduced		1,500.00	750
Panel beating.				1,200.00	400 1430
Spray painting.				1,600.00	1000
Wiring.				30.00	✓
				<u>9,209.90</u>	
Plus 7% GST				644.69	
				<u>9854.59</u>	

SD : Nine thousand eight hundred fifty-four & cents fifty-nine only.

Adrian Lj  
 28/03/18.  
 1/3 04 by.  
 total: 4539.2  
 1/3: 3.6K.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: