



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

not added
Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn : *Confirmp*
Tel :
Fax :
on 29/03/18
29/3/18
P/P 2004.17
3 day
before job

Quotation No : QO18/03-1298	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7812B	Chassis No : MHFB29F3802011992	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLM8396U, DATE OF ACCIDENT: 27.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	REAR BUMPER	1	504.9000	504.90	✓
2	REAR BUMPER REINFORCEMENT	1	135.0000	135.00	✓
3	REAR BUMPER SIDE RETAINER	2	50.0000	100.00	✓
4	REAR BUMPER SIDE HOLDER	2	22.3000	44.60	✓
5	REAR BUMPER CLIPS	8	4.3000	34.40	✓
6	REAR BUMPER REFLECTOR	2	130.5000	261.00	X
7	REAR END PANEL	1	694.7000	694.70	X
8	REAR END PANEL INNER TRIM	1	234.3000	234.30	X
9	REAR LAMP	2	375.8000	751.60	X
10	REAR LAMP CLIP HOLDER	4	9.5000	38.00	X
11	BOOTLID E BADGE	1	39.4000	39.40	X
12	BOOTLID VIOS BADGE	1	44.1000	44.10	X
13	BOOTLID CENTRE LOGO BADGE	1	59.8000	59.80	X
14	REAR EXHAUST BOX	1	638.8000	638.80	X
15	REAR EXHAUST BOX HEAT SHIELD	1	46.6000	46.60	X
16	REAR EXHAUST MOUNT	1	78.9000	78.90	X
17	LESS 25% (ITEMS 1-16)	1	-926.5300	-926.53	
18	REAR BUMPER PARKING SENSOR	2/scr	450.0000	900.00	200
19	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	900.0000	900.00	480
20	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	800.0000	800.00	580
21	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00	50

*01890
614.92
2004.17*

C/F 0.00

*819.90
614.92
2004.92*



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Quotation No : QO18/03-1298	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7812B	Chassis No : MHFB29F3802011992	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLM8396U, DATE OF ACCIDENT: 27.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
22	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	150.00 60
23	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	150.0000	150.00 X
24	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	50.00 20
25	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.	1	150.0000	150.00 11 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	5,999.57
GST(7.00%)	419.97
Total (SGD)	6,419.54

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216