

Mon 09/04 @ 12am
82R

SLJ2818A

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 APR 2018

Estimate No. : b1 46438	Page No. : 1 of 2
Date Estimated : 31/03/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Ho Hai Wee (He Haiwei) 12C Hougang Street 11 #14-65 Singapore 534072	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0

DESCRIPTION

To replace front bumper & attachments including to knock out dented area caused by the accident

850 ~~1,275.00~~

To respray front bumper

934 ~~1,088.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

To remove old PDC assembly, and reconnect to new bumper including conduct checks for proper function.

X 177.00

Sundries.

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

FRT IMPACT ABSORBER
RH FINISHER (LUXURY LINE)
RH SUPPORT FOG LAMP (GESCHLOSSEN)
FRT BUMPER PANEL PRIMED (PMA)
GRILLE SIDE OPEN RH (LUXURY CLIP

QTY	PRIC	VALUE
1	47.80	? 47.80
1	60.20	? 60.20
1	50.95	? 50.95
1	842.00	R 842.00
1	95.85	? 95.85
10	1.30	? 13.00

Total Parts : 1,109.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46438	Page No. : 2 of 2
Date Estimated	: 31/03/2018	
Prepared By	: Han Kwan Yong	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ2818A	5B45446	02/12/2016	216d G TOURER	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>09/04/16 @ 1400</u>	Excess S\$ _____
Surveyor's Name <u>Rahul</u>	Sign _____
Surveyor's Tel <u>96010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Resurvey after repair

Labour 1	:	2,747.00
Parts	:	1,109.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	269.98
Grand Total	:	<u>4,126.78</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **