

ASS. REC. BY:

REF: CS/MSG180054147 / Amber

Special Instruction:

Survivor

Admin.

ASSIGNMENT (Office)

From (Person):

merimen
Ong Chin Kiat

of

MSG

Date/Time: 29032018 5:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFR 578J

Insured:

at Workshop m/s:

Premium

Tel:

of

55 Ubi Rd 1

Policy No:

A29820191QMY

Claim No:

553806

Sum Insured:

Excess:

\$ 800.00

Make of Veh:

D.O.A. 27032018

(Client's Record)

CA / ~~REP~~ / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

02042018 11:21am

Person Contacted:

Tony

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SFR 578J - CS/TP13006065 / Km

Ref: 05022012

3/4/18

Revert by merimen

3/4/18

Rece approved from Chen How by merimen

3/4/18

Informal Jerrery CIA on IBI not exceeding \$30k ex \$800 by email

19/7/18

@ 351pm Confirmed repair cost \$30000 with Mr Bod
(Red 14 In. 3390)

REF: MS64

ASSIGNMENT

From: Date: 01042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFR 578J

at Workshop m/s Premium

of 55 Ubi Rd 1

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$ 800.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 110K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8/14 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFR578J. Yr Regn: 2014 / Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 c.c. 1984.

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 45678 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No: WAU2ZZ46XEN074591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 02/04/18

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD MS64.

MV: 110K
 RV: 77K
 Nett: 33K.

RECEIVED 27 JUL 2018

Date/Time: For Pass m?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: For Return to?

2) 27/7 - typist

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1. S + P5. 28

1. Photo

1. Draw

TOTAL:

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech Univ \$☐ Weekend \$

Report Format: merimen

Lump Sum / I.B.I: \$ RS \$ 30,000/2

450

10

460



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005947/Avb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-04-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SFR 578J	
Policy No. A28820191QMY	Coverage (\$)		0.00	
Claim No. 553806	Excess (\$)		800.00	
Assign From MERIMEN (ONG CHIN KIAT)	Assign Date		29/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 27/03/2018	Inspection Date		02/04/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		29 Mar 2018 17:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIE KHIN SIN, ID: S1852647F, Tel: +6597303028		
Vehicle Reg. No.:	SFR578J	Date of Loss:	27/03/2018 19:00 - :59
Claim Type:	OD / 553806	Policy/Cover Note No.:	A28820191QMY (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
		Excess:	S\$800.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]		
Driver/Custodian:	LIE YI FANG, PAUL (35 / Male), NRIC: S8300050C, Tel: +6597988979		
Adj Asp. Remarks:	URGENT. Please revert.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

07042018 @ 11:21am
 Tony vehin
 Admin

View Received Message

This mail is associated with :

***SFR578J (553806)**

OD

Mar 27 2018 7:00PM

[LIE KHIN SIN]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 26/07/2018 13:56 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$30000.00) - SFR578J - Claim Handler: Ong Chin Kiat

Approved:30000.00:Repair cost cap at \$30000 before excess and GST

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 17 Jul 2018

Preliminary Advice

Vehicle No	: SFR578J	Accident Date	: 27/03/2018
Make	: AUDI A6	Policy No.	: A28820191QMY
Assignment Date	: 29/03/2018	Excess	: S\$800.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 14.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,702.00	(incl.supplementary \$2424)
Revised Amount	:S\$	32,121.50	(incl.supplementary \$2424)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	32,121.50	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	77,090.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,910.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

View Received Message

This mail is associated with :

***SFR578J (553806)**

OD

Mar 27 2018 7:00PM

[LIE KHIN SIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 16/04/2018 16:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$20415.00) - SFR578J - Claim Handler: Ong Chin Kiat

Approved:20415.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Ong Chin Kiat

Date: 16 Apr 2018

Preliminary Advice

Vehicle No	: SFR578J	Accident Date	: 27/03/2018
Make	: AUDI A6	Policy No.	: A28820191QMY
Assignment Date	: 29/03/2018	Excess	: S\$800.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,702.00	(incl.supplementary \$2345)
Revised Amount	:S\$	20,415.00	(incl.supplementary \$2345)
Check Items (Estimated)	:S\$	11,592.00	
Total	:S\$	32,007.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	110,000.00	
COE / PARF Rebate	:S\$	77,090.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	32,910.00	

Remarks

(X)

The vehicle is economical for repair. Kindly approved on the supplementary.

()

The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 5 April 2018 9:10 AM
To: 'Nora Khai'; 'Claims Dept'
Cc: SUR
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Nora,

The limit repair \$30 K on part by part basis.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nora Khai [mailto:nora.khai@premiumauto.com.sg]
Sent: Wednesday, 4 April 2018 7:15 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Hi Veron,

Is the limit repair 30 K ?

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 189902771W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Now is calling

The all-new Audi Q5



Find out more

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: 03 April, 2018 4:39 PM
To: Claims Dept
Cc: SUR
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Jeffery,

As instructed by our client, please proceed to repair the insured vehicle **SFR 578J not exceeding part by part \$30,000/- (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Monday, 2 April 2018 6:45 PM
To: claims@sg.msig-asia.com
Cc: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Survey was carried out earlier this afternoon.

Kindly follow up on the approval for this vehicle.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 209902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]

Sent: Monday, 2 April, 2018 1:02 PM

To: claims@sg.msig-asia.com

Cc: claims@premiumauto.com.sg

Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Importance: High

[Urgent reply please.](#)

Dear All,

Re-forwarding email to request for urgent survey.

Thank you.

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 209902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Now is calling

The all-new Audi Q5



Find out more

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]

Sent: 31 March, 2018 12:46 PM

To: 'claims@sg.msig-asia.com'

Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Re forwarding email.

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 299802731W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: 29 March, 2018 3:54 PM
To: claims@sg.msig-asia.com
Cc: 'Claims Dept'
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 159901271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 28 March, 2018 11:43 AM
To: claims@sg.msig-asia.com; claims@premiumauto.com.sg
Cc: 'Mastura' <mastura@premiumauto.com.sg>
Subject: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Do take note, vehicle is in our premises.

Thank you.

Best Regards,
Mastura
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. mastura@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 April 2018 4:39 PM
To: 'Claims Dept'
Cc: SUR
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Jeffery,

As instructed by our client, please proceed to repair the insured vehicle **SFR 578J not exceeding part by part \$30,000/- (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Monday, 2 April 2018 6:45 PM
To: claims@sg.msig-asia.com
Cc: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Survey was carried out earlier this afternoon.

Kindly follow up on the approval for this vehicle.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]
Sent: Monday, 2 April, 2018 1:02 PM
To: claims@sg.msig-asia.com
Cc: claims@premiumauto.com.sg
Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)
Importance: High

[Urgent reply please.](#)

Dear All,

Re-forwarding email to request for urgent survey.

Thank you.

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 139902373W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183
e. nora.khai@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]
Sent: 31 March, 2018 12:46 PM
To: 'claims@sg.msig-asia.com'
Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Re forwarding email.

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183
e. nora.khai@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: 29 March, 2018 3:54 PM
To: claims@sg.msig-asia.com
Cc: 'Claims Dept'
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 28 March, 2018 11:43 AM

To: claims@sg.msig-asia.com; claims@premiumauto.com.sg

Cc: 'Mastura' <mastura@premiumauto.com.sg>

Subject: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Do take note, vehicle is in our premises.

Thank you.

Best Regards,
Mastura
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. mastura@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SFR578J (553806)**

OD

Mar 27 2018 7:00PM

[LIE KHIN SIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/04/2018 16:22 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$18070.00) - SFR578J - Claim Handler: Ong Chin Kiat

Approved: 18070.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 03 Apr 2018

Preliminary Advice

Vehicle No	: SFR578J	Accident Date	: 27/03/2018
Make	: AUDI A6	Policy No.	: A28820191QMY
Assignment Date	: 29/03/2018	Excess	: S\$800.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,357.00
Revised Amount	:S\$	18,070.00
Check Items (Estimated)	:S\$	11,592.00
Total	:S\$	29,662.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	77,090.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,910.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2647F
Vehicle Details	
Vehicle No.:	SFR578J
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CDN385691
Chassis No.:	WAUZZZ4GXEN074591
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$38,197.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$40,476.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$30,357.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,801.00
COE Rebate Amount:	\$46,733.00
Total Rebate Amount:	\$77,090.00

The information contained herein is correct as at 02 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2647F
Vehicle Details	
Vehicle No.:	SFR578J
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CDN385691
Chassis No.:	WAUZZZ4GXEN074591
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$38,197.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$40,476.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$30,357.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,801.00
COE Rebate Amount:	\$46,733.00
Total Rebate Amount:	\$77,090.00

The information contained herein is correct as at 02 Apr 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2000 Downpayment Monthly
From \$688 Onwards. Lowest
3.68% P.A. 90% Cars Financing.
GV Credit Pte Ltd StarAd

• Free VICOM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

Audi A6

Advanced Search:

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A6		Any	Any	2014	Any	Any	Any	Available

**Audi A6 Avant 2.0A TFSI MU****\$116,800**

\$16,060 /yr

28-Feb-2014

1,984 cc

60,000 km

Stationwagon

Available

Agent Maintained, Accident Free. Extremely Reliable Family Ride. Rare In The Market. Trade In And Loan Available. Please Call For An Appointment.

PREMIUM AD

Posted: 08-Mar-2018 Tags: 2014 Audi A6, Audi A6, Audi, A6, Used Audi

**Audi A6 2.0A TFSI MU Ultra Edition****\$115,800**

\$14,170 /yr

17-Oct-2014

1,984 cc

-

Luxury

Available

Graded B by **STP**

STA 120 Points Evaluated. Up To 90% Loan! Flexible Repayment With In House Financing. Opt Extended Warranty Available. Owning A Car Is So Much Easier With Us. View To Believe. Call Us Now.

PREMIUM AD

Universe Motoring

Posted: 31-Mar-2018 Tags: 2014 Audi A6, Audi A6, Audi, A6, Used Audi

**Audi A6 2.0A TFSI MU****\$112,800**

\$13,680 /yr

30-Dec-2014

1,984 cc

45,000 km

Luxury

Available

White On Black Interior, Full Serviced And Maintained By Agent (Premium Automobiles), Powerful And Fuel Efficient Mid-Size Executive Sedan With 4 Different Driving Modes To Cater To Your Mood And Styl...

PREMIUM AD

Posted: 01-Apr-2018 Tags: 2014 Audi A6, Audi A6, Audi, A6, Used Audi

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 ▼ results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A6, Audi A6 Singapore, used Audi A6 Singapore, used Audi A6, used vehicles Singapore or even buy used Audi A6 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Taxi & Tip

- About Us
- Careers
- Contact Us
- Sitemap

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. A 28820191 QMY

Excess : SGD800

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle

SFR578J

2. Name of Policyholder

Lie Khin Sin

3. Effective Date of the Commencement of Insurance for the purposes of the Act

30/09/2017

4. Date of Expiry of Insurance

29/09/2018

5. Persons or Classes of Persons entitled to drive*

Lie Khin Sin

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8300050C**

Name
LIE YI FANG, PAUL

Birth Date **04 Jan 1983**
Issue Date **07 Apr 2004**

001190179H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8300050C**

Name
LIE YI FANG, PAUL

李奕芳

Race
CHINESE

Date of birth **04-01-1983** Sex **M**

Country of birth
SINGAPORE

Passion
SILVER

LIE KHIN SIN
S1852647F
8800 3000 0626 2587
EXPIRES ON 31/08/2023

SENIOR CITIZEN CONCESSION

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

PASS DATE **07 Apr 2004**

Licence No: **S8300050C**

NP 428A

4805308

NRIC No: **S8300050C**

Date of issue **03-07-2010**

383 TANGLIN ROAD #08-04
SINGAPORE 247866

NRIC No: **S8300050C** Date: **17/01/2016**

Concession

- This card is issued and managed by the Land Transport Authority of Singapore.
- Use governed by conditions published at www.lta.gov.sg, statutes and regulations.
- This card can only be used by the person whose name and Birth Certificate No./NRIC is printed on the reverse side of this card. Unlawful use of this card to evade lawfully payable fees is an offence.
- This card shall be retained if it has been tampered with, misused, replaced or refunded.
- Customer Service Line: 1800-CALL ONE (1800-2255 603)



CAN 8008 1600 0170 3265

CD 11/10/2016

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/03/2018 11:12
Date Of Accident	27/03/2018 19:40
Exact Location Of Accident	CLEMENTI RD BEF AYE TURNING OFF
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFR578J
Insured/Policyholder	
Name Of Registered Owner	LIE KHIN SIN
NRIC No	S1852647F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97303028
Alternative Phone No	OFFICE-64665247

Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU 4G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28820191 QMY
Cover Note Number	

Driver

Name of Driver	LIE YI FANG, PAUL
NRIC No	S8300050C
Date Of Birth	04/01/1983
Occupation	INDOOR
Date Of Driving Pass	07/04/2004
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97988979
Fax Number	
Contact Number	
Email Address	PAULNPEGS@GMAIL.COM

Address	383 TANGLIN ROAD #06-04
Postcode	247966
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG CLEMENTI ROAD TOWARDS THE TURN OFF THE AYE (CITY) EXIT, WHEN THE THE CARS IN FRONT OF ME DID AN EMERGENCY BRAKE. I BRAKED BUT AS THE ROAD WAS WET, I WAS UNABLE TO STOP IN TIME AND COLLIDED WITH THE LAST CAR. THE FIRST TWO CARS COLLIDED, THE THIRD AND FOURTH CAR STOPPED IN TIME BUT I COLLIDED WITH THE FOURTH CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8322G
Vehicle Make/Model/Colour	MAZDA / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KAI HUI COLIN
NRIC/Passport Number	S8220249H
Contact Number	96881909
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 24/3/18

Reporting Centre Personnel's Signature
Name: Norazma Binte Khairuddin
NRIC/FIN No: 58034767Z

Sketch Plan #2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along eleventh road towards the turn off the AYE (city) when the cars in front of me did an emergency brake. I ~~was~~ braked but as the road was wet I was unable to stop in time and collided with the last car. The first two cars collided, the third and fourth car stopped in time but I collided with the fourth car.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/3/18

0840


Reporting Centre Personnel's Signature
Name: NCHAZIMA Binte Khamuddin
NRIC/TIN No: 580547572

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0383/2018/GW
Date : 29-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr. Lie Khin Sin
Address : 16 Vanda Drive
Singapore 287854

Telephone : HP 97893436
Type of Claim : Own Damage Claims
Policy No. : A 28820191 QMY
Vehicle No : **SFR 578 J**
Model Code : Audi A6 C7 2.0 TFSI Mu 4G
Model / Year : Sep-14
Engine No : CDN 385691
Chassis No : WAUZZZ4GXEN074591
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-18
Place of Accident : Clementi Rd BEF AYE Turning Off

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFR 578 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,200.00 ?	✓
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,300.00 4550 (part including lock carrier)	
4	To respray front bumper, both front fenders, bonnet and hinges.	\$ 3,600.00 2800 2900	
5	To renew front windscreen.	S/N \$ 480.00 ✓	✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 12,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,326.00	✓ 2326
2	FRONT BUMPER FIXING PARTS <i>Not</i>	\$ 236.00	+
3	RADIATOR GRILLE <i>Can't</i>	\$ 1,174.00	✓ 1174
4	RADIATOR GRILLE COVER <i>Can't</i>	\$ 32.00	✓ 31.30
5	FRONT SUPPORT PARKING AID-LH/RH <i>Not Nec</i>	2 \$ 118.00	? X
6	FRONT BUMPER GRILLE-LH/RH <i>RH Missing</i>	2 \$ 268.00	134. 133.50
7	FRONT BUMPER END CAP-LH ? <i>nn</i>	\$ 34.00	✓ X
8	FOAM FILLER PIECE <i>Del'd</i>	\$ 85.00	✓ 84.30
9	FRONT BUMPER HOLDER BRACKET-LH/RH ? <i>Not Nec</i>	\$ 446.00	X
10	FRONT BUMPER SUPPORT- LH/RH	2 \$ 21.00	X
11	FRONT BUMPER GUIDE PIECE-LH/RH <i>Damaged</i>	2 \$ 64.00	+ 31.70
12	FRONT BUMPER COVER <i>Del'd</i>	\$ 105.00	✓ 105
13	SIGN "CUATION" <i>nn</i>	\$ 12.00	✓ 11.60
14	FRONT FENDER-LH/RH <i>Repair</i>	2 \$ 2,440.00	+
15	FENDER ATTACHMENT PARTS <i>Not Nec</i>	\$ 36.00	X
16	FRONT STONE GUARD CHIP-LH <i>nn</i>	\$ 105.00	✓ 104.50
17	FRONT FENDER BRACE-LH/RH <i>nn</i>	2 \$ 144.00	+
18	FRONT WHEEL SPOILER-LH/RH <i>nn LH to RH</i>	2 \$ 404.00	+ 301.50
19	HEADLIGHT GAS DISCHARGE-LH/RH <i>nn Can't</i>	2 \$ 5,806.00	2903. 5806
20	GAS DISCHARGE LAMP <i>nn Not Nec</i>	\$ 394.00	in ? X
SUB - TOTAL SPARE PARTS		\$ 14,250.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	GAS DISCHARGE BULB RETAINING RING <i>new</i>	\$ 75.00	? ☒
22	GAS DISCHARGE CONTROL UNIT <i>new</i>	\$ 1,018.00	? ☒
23	HEADLIGHT POWER MODULE <i>Damaged</i>	\$ 501.00	? ☒ <i>500.50</i>
24	HOSE <i>new</i>	\$ 14.00	? ☒
25	HEADLIGHT MOUNTING-LH/RH <i>2x Touchd</i>	2 \$ 206.00	? ☒ <i>103</i>
26	HEADLIGHT COVER CAP-LH/RH <i>new</i>	2 \$ 98.00	? ☒
27	HEADLIGHT LIFT CYLINDER <i>embd</i>	\$ 208.00	? ☒ <i>207.50</i>
28	ELBOW FITTING <i>new</i>	2 \$ 45.00	+
29	HEADLIGHT WASHER HOSE <i>new</i>	5 \$ 172.00	+
30	BONNET <i>Distorted</i>	\$ 4,771.00	✓ <i>4771</i>
31	BONNET ONE ATTACHMENT PARTS <i>new</i>	\$ 123.00	? ☒
32	BONNET LID HINGE-LH/RH <i>new</i>	2 \$ 282.00	+
33	BONNET CATCH HOOK <i>Best</i>	\$ 122.00	? ☒ <i>122</i>
34	BONNET LOCK BAR <i>Damaged</i>	2 \$ 87.00	? ☒ <i>86.40</i>
35	BONNET HOOD LATCH <i>new</i>	\$ 15.00	? ☒
36	BONNET LID LOCK WITH MICRO <i>Damaged</i>	2 \$ 376.00	? ☒ <i>376</i>
37	BOWDEN CABLE <i>Damaged</i>	\$ 50.00	✓ ☒ <i>50</i>
38	BONNET LID LOCK CABLE <i>new</i>	\$ 64.00	+
39	BONNET LOCK CARRIER WITH MOUNTING <i>embd</i>	\$ 1,024.00	✓ ☒ <i>1024</i>
40	AIR GUIDE-LH/RH <i>embd RH</i>	2 \$ 54.00	? ☒ <i>56.40</i>
SUB - TOTAL SPARE PARTS		\$ 9,305.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
41	CHARGE AIR COOLER <i>Not New</i>	S 492.00	X
42	A/C CONDENSOR <i>Detected</i>	S 683.00	? <i>683.50</i>
43	RADIATOR <i>Detected</i>	S 674.00	? <i>673.50</i>
44	RUBBER BUSH <i>Not New</i>	6 S 52.00	? X
45	COOLANT CONCENTRATE <i>New</i>	4 S 133.00	? <i>1132.80</i>
46	FRONT NO. PLATE <i>New</i>	S/N S 25.00	✓ <i>25</i>
47	TWIN FAN RING <i>Not New</i>	S 226.00	? X
48	RADIATOR FAN <i>Not New</i>	2 S 1,439.00	? X
49	RADIATOR CONTROL UNIT <i>Not New</i>	S 740.00	? X
50	AIR DUCT <i>Detected</i>	S 22.00	? <i>51.70</i>
51	INTAKE AIR DUCT <i>Detected</i>	S 65.00	? <i>65</i>
52	AIR FILTER <i>Detected</i>	S 256.00	? <i>355.50</i>
53	EXTERNAL TEMPERATURE SENSOR <i>Not New</i>	S 54.00	? X
54	AIR TEMPERATURE SENSOR BRACKET <i>Not New</i>	S 20.00	? X
55	WINDSHIELD WIPER COVER <i>Not New</i>	S 174.00	+ <i>173.50</i>
56	WATER DEFLECTOR <i>Not New</i>	S 66.00	+ <i>65.30</i>
57	GEL FOIL FOR RAIN SENSOR <i>New</i>	S 127.00	- <i>126.50</i>
58	PRIMER <i>New</i>	S 19.00	✓ <i>18.20</i>
59	WATER DEFLECTOR STRIP <i>Not New</i>	S 58.00	? X
60	FRONT NO. PLATE <i>Repeated</i>	S/N S 25.00	+
SUB-TOTAL SPARE PARTS		: S	<u><u>5,350.00</u></u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	FRONT WINDSCREEN SEALANT <i>new</i>	S/NETT \$ 200.00	✓ 200
42	SUNDRIES <i>new</i>	\$ 1,000.00	? 181.90
TOTAL SPARE PARTS		: \$ 30,105.00	
TOTAL LABOUR CHARGES		: \$ 12,252.00	
GRAND TOTAL		: \$ 42,357.00	44,702

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

30779

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	CHARGE AIR COOLER <i>Not New</i>	\$	492.00 X
42	A/C CONDENSOR ? <i>del</i>	\$	683.00 ?
43	RADIATOR ? <i>del</i>	\$	674.00 ?
44	RUBBER BUSH ?	6 \$	52.00 ?
45	COOLANT CONCENTRATE ? <i>del</i>	4 \$	133.00 ?
46	FRONT NO. PLATE <i>del</i>	S/N \$	25.00 ✓ <i>25.00</i>
47	TWIN FAN RING ?	\$	226.00 ?
48	RADIATOR FAN ?	2 \$	1,439.00 ?
49	RADIATOR CONTROL UNIT ?	\$	740.00 ?
50	AIR DUCT ? <i>del</i>	\$	22.00 ?
51	INTAKE AIR DUCT ? <i>del</i>	\$	65.00 ?
52	AIR FILTER ? <i>del</i>	\$	256.00 ?
53	EXTERNAL TEMPERATURE SENSOR ?	\$	54.00 ?
54	AIR TEMPERATURE SENSOR BRACKET ?	\$	20.00 ?
55	WINDSHIELD WIPER COVER <i>Not on</i>	\$	174.00 X
56	WATER DEFLECTOR <i>del</i>	\$	66.00 X
57	GEL FOIL FOR RAIN SENSOR <i>del</i>	\$	127.00 ✓
58	PRIMER <i>del</i>	\$	19.00 ✓
59	WATER DEFLECTOR STRIP ?	\$	58.00 ?
60	FRONT NO. PLATE <i>del Repeated</i>	S/N \$	25.00 X
SUB-TOTAL SPARE PARTS		\$	5,350.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Front WLS parts not inside.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 1

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	GAS DISCHARGE BULB RETAINING RING ?	\$ 75.00	?
22	GAS DISCHARGE CONTROL UNIT ?	\$ 1,018.00	?
23	HEADLIGHT POWER MODULE ? <i>dis</i>	\$ 501.00	?
24	HOSE ?	\$ 14.00	?
25	HEADLIGHT MOUNTING-LH/RH <i>2H</i> ?	2 \$ 206.00	?
26	HEADLIGHT COVER CAP-LH/RH <i>2H</i> ?	2 \$ 98.00	?
27	HEADLIGHT LIFT CYLINDER ?	\$ 208.00	?
28	ELBOW FITTING <i>new</i>	2 \$ 45.00	?
29	HEADLIGHT WASHER HOSE <i>new</i>	5 \$ 172.00	?
30	BONNET <i>Distorted</i>	\$ 4,771.00	✓
31	BONNET ONE ATTACHMENT PARTS ?	\$ 123.00	?
32	BONNET LID HINGE-LH/RH <i>new</i>	2 \$ 282.00	?
33	BONNET CATCH HOOK ? <i>dis</i>	\$ 122.00	?
34	BONNET LOCK BAR ? <i>dis</i>	2 \$ 87.00	?
35	BONNET HOOD LATCH ?	\$ 15.00	?
36	BONNET LID LOCK WITH MICRO ? <i>dis</i>	2 \$ 376.00	?
37	BOWDEN CABLE <i>new</i>	\$ 50.00	?
38	BONNET LID LOCK CABLE <i>new</i>	\$ 64.00	?
39	BONNET LOCK CARRIER WITH MOUNTING ? <i>dis</i>	\$ 1,024.00	?
40	AIR GUIDE-LH/RH ? <i>dis</i>	2 \$ 54.00	?
SUB - TOTAL SPARE PARTS		\$ 9,305.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

84791

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$	2,326.00 ✓
2	FRONT BUMPER FIXING PARTS <i>As per</i>	\$	236.00 ✓
3	RADIATOR GRILLE <i>Canled</i>	\$	1,174.00 ✓
4	RADIATOR GRILLE COVER <i>Canled</i>	\$	32.00 ✓
5	FRONT SUPPORT PARKING AID-LH/RH ?	2 \$	118.00 ?
6	FRONT BUMPER GRILLE-LH/RH <i>RH Missing</i>	2 \$	268.00 134
7	FRONT BUMPER END CAP-LH ?	\$	34.00 ?
8	FOAM FILLER PIECE <i>De hand</i>	\$	85.00 ✓
9	FRONT BUMPER HOLDER BRACKET-LH/RH	\$	446.00
10	FRONT BUMPER SUPPORT- LH/RH	2 \$	21.00
11	FRONT BUMPER GUIDE PIECE-LH/RH <i>As per</i>	2 \$	64.00 ✓
12	FRONT BUMPER COVER <i>De hand</i>	\$	105.00 ✓
13	SIGN "CUATION" <i>As</i>	\$	12.00 ✓
14	FRONT FENDER-LH/RH <i>Repair</i>	2 \$	2,440.00 ✓
15	FENDER ATTACHMENT PARTS	\$	36.00
16	FRONT STONE GUARD CHIP-LH <i>As</i>	\$	105.00 ✓
17	FRONT FENDER BRACE-LH/RH <i>As per</i>	2 \$	144.00 ✓
18	FRONT WHEEL SPOILER-LH/RH <i>As per</i>	2 \$	404.00 ✓
19	HEADLIGHT GAS DISCHARGE-LH/RH <i>As per RH Canled</i>	2 \$	5,806.00 2903
20	GAS DISCHARGE LAMP <i>As per ?</i>	\$	394.00 ✓ ?
SUB - TOTAL SPARE PARTS		:	<u>\$ 14,250.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Confirmed : 8/6/97

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 02/04/18
Authorised Date :
Excess Cost : \$200
Liability :
Remarks : Not Authorised , 10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


3/6/18

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate - 1

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd No 4 Shenton Way #23-01 SGX Centre 2 Singapore 068896 Attn: Motor Claims Dept Tel: 6827 2762 - Fax: 6225 7402		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0383/2018/GW 12-Apr-18 CHANG 1 SFR 578 J Audi A6 C7 2.0 TFSI MU
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT REINFORCEMENT BEAM	\$ 702.00	by ✓
2	FRONT REINFORCEMENT BEAM BRACKET - RH	\$ 223.00	by ✓
3	FRONT BUMPER BRACE - RH	\$ 25.00	by ✓
4	HEADLIGHT CONNECTOR HOUSING	\$ 28.00	one ✓
5	FRONT WINDSCREEN	\$ 1,367.00	One ✓
GRAND TOTAL		\$ 2,345.00	

For Premium Automobiles Pte Ltd

Handwritten:
12/4/18

Handwritten signature over stamp

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate - 2

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd No 4 Shenton Way #23-01 SGX Centre 2 Singapore 068896 Attn: Motor Claims Dept Tel: 6827 2762 - Fax: 6225 7402		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0383/2018/GW 16-Apr-18 CHANG 1 SFR 578 J Audi A6 C7 2.0 TFSI MU	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	SOLENOID VALVE <i>Damaged</i>	\$ 70.00		
2	SOLENOID VALVE CONNECTOR <i>included</i>	\$ 9.00		
GRAND TOTAL		\$ 79.00		

Adrian Ling
8/5

For Premium Automobiles Pte Ltd



Authorised Signature

Veron Chen (LKKAUTO)

From: PAL Claim <claims@premiumauto.com.sg>
Sent: Monday, 7 May 2018 5:41 PM
To: Veron Chen (LKKAUTO)
Cc: Adrian Ling (LKKAUTO); 'PAL Claim'
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)
Attachments: [Untitled].pdf; AFWN2608.JPG; OBTA6602.JPG; DUUV9251.JPG; KKKI5230.JPG; JJK3102.JPG; JRCW4505.JPG; JWRA5951.JPG; LESM9864.JPG; VPD12782.JPG; XHFG2587.JPG; GCM14455.JPG; VJXT4309.JPG; PLXX8466.JPG

Dear Veron,

Kindly assist to pass the supplementary document and photographs to Mr Adrian for marking.

Thank you.

Best regards,
Chang Chee Sing
Estimator

Premium Automobiles Pte Ltd (Reg No. 199802271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nora Khai <nora.khai@premiumauto.com.sg>
Sent: Monday, 16 April 2018 5:26 PM
To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Veron,

Noted with thanks.

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 189902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Now is calling

The all-new Audi Q5



Q5

Find out more

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]

Sent: 16 April, 2018 5:23 PM

To: Nora Khai; 'Claims Dept'

Cc: SUR

Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Nora,

Please refer supplementary marking.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)

Sent: Thursday, 5 April 2018 9:10 AM

To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; 'Claims Dept' <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Nora,

The limit repair \$30 K on part by part basis.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nora Khai [mailto:nora.khai@premiumauto.com.sg]

Sent: Wednesday, 4 April 2018 7:15 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Hi Veron,

Is the limit repair 30 K ?

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: 03 April, 2018 4:39 PM

To: Claims Dept

Cc: SUR

Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear Jeffery,

As instructed by our client , please proceed to repair the insured vehicle **SFR 578J** not exceeding part by part \$30,000/- (Excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Monday, 2 April 2018 6:45 PM

To: claims@sg.msig-asia.com

Cc: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Survey was carried out earlier this afternoon.

Kindly follow up on the approval for this vehicle.

Many thanks!

Best regards,

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]
Sent: Monday, 2 April, 2018 1:02 PM
To: claims@sg.msig-asia.com
Cc: claims@premiumauto.com.sg
Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)
Importance: High

Urgent reply please.

Dear All,

Re-forwarding email to request for urgent survey.

Thank you.

Best Regards,

Norazima Khairuddin
 Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]
Sent: 31 March, 2018 12:46 PM
To: 'claims@sg.msig-asia.com'
Subject: FW: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Re forwarding email.

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199602271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183
e. nora.khai@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: 29 March, 2018 3:54 PM
To: claims@sg.msig-asia.com
Cc: 'Claims Dept'
Subject: RE: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Attached the estimate for your kind reference.

Kindly advise the surveyor firm engages for this company and make an urgent arrangement as the vehicle in in the workshop.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 28 March, 2018 11:43 AM
To: claims@sg.msig-asia.com; claims@premiumauto.com.sg
Cc: 'Mastura' <mastura@premiumauto.com.sg>
Subject: SFR 0578 J - MSIG OD - DOA: 27/03/2018 (VEHICLE IN)

Dear all,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Do take note, vehicle is in our premises.

Thank you.

Best Regards,
Mastura
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 188802271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. mastura@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0383/2018/GW
Date : 29-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Hi Adrian
You recommended 6 days
We took 14 days exclude 3 Sundays
with checked items replace. Etc
jd 5 Jul 18

Owner's Name : Mr. Lie Khin Sin
Address : 16 Vanda Drive
Singapore 287854

Telephone : HP 97893436
Type of Claim : Own Damage Claims
Policy No. : A 28820191 QMY
Vehicle No : **SFR 578 J**
Model Code : Audi A6 C7 2.0 TFSI Mu 4G
Model / Year : Sep-14
Engine No : CDN 385691
Chassis No : WAUZZZ4GXEN074591
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-18
Place of Accident : Clementi Rd BEF AYE Turning Off

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6386 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFR 578 J.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid .	S/N \$	480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$	1,200.00	\$ 1,200.00
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed. <i>(Added 3.5 days @\$700.00 = \$2450 + 2100 = \$4550.00 L/Carrier, HL etc)</i>	\$	6,300.00	\$ 4,550.00
4	To respray front bumper, both front fenders, bonnet and hinges. <i>(Bonnet New add \$100.00)</i>	\$	3,600.00	\$ 2,900.00
5	To renew front windscreen.	S/N \$	480.00	\$ 480.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 12,252.00</u>	<u>\$ 9,802.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,326.00	\$ 2,326.00
2	FRONT BUMPER FIXING PARTS	\$ 236.00	
3	RADIATOR GRILLE	\$ 1,174.00	\$ 1,174.00
4	RADIATOR GRILLE COVER	\$ 32.00	\$ 31.20
5	FRONT SUPPORT PARKING AID-LH/RH	2 \$ 118.00	
6	FRONT BUMPER GRILLE-LH/RH	2 \$ 268.00	\$ 133.50
7	FRONT BUMPER END CAP-LH	\$ 34.00	
8	FOAM FILLER PIECE	\$ 85.00	\$ 84.30
9	FRONT BUMPER HOLDER BRACKET-LH/RH	\$ 446.00	
10	FRONT BUMPER SUPPORT- LH/RH	2 \$ 21.00	
11	FRONT BUMPER GUIDE PIECE-LH/RH	2 \$ 64.00	\$ 31.70
12	FRONT BUMPER COVER	\$ 105.00	\$ 105.00
13	SIGN "CUATION"	\$ 12.00	\$ 11.60
14	FRONT FENDER-LH/RH	2 \$ 2,440.00	
15	FENDER ATTACHMENT PARTS	\$ 36.00	
16	FRONT STONE GUARD CHIP-LH	\$ 105.00	\$ 104.50
17	FRONT FENDER BRACE-LH/RH	2 \$ 144.00	
18	FRONT WHEEL SPOILER-LH/RH	2 \$ 404.00	\$ 201.50
19	HEADLIGHT GAS DISCHARGE-LH/RH	2 \$ 5,806.00	\$ 5,806.00
20	GAS DISCHARGE LAMP	\$ 394.00	
SUB - TOTAL SPARE PARTS		\$ 14,250.00	\$ 10,009.30

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J

S/N	Parts Description	c/f	Damage Parts & Prices		
			S/NETT	REMARKS	
				\$	10,009.30
21	GAS DISCHARGE BULB RETAINING RING		\$ 75.00		
22	GAS DISCHARGE CONTROL UNIT		\$ 1,018.00		
23	HEADLIGHT POWER MODULE		\$ 501.00	\$ 500.50	
24	HOSE		\$ 14.00		
25	HEADLIGHT MOUNTING-LH/RH	2	\$ 206.00	\$ 103.00	
26	HEADLIGHT COVER CAP-LH/RH	2	\$ 98.00		
27	HEADLIGHT LIFT CYLINDER		\$ 208.00	\$ 207.50	
28	ELBOW FITTING	2	\$ 45.00		
29	HEADLIGHT WASHER HOSE	5	\$ 172.00		
30	BONNET		\$ 4,771.00	\$ 4,771.00	
31	BONNET ONE ATTACHMENT PARTS		\$ 123.00		
32	BONNET LID HINGE-LH/RH	2	\$ 282.00		
33	BONNET CATCH HOOK		\$ 122.00	\$ 122.00	
34	BONNET LOCK BAR	2	\$ 87.00	\$ 86.40	
35	BONNET HOOD LATCH		\$ 15.00		
36	BONNET LID LOCK WITH MICRO	2	\$ 376.00	\$ 376.00	
37	BOWDEN CABLE		\$ 50.00	\$ 50.00	
38	BONNET LID LOCK CABLE		\$ 64.00		
39	BONNET LOCK CARRIER WITH MOUNTING		\$ 1,024.00	\$ 1,024.00	
40	AIR GUIDE-LH/RH	2	\$ 54.00	\$ 26.40	
SUB - TOTAL SPARE PARTS			\$ 9,305.00	\$ 17,276.10	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFR 578 J.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	17,276.10
41	CHARGE AIR COOLER		\$ 492.00	
42	A/C CONDENSOR		\$ 683.00	\$ 682.50
43	RADIATOR		\$ 674.00	\$ 673.50
44	RUBBER BUSH	6	\$ 52.00	
45	COOLANT CONCENTRATE	4	\$ 133.00	\$ 132.80
46	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
47	TWIN FAN RING		\$ 226.00	
48	RADIATOR FAN	2	\$ 1,439.00	
49	RADIATOR CONTROL UNIT		\$ 740.00	
50	AIR DUCT		\$ 22.00	\$ 21.70
51	INTAKE AIR DUCT		\$ 65.00	\$ 65.00
52	AIR FILTER		\$ 256.00	\$ 255.50
53	EXTERNAL TEMPERATURE SENSOR		\$ 54.00	
54	AIR TEMPERATURE SENSOR BRACKET		\$ 20.00	
55	WINDSHIELD WIPER COVER		\$ 174.00	\$ 173.50
56	WATER DEFLECTOR		\$ 66.00	\$ 65.30
57	GEL FOIL FOR RAIN SENSOR		\$ 127.00	\$ 126.50
58	PRIMER		\$ 19.00	\$ 18.20
59	WATER DEFLECTOR STRIP		\$ 58.00	
60	FRONT NO. PLATE	S/N	\$ 25.00	
SUB-TOTAL SPARE PARTS		:	\$ 5,350.00	\$ 19,515.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 19,515.60
61	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
63	<i>Added parts</i>		\$ 79.00	\$ 77.90
64	<i>Added parts</i>		\$ 2,345.00	\$ 2,344.10
65	SUNDRIES		\$ 1,000.00	\$ 181.90
	TOTAL SPARE PARTS	:	\$ 32,529.00	\$ 22,319.50
	TOTAL LABOUR CHARGES	:	\$ 12,252.00	\$ 9,802.00
	GRAND TOTAL	:	\$ 44,781.00	\$ 32,121.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 July 2018 9:35 AM
To: 'Boo seng yak'; Adrian Ling (LKKAUTO); SUR; 'Carrine Leong'; 'jiayee.yap@premiumauto.com.sg'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SFR578J - OD MSIG - SURVEYED 2 APR 18

Dear Carrine,

Confirmed repair cost \$30,000 before excess \$800 and GST @ 14 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 July 2018 5:45 PM
To: 'Boo seng yak' <boojohnny@gmail.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SFR578J - OD MSIG - SURVEYED 2 APR 18

Dear Carrine,

Please refer attached email, repair cost not exceeding \$30,000/-.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Thursday, 5 July 2018 2:31 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SFR578J - OD MSIG - SURVEYED 2 APR 18

Hi Adrian and all,

Revised estimate and photographs for checked items is attached for your attention.

Please confirm repair cost of \$32,121.50 @ 14 days of repairs exclude 3 Sundays. Our invoice will be for \$30K limited repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate - 1

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd No 4 Shenton Way #23-01 SGX Centre 2 Singapore 068896 Attn: Motor Claims Dept Tel: 6827 2762 - Fax: 6225 7402		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0383/2018/GW 12-Apr-18 CHANG 1 SFR 578 J Audi A6 C7 2.0 TFSI MU	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 702.00	\$	702.00
2	FRONT REINFORCEMENT BEAM BRACKET - RH <i>Best</i>	\$ 223.00	\$	223.00
3	FRONT BUMPER BRACE - RH <i>2x</i>	\$ 25.00	\$	24.90
4	HEADLIGHT CONNECTOR HOUSING <i>and</i>	\$ 28.00	\$	27.20
5	FRONT WINDSCREEN <i>Cracked</i>	\$ 1,367.00	\$	1,367.00
GRAND TOTAL		\$ 2,345.00	\$	2,344.10

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate - 2

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd No 4 Shenton Way #23-01 SGX Centre 2 Singapore 068896 Attn: Motor Claims Dept Tel: 6827 2762 - Fax: 6225 7402		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0383/2018/GW 16-Apr-18 CHANG 1 SFR 578 J Audi A6 C7 2.0 TFSI MU	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	SOLENOID VALVE	\$ 70.00	\$	69.80
2	SOLENOID VALVE CONNECTOR	\$ 9.00	\$	8.10
GRAND TOTAL		\$ 79.00	\$	77.90

For Premium Automobiles Pte Ltd

Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		29 Mar 2018 17:16 Edit Adj Rpt	\$530,000.00 Edit Estimates	\$530,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIE KHIN SIN , ID: S1852647F, Tel: +6597303028									
Vehicle Reg. No.: SFR578J		Date of Loss: 27/03/2018 19:00 - :59 [41 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 553806		Policy/Cover Note No.: A28820191QMY (Comprehensive) Coverage: 30/09/2017 - 29/09/2018 Excess: \$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/04/2018]									
Driver/Custodian: LIE YI FANG, PAUL (35 / Male), NRIC: S8300050C, Tel: +6597988979									
Adj Asg. Remarks: URGENT. Please revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (26/07/2018): Alert - Adj Mandate Approved (\$530000.00) - SFR578J - Claim Handler: Ong Chin Ki... - MSIG_SG (16/04/2018): Alert - Adj Mandate Approved (\$20415.00) - SFR578J - Claim Handler: Ong Chin Ki... - MSIG_SG (03/04/2018): Alert - Adj Mandate Approved (\$18070.00) - SFR578J - Claim Handler: Ong Chin Ki...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFR578J (553806)
OD
Mar 27 2018 7:00PM
[LIE KHIN SIN]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/03/18 11:37	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 09:54	Adjuster Immediate Advice	 Load HTM	
2	16/04/18 11:52	Adjuster Immediate Advice	 Load HTM	
3	17/07/18 15:41	Adjuster Immediate Advice	 Load HTM	
4	17/07/18 15:47	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 09:55	General View	 Load JPG	☒
2	03/04/18 09:55	General View	 Load JPG	☒
3	03/04/18 09:55	General View	 Load JPG	☒
4	03/04/18 09:55	General View	 Load JPG	☒
5	03/04/18 09:55	General View	 Load JPG	☒
6	03/04/18 09:55	General View	 Load JPG	☒
7	03/04/18 09:55	General View	 Load JPG	☒
8	03/04/18 09:55	General View	 Load JPG	☒
9	03/04/18 09:55	General View	 Load JPG	☒
10	03/04/18 09:55	General View	 Load JPG	☒
11	03/04/18 09:55	General View	 Load JPG	☒
12	03/04/18 09:55	General View	 Load JPG	☒
13	03/04/18 09:55	General View	 Load JPG	☒
14	03/04/18 09:55	General View	 Load JPG	☒
15	03/04/18 09:55	General View	 Load JPG	☒
16	03/04/18 09:55	General View	 Load JPG	☒
17	03/04/18 09:55	General View	 Load JPG	☒
18	03/04/18 09:55	General View	 Load JPG	☒
19	03/04/18 09:55	General View	 Load JPG	☒
20	03/04/18 09:55	General View	 Load JPG	☒
21	03/04/18 09:55	General View	 Load JPG	☒
22	03/04/18 09:55	General View	 Load JPG	☒
23	03/04/18 09:55	General View	 Load JPG	☒
24	03/04/18 09:55	General View	 Load JPG	☒
25	03/04/18 09:55	General View	 Load JPG	☒
26	03/04/18 09:55	General View	 Load JPG	☒
27	03/04/18 09:55	General View	 Load JPG	☒
28	03/04/18 09:55	General View	 Load JPG	☒
29	16/04/18 11:07	Reinspection Photo	 Load JPG	☒
30	16/04/18 11:07	Reinspection Photo	 Load JPG	☒
31	16/04/18 11:07	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
32	16/04/18 11:07	Reinspection Photo		Load JPG	☒
33	16/04/18 11:07	Reinspection Photo		Load JPG	☒
34	16/04/18 11:07	Reinspection Photo		Load JPG	☒
35	16/04/18 11:07	Reinspection Photo		Load JPG	☒
36	16/04/18 11:07	Reinspection Photo		Load JPG	☒
37	16/04/18 11:07	Reinspection Photo		Load JPG	☒
38	16/04/18 11:07	Reinspection Photo		Load JPG	☒
39	16/04/18 11:07	Reinspection Photo		Load JPG	☒
40	16/04/18 11:07	Reinspection Photo		Load JPG	☒
41	16/04/18 11:07	Reinspection Photo		Load JPG	☒
42	16/04/18 11:07	Reinspection Photo		Load JPG	☒
43	16/04/18 11:07	Reinspection Photo		Load JPG	☒
44	16/04/18 11:07	Reinspection Photo		Load JPG	☒
45	16/04/18 11:07	Reinspection Photo		Load JPG	☒
46	16/04/18 11:07	Reinspection Photo		Load JPG	☒
47	16/04/18 11:07	Reinspection Photo		Load JPG	☒
48	16/04/18 11:07	Reinspection Photo		Load JPG	☒
49	16/04/18 11:07	Reinspection Photo		Load JPG	☒
50	16/04/18 11:07	Reinspection Photo		Load JPG	☒
51	16/04/18 11:07	Reinspection Photo		Load JPG	☒
52	16/04/18 11:07	Reinspection Photo		Load JPG	☒
53	16/04/18 11:07	Reinspection Photo		Load JPG	☒
54	16/04/18 11:07	Reinspection Photo		Load JPG	☒
55	16/04/18 11:07	Reinspection Photo		Load JPG	☒
56	16/04/18 11:07	Reinspection Photo		Load JPG	☒
57	16/04/18 11:07	Reinspection Photo		Load JPG	☒
58	16/04/18 11:07	Reinspection Photo		Load JPG	☒
59	16/04/18 11:07	Reinspection Photo		Load JPG	☒
60	16/04/18 11:07	Reinspection Photo		Load JPG	☒
61	16/04/18 11:07	Reinspection Photo		Load JPG	☒
62	16/04/18 11:07	Reinspection Photo		Load JPG	☒
63	16/04/18 11:07	Reinspection Photo		Load JPG	☒
64	16/04/18 11:07	Reinspection Photo		Load JPG	☒
65	16/04/18 11:07	Reinspection Photo		Load JPG	☒
66	16/04/18 11:07	Reinspection Photo		Load JPG	☒
67	16/04/18 11:07	Reinspection Photo		Load JPG	☒
68	16/04/18 11:07	Reinspection Photo		Load JPG	☒
69	16/04/18 11:07	Reinspection Photo		Load JPG	☒
70	16/04/18 11:07	Reinspection Photo		Load JPG	☒
71	16/04/18 11:07	Reinspection Photo		Load JPG	☒
72	16/04/18 11:07	Reinspection Photo		Load JPG	☒
73	16/04/18 11:07	Reinspection Photo		Load JPG	☒
74	16/04/18 11:07	Reinspection Photo		Load JPG	☒
75	16/04/18 11:07	Reinspection Photo		Load JPG	☒
76	16/04/18 11:07	Reinspection Photo		Load JPG	☒
77	16/04/18 11:07	Reinspection Photo		Load JPG	☒
78	16/04/18 11:07	Reinspection Photo		Load JPG	☒
79	16/04/18 11:07	Reinspection Photo		Load JPG	☒
80	16/04/18 11:07	Reinspection Photo		Load JPG	☒
81	16/04/18 11:07	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
82	16/04/18 11:07	Reinspection Photo		☒
83	16/04/18 11:07	Reinspection Photo		☒
84	16/04/18 11:07	Reinspection Photo		☒
85	16/04/18 11:07	Reinspection Photo		☒
86	16/04/18 11:07	Reinspection Photo		☒
87	16/04/18 11:07	Reinspection Photo		☒
88	16/04/18 11:07	Reinspection Photo		☒
89	16/04/18 11:07	Reinspection Photo		☒
90	16/04/18 11:07	Reinspection Photo		☒
91	16/04/18 11:07	Reinspection Photo		☒
92	16/04/18 11:07	Reinspection Photo		☒
93	16/07/18 18:58	Reinspection Photo		☒
94	16/07/18 18:58	Reinspection Photo		☒
95	16/07/18 18:58	Reinspection Photo		☒
96	16/07/18 18:58	Reinspection Photo		☒
97	16/07/18 18:58	Reinspection Photo		☒
98	16/07/18 18:58	Reinspection Photo		☒
99	16/07/18 18:58	Reinspection Photo		☒
100	16/07/18 18:58	Reinspection Photo		☒
101	16/07/18 18:58	Reinspection Photo		☒
102	16/07/18 18:58	Reinspection Photo		☒
103	16/07/18 18:58	Reinspection Photo		☒
104	16/07/18 18:58	Reinspection Photo		☒
105	16/07/18 18:58	Reinspection Photo		☒
106	16/07/18 18:58	Reinspection Photo		☒
107	16/07/18 18:58	Reinspection Photo		☒
108	16/07/18 18:58	Reinspection Photo		☒
109	16/07/18 18:58	Reinspection Photo		☒
110	16/07/18 18:58	Reinspection Photo		☒
111	16/07/18 18:58	Reinspection Photo		☒
112	16/07/18 18:58	Reinspection Photo		☒
113	16/07/18 18:58	Reinspection Photo		☒
114	16/07/18 18:58	Reinspection Photo		☒
115	16/07/18 18:58	Reinspection Photo		☒
116	16/07/18 18:58	Reinspection Photo		☒
117	16/07/18 18:58	Reinspection Photo		☒
118	16/07/18 18:58	Reinspection Photo		☒
119	16/07/18 18:58	Reinspection Photo		☒
120	16/07/18 18:58	Reinspection Photo		☒
121	16/07/18 18:58	Reinspection Photo		☒
122	16/07/18 18:58	Reinspection Photo		☒
123	16/07/18 18:58	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/18 17:06	Premium Automobiles email		☐
2	29/03/18 17:06	Premium Automobiles estimates		☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 09:57	MARK ESTIMATE		☐
2	16/04/18 11:11	SUPPLEMENTARY		☐
3	17/07/18 15:42	SURVEYOR MARK ESTIMATE		☐
4	17/07/18 15:42	SUPPLEMENTARY LIST		☐

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/03/18 11:37	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/03/18 11:33	Accident Photo		Load JPG	☒
2	28/03/18 11:33	Accident Photo		Load JPG	☒
3	28/03/18 11:33	Accident Photo		Load JPG	☒
4	28/03/18 11:33	Accident Photo		Load JPG	☒
5	28/03/18 11:33	Accident Photo		Load JPG	☒
6	28/03/18 11:33	Accident Photo		Load JPG	☒
7	28/03/18 11:33	Accident Photo		Load JPG	☒
8	28/03/18 11:33	Accident Photo		Load JPG	☒
9	28/03/18 11:33	Accident Photo		Load JPG	☒
10	28/03/18 11:33	Accident Photo		Load JPG	☒
11	28/03/18 11:33	Accident Photo		Load JPG	☒
12	28/03/18 11:33	Accident Photo		Load JPG	☒
13	28/03/18 11:33	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/03/18 11:30	Sketch Plan		Load JPG	☒
2	28/03/18 11:30	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005947/AVBE2

Date: 14/08/2018

REFERENCE

Insured/Claimant:	LIE KHIN SIN	Policy No:	A28820191QMY	Claim No:	553806
Date of Loss:	27/03/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFR578J	Engine No:	CDN385691
Make & Model:	AUDI A6, 2.0 TFSI MU (C6) (A)	Chassis No:	WAUZZZ4GXEN074591
Reg. Date:	30/09/2014 (Man. Year: 2013)	Odometer:	45678 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,527.00	22,319.50	10,207.50	31.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,252.00	9,802.00	2,450.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,779.00	32,121.50	12,657.50	28.27
Approved Total (Overridden) (S\$)		30,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	43,979.00	29,200.00	14,779.00	33.60
+ GST 7.00/7.00% (S\$)	3,078.53	2,044.00	1,034.53	33.60
Nett Amount (S\$)	47,057.53	31,244.00	15,813.53	33.60

INSPECTION

Date of Assignment: 29/03/2018

Date Inspected: 02/04/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2018)
Parts:	143	AUDI A6 2.0 TFSI MU (C6) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFR578J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,326.00 FS	*2,326.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	236.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	1,174.00 FS	*1,174.00 FS
4	1		*RADIATOR GRILLE COVER	Cracked	32.00 FS	*31.20 FS
5	2		*FRONT SUPPORT PARKING AID - LH / RH	Not Necessary	118.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LH / RH	O/S Missing	268.00 FS	*133.50 FS
7	1		*FRONT BUMPER END CAP - LH	Not Necessary	34.00 FS	*- FS
8	1		*FOAM FILLER PIECE	Deformed	85.00 FS	*84.30 FS
9	1		*FRONT BUMPER HOLDER BRACKET - LH / RH	Not Necessary	446.00 FS	*- FS
10	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	21.00 FS	*- FS
11	2		*FRONT BUMPER GUIDE PIECE - LH / RH	Damaged	64.00 FS	*31.70 FS
12	1		*FRONT BUMPER COVER	Deformed	105.00 FS	*105.00 FS
13	1		*SIGN CAUTION	Necessary	12.00 FS	*11.60 FS
14	2		*FRONT FENDER - LH / RH	Repair	2,440.00 FS	*- FS
15	1		*FENDER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
16	1		*FRONT STONE GUARD CHIP - LH	Necessary	105.00 FS	*104.50 FS
17	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	144.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER - LH / RH	N/S Torn	404.00 FS	*201.50 FS
19	2		*HEADLIGHT GAS DISCHARGE - LH / RH	Cracked	5,806.00 FS	*5,806.00 FS
20	1		*GAS DISCHARGE LAMP	Not Necessary	394.00 FS	*- FS
21	1		*GAS DISCHARGE BULB RETAINING RING	Not Necessary	75.00 FS	*- FS
22	1		*GAS DISCHARGE CONTROL UNIT	Not Necessary	1,018.00 FS	*- FS
23	1		*HEADLIGHT POWER MODULE	Damaged	501.00 FS	*500.50 FS
24	1		*HOSE	Not Necessary	14.00 FS	*- FS
25	1		*HEADLIGHT MOUNTING - LH / RH	O/S Cracked	206.00 FS	*103.00 FS
26	2		*HEADLIGHT COVER CAP - LH / RH	Not Necessary	98.00 FS	*- FS
27	1		*HEADLIGHT LIFT CYLINDER	Cracked	208.00 FS	*207.50 FS
28	2		*ELBOW FITTING	Not Necessary	45.00 FS	*- FS
29	5		*HEADLIGHT WASHER HOSE	Not Necessary	172.00 FS	*- FS
30	1		*BONNET	Distorted	4,771.00 FS	*4,771.00 FS
31	1		*BONNET ONE ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
32	2		*BONNET LID HINGE - LH / RH	Not Necessary	282.00 FS	*- FS
33	1		*BONNET CATCH HOOK	Bent	122.00 FS	*122.00 FS
34	2		*BONNET LOCK BAR	Damaged	87.00 FS	*86.40 FS
35	1		*BONNET HOOD CATCH	Not Necessary	15.00 FS	*- FS
36	2		*BONNET LID LOCK WITH MICRO	Damaged	376.00 FS	*376.00 FS
37	1		*BOWDEN CABLE	Damaged	50.00 FS	*50.00 FS
38	1		*BONNET LID LOCK CABLE	Not Necessary	64.00 FS	*- FS
39	1		*BONNET LOCK CARRIER WITH MOUNTING	Deformed	1,024.00 FS	*1,024.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR GUIDE - LH / RH	O/S Deformed	54.00 FS	*26.40 FS
41	1		*CHARGE AIR COOLER	Not Necessary	492.00 FS	*- FS
42	1		*A/C CONDENSOR	Dented	683.00 FS	*682.50 FS
43	1		*RADIATOR	Dented	674.00 FS	*673.50 FS
44	6		*RUBBER BUSH	Not Necessary	52.00 FS	*- FS
45	4		*COOLANT CONCENTRATE	Necessary	133.00 FS	*132.80 FS
46	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
47	1		*TWIN FAN RING	Not Necessary	226.00 FS	*- FS
48	2		*RADIATOR FAN	Not Necessary	1,439.00 FS	*- FS
49	1		*RADIATOR CONTROL UNIT	Not Necessary	740.00 FS	*- FS
50	1		*AIR DUCT	Deformed	22.00 FS	*21.70 FS
51	1		*INTAKE AIR DUCT	Deformed	65.00 FS	*65.00 FS
52	1		*AIR FILTER	Deformed	256.00 FS	*255.50 FS
53	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	54.00 FS	*- FS
54	1		*AIR TEMPERATURE SENSOR BRACKET	Not Necessary	20.00 FS	*- FS
55	1		*WINDSHIELD WIPER COVER	Necessary	174.00 FS	*173.50 FS
56	1		*WATER DEFLECTOR	Necessary	66.00 FS	*65.30 FS
57	1		*GEL FOIL FOR RAIN SENSOR	Necessary	127.00 FS	*126.50 FS
58	1		*PRIMER	Necessary	19.00 FS	*18.20 FS
59	1		*WATER DEFLECTOR STRIP	Not Necessary	58.00 FS	*- FS
60	1		*FRONT NO. PLATE	Repeated	25.00 FS	*- FS
61	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
62	1		*SUNDRIES	Necessary	1,000.00 FS	*181.90 FS
63	1		*FRONT REINFORCEMENT BEAM	Bent	702.00 FS	*702.00 FS
64	1		*FRONT REINFORCEMENT BEAM BRACKET - RH	Bent	223.00 FS	*223.00 FS
65	1		*FRONT BUMPER BRACE - RH	Damaged	24.90 FS	*24.90 FS
66	1		*HEADLIGHT CONNECTOR HOUSING	Damaged	27.20 FS	*27.20 FS
67	1		*FRONT WINDSCREEN	Cracked	1,367.00 FS	*1,367.00 FS
68	1		*SOLENOID VALVE	Damaged	69.80 FS	*69.80 FS
69	1		*SOLENOID VALVE CONNECTOR	Damaged	8.10 FS	*8.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	32,527.00	22,319.50
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	4,550.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HINGES	New	3,600.00	2,900.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,252.00	9,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >