

REPAIR ESTIMATE*

MODEL : HYUNDAI SONATA

Lxx-Kalvin P1/2

Page 1 of 2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			<u>600</u>
	Panel Beating		B1/2	\$ 1,000.00
	Spray Painting Charge			\$ 750.00 600
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Towing Charge			\$ 50.00 1
	Remove/Refix Aircon & Refill Gas			\$ 150.00 50
	TOTAL LABOUR			\$ 2,050.00
	ESTIMATE TOTAL			\$ 10,500.84
Kalvin 1 (KKK) 2/4/18 1545hrs 4 Purp 45 After Repair photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				