

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

emailed
on 02/04
@ 1000 hours

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : TAN LIM MOTOR Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1313	Quotation Date : 29/03/2018	Terms : 30 DAYS
Vehicle No : SLS4229P	Chassis No : JM6BN22A8H0158629	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: III , INSURED'S VEH NO: SH9035Z , DATE OF ACCIDENT: 29.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER O/S <i>5.05m</i>	1	334.0000	334.00 ✓
2	FRONT FENDER INNER LINER <i>u1</i>	1	130.0000	130.00 X
3	FRONT FENDER INNER LINER CLIPS <i>11</i>	4	4.5000	18.00 X
4	LESS 20% (ITEM 1 - 3)	1	-96.4000	-96.40
5	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	250.0000 <i>100</i>	250.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	350.0000 <i>180</i>	350.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000 <i>11</i>	120.00 X

Not Allowed
2/s #400/2
2 day.

p-334
2%
267.2
547.2

4/4/18
Take photo After repair.
Confirmed on
04/04/18

437.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
Date:

Sub Total 1,105.60
GST(7.00%) 77.39
Total (SGD) 1,182.99