

**CITY CAB PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHA 9055H

DATE 2/4/2018 10:40

MAKE :

MODEL : HYUNDAI i40

LV  
 EQ  
 Chong

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door Mirror (RH) / va			\$ 980.50	
	Frt & Rear Wheel Hup-Cap (RH) Front & Rear X one		\$ 150.70	\$ 301.40	
				<b>SUB TOTAL</b>	<b>\$ 1,281.90</b>
				LESS 20%	\$ 256.38
				<b>DISCOUNTED TOTAL</b>	<b>\$ 1,025.52</b>
	Front Bumper X repair				
	Front (RH) Fender X repair				
	Front (RH) Door X repair				
	Rear (RH) Door X repair				
	Rear (RH) FA Lx repair				
	Rear Bumper i40 Plate X 11			\$ 50.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH)			\$ 75.00	Nett
				<b>\$ 205.00</b>	
	<b>Labour Charge</b>				
	Panel Beating-Repair RR Bumper/RR Rh Fender/RR Rh Door/Frt Rh Door/			\$ 500.00	400
	Frt Rh Fender & Frt Bumper				800
	Spray Painting Charge			\$ 1000	
	Wiring Charge			\$ 50.00	20
	Rear Wheel Alignment			\$ 120.00	X 11
				<b>TOTAL LABOUR</b>	<b>\$ 1,420.00</b>
				<b>ESTIMATE TOTAL</b>	<b>\$ 2,650.52</b>
	Kaka 11/11/11 2/4/18 1200 hrs 4 Pass P/P Before 1st p/A				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer Signature: _____ Date: _____				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				