

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7736P

DATE 2/4/2018 10:09

Jumani

MAKE :

MODEL : HYUNDAI i40

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 603.60
	Rear Bumper Clips 10 pcs <i>X</i>			\$ 22.00
	Rear Fender (RH) <i>X repair</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 164.40
	Rear Windscreen Moulding <i>X</i>			\$ 60.00
	Rear Door (RH) <i>-</i>			\$ 1,351.10
	Rear Wheel Hup-Cap (RH) <i>-</i>			\$ 150.70
	SUB TOTAL			\$ 4,371.90
	LESS 20%			\$ 874.38
	DISCOUNTED TOTAL			\$ 3,497.52
	Rear Bumper Advertisement Logo <i>-</i>			\$ 50.00 Nett
	Rear Bumper Rubber Mat <i>-</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>-</i>		\$ 100.00	\$ 200.00 Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00 Nett
	Rear Door Advertisement Logo (RH) <i>-</i>			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>-</i>			\$ 80.00 Nett
				\$ 526.00
	Labour Charge			<i>400</i>
	Panel Beating			\$ 750.00
	Spray Painting Charge-Bumper/Fender/Door			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	Transfer of Door			\$ 120.00 <i>50</i>
	Rear Wheel Alignment			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 2,190.00
	ESTIMATE TOTAL			\$ 6,213.52

Kalin (11/16)
3/4/18 1130L
3 Rep's
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary items are not included and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.