

Survey: MARLUS

ASSIGNMENT  
DOI: 7/4/18

Date / Time: 7/4/18  
Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE



Insured Vehicle No. : SJT 43886  
Name of Insured : Ng YONG KIAT  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A: 7/4/18  
Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_  
If NO, Driver Name / Age: UM YEW KUIE  
Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO )

Claim No. : 1718181005/020501  
Policy No. : 7170050107644  
Make / Model : LITRAE  
Place of Accident : HOANG ANH AVE & TO ANH C  
OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
Insured Liability : \_\_\_\_\_ % Final ? Yes / No

SJH 6627K



INSRS: private  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time		STAGE	DATE / PIC
<u>7/4/18</u>	<u>SJH 6627K -&gt;</u>	Non-Reporting ltr (1st):	
<u>7/4/18</u>	<u>SJT 43886 -&gt;</u>	Non-Reporting ltr (2nd):	
<u>7/4/18</u>		Non-Reporting ltr (Final):	
<u>7/4/18</u>		Notification ltr (if non-pickup):	
<u>7/4/18</u>		Call OE:	
<u>11/4/18</u>	<u>Bola &gt;7. Head to rear.</u>	After call ltr to OE:	
<u>3/8/18</u>	<u>File pass to typist type report</u>	Documentation Check List: Handler	Typist
<u>5/4/19</u>	<u>Email to LPC to seek mandate.</u>	Notification ltr (if non-pickup)	<input type="checkbox"/>
<u>15/4/19</u>	<u>Email From LPC approve mandate</u>	After call ltr to OE:	<input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS _____	( _____ days) Reduction:	% _____ Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: <u>27/4/19</u>	Confirm with <u>Van Hong</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No. : <u>37</u>	If NO or B 28. Ass. Lia :
Repair Cost:	SS <u>5350.00</u>		<b>COPIES SENT</b> <u>15/4</u>
Loss of Rental (LOR):	SS <u>700.00</u>	( <u>7</u> days) x <u>100</u>	
Loss of Use (LOU):	SS _____	( \$ _____ x _____ days)	
Loss of Income (LOI):	SS _____	( \$ _____ x _____ days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS <u>8.00</u>		1) Claim status: Normal/Reject/Private Settle
Medical:	SS _____		2) Report Format:
Disbursement:	SS _____	(e.g. Tow/ Independent )	3) Survey fee:
Legal Cost	SS _____		
<b>Total:</b>	SS <u>6058.00</u>	<b>Global Sum SS:</b>	
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>6058.00</u>	Name 1: <u>Precise Auto Service</u>	
Payee 2: (Strike if N.A.)	SS _____	Name 2:	
Payee 3: (Strike if N.A.)	SS _____	Name 3:	

REF: **LPC**

**ASSIGNMENT**

**SJN 6627K**

**2 / 09**

From: \_\_\_\_\_ Date: **3/1/18**

Veh No: \_\_\_\_\_ Yr Regn: **2 / 09**

Estimated Cost: \_\_\_\_\_

Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or **CA /**

To Inspect Vehicle No: **SJN 6627K**

Make: **Honda Fit** c.c. **1339**

at Workshop m/s: **Precise Auto**

Colour: **silver** A/C: **Insured / Std / NI / NA**

of **1 Kaki Blct Ave 6 # 02-33**

Sp. Reading: **163152** T/Radio: **Insured / Std / NI / NA**

Insured: **SJ1438861**

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: **GE61135763**

Claims No. \_\_\_\_\_

Gen. Cond: **Good** / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Steering: **In order** / Jammed / Leaked / Burnt or

(Client's Record)

Brake: **In order** / Jammed / Leaked / Burnt or

Make of Veh: \_\_\_\_\_

Modi: **Nil** / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: **185/65R15**

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Newton**

Bal. or Market Value: **14k.**

Front **6** mm Rear **6** mm

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. **6** mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. **6** mm

Est. Repairs: **8** days Res.: Yes or No

D.O.A. **31/3/18** D.O.I. **31/4/18**

Lum Sum: **20** % 3 Val.: Yes or No

Survey held at: **9.15am.**

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **Rear**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
**cont. conf 2/5 2747471 - net 6529**

**20/7/18 conf 2/5 \$5000 with yanhey**

**(Ref # 4009.84 451.)**

Date/Time File Pass to?  : Preli. Report

Days Of Repair: \_\_\_\_\_

1)  : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time File Return to? \_\_\_\_\_

Survey Fee:	
Transportation	
_____ \$ - RE. SI	
Photos:	
Others:	
TOTAL	

- Add Fee:
- Site Insp (\$)
  - Interview (\$)
  - Tech. Invs (\$)
  - Weekend (\$)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$)



**SELL YOUR CAR BY BIDDING**

**HIGHEST SELLING PRICE GUARANTEED!**

**OR GET \$100 CASH!**



**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years COE Renewal, Toyota Vios 1.5A.



\$2500 Down Payment Monthly  
 From \$580 Onwards. Lowest  
 3.66%P.A@GV Cars Financing.  
 GV Credit Pte Ltd StarAd



**click here to view**  
**our PRISTINE USED CARS**  
 at GREAT PRICES

Browse by Category

« Back ( 1 2 ) Next »

Sort by Date Posted  20 results/page

30 vehicles

Advanced Search  Submit

**Search Selection**

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
honda fit		Any	Any	2009	Any	Any	Any	Available



**Honda Fit 1.3A GF** **\$14,800** \$8,340 /yr 26-Mar-2009 1,339 cc 100,000 km Hatchback Available

Cheapest In The Market. Purchase With A Peace Of Mind With Minimum Risk. Comes With 6 Months Warranty Including 24/7 Emergency Towing In Case Of Breakdown. Loan/Insurance Flexibility, Trade In And Scr...

Posted: 03-Apr-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda



**Honda Fit 1.3A G** **\$16,200** \$9,970 /yr 03-Mar-2009 1,339 cc - Hatchback Available

A Spacious Hatchback In Good Condition For Either Short Term Drive Or Future Plan For COE Renewal. Owned By 1 Careful Driver. No Repair Needed. Bank Loan Up To 80%, In House Loan Up To 90% Available. ...

Allmotoring.sg  
 Posted: 02-Apr-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda



**Honda Fit 1.3A G** **\$14,800** \$7,330 /yr 24-Mar-2009 1,339 cc - Hatchback Available

Black Sporty Fit. Best Model For First Time Car Owner. Easy To Maintain And Robust For Daily Usage. Original Nice Paintwork. Excellent Condition! Loan And Trade In Available. Very Well Maintained Car....

Posted: 01-Apr-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda



**Honda Fit 1.3A G** **\$18,900** \$8,020 /yr 10-Sep-2009 1,339 cc - Hatchback Available

100% Accident Free, Affordable Car For Everyone, Lowest Depreciation In The Market, Depreciation Per Day Only \$19, New Paint Work, New Road Tax Valid Till Sep 2018, The Most Reliable And Popular Car F...

Posted: 30-Mar-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda

Car Buying Car Selling Car Ownership Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation

Car Aftermarket On The Move Lifestyle



**Honda Fit 1.3A L Skyroof** **\$19,999** \$8,130 /yr 30-Oct-2009 1,339 cc 126,000 km Hatchback Available

Black Body With Black Rims, Sporty Exterior And Interior.

Posted: 30-Mar-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda



**Honda Fit 1.3A GF Skyroof** **\$18,800** \$8,880 /yr 04-Aug-2009 1,339 cc - Hatchback Available

A Very Unique Black Color Beauty With Outstanding Feel. Both Interior And Exterior Are Very Well Maintained. Superb Drive, Excellent Fuel Economy. Come With HKS Road Legal Exhaust With Receipt To Prov...

Posted: 30-Mar-2018 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit, Used Honda



**Honda Fit 1.3A G** **\$18,800** \$9,000 /yr 24-Jul-2009 1,339 cc 145,000 km Hatchback Available

Brand New Number Plate! SLW Series! Brilliant Silver Color! Easy To Maintain! Low Mileage Low Depreciation! In Excellent Drive Away Condition! Very Well Maintained! Come And See Now Before Its Too Late...

Ka-Hup Vehicles Trading

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5999D

**Vehicle Details**

Vehicle No.:	SJN6627K
Vehicle to be Exported:	No
Intended De-registration Date:	03 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13A4147828
Chassis No.:	GE61135763
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,760.00
Original Registration Date:	24 Feb 2009
First Registration Date:	24 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$14,760.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2019
PARF Rebate Amount:	\$7,380.00 ✓

**Intended COE Rebate Details**

COE Expiry Date:	23 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$1,020.00
COE Rebate Amount:	\$91.00
<b>Total Rebate Amount:</b>	<b>\$7,471.00</b>

The information contained herein is correct as at 03 Apr 2018

OK

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

30-06-18

Date of accident : 31-03-18

Marcus

OUR REF : SJN 6627K/T/18

Date in/out : 01/04/18 to 10/04/18

TAN YONG MONG

Blk 610 Hougang Ave 8

#06-494

Singapore 530610

no of Approval  
Lack  
L/S + 5000/-  
31/4/18  
S. Jay.

ESTIMATE BILL ON VEH. NO. : SIN 6627K

MODEL : HONDA FIT

CHASSIS NO : GE61135763

LIST ITEM

Rear Bumper Fascia	460.50		Dis	686.20	
Rear Bumper Side Retainer		2pcs @ 14.80	Set	29.60	
Rear Bumper Bracket		2pcs @ 8.60	ols set	17.20	l/c
Rear Bumper Clips		10pcs @ 4.10	neu	41.00	
Tail Gate	784.80		Safety, 20	878.90	
Tail Gate Hinge		2pcs @ 35.80	11	71.60	X
Tail Gate Stopper		2pcs @ 10.00	11	20.00	X
Tail Gate Absorber		2pcs @ 169.30	11	338.60	X
Tail Gate Lock			twi/shd	230.20	
Tail Gate Lock Striker			11	25.00	X
Tail Gate Inner Trim Board			De/cne	180.30	
Tail Gate Inner Trim Board Clips		10pcs @ 4.10	neu	41.00	
Tail Gate Weather Stripe			twi	97.20	
Tail Gate Inner Handle Holder			11	18.00	X
Tail Gate Outer Garnish			11	120.40	X
Tail Gate Outer Garnish Clips		4pcs @ 3.50	11	14.00	X

Rear Windscreen Glass Moulding (Top)			RM	40.60	/
Rear Windscreen Glass Moulding (Bottom)			RM	51.70	/
Rear Windscreen Glass Clips	14pcs @ 4.10		RM	57.40	X
Rear Windscreen Glass Seal			RM	24.00	/
Tail Lamp Assy - n/s & o/s	2pcs @ 243.10		ONE	486.20	/
Tail Lamp Sealant	2pcs @ 29.80		RM	59.60	X
Tail Lamp Clips	4pcs @ 7.60		RM	30.40	X
Tail Lamp Base Panel	2pcs @ 94.20		o/s DD	188.40	PC
Rear End Panel			S. J DD	296.60	/
Rear End Panel Top Trim			TRIM	112.30	/
Rear End Panel Top Trim Clips	4pcs @ 4.10		RM	16.40	X
Rear Fender Inner Trim Board - RH & LH	198.60	2PCS	o/s CRG	397.20	PC
Rear Fender Inner Trim Board Clips	2pcs @ 28.00		RM	56.00	X
Rear Floor Panel Board			TRIM	185.00	/
Rear Floor Panel Insulator Cloth			NF	258.10	X
Rear floor panel			CRAMP/GRG	590.10	/
Exhaust Silencer Hook	3952.50 202		RM	55.00	X
Tail Gate Emblem	3162.00		NF	60.60	X
				5,774.80	
			20% Less Discount	1,154.96	
				4,619.84	

**SPECIAL NETT ITEM**

Rear Bumper Reverse Sensor

TRIM 200  
380.00

**LABOUR CHARGE**

To Remove & Refix Rear Windscreen Glass

120 180.00

To Tuff Coat Affected Areas.

100 180.00

To Remove & Refix Interior Upholstery.	80	180.00
To Remove & Refix Exhaust Silencer & Straighter Exhaust Center Pipe.	60	280.00
Install Bumper Reserve Sensor	50	120.00
To Check Wiring System	30	120.00
To Respray Affected Areas.	1100	1,200.00
To Renew Damaged Parts, Straighter & Repair Spare Tyre Panel, Repair Rear Chassiss Sub Frame Member & Aligned All Parts	1300	1,600.00
To Transfer Mechanism Into New Tail Gate	60	150.00

TOTAL :	9,009.84
GST 7% :	630.69
<b>AMOUNT DUE :</b>	<b>9,640.53</b>

6262

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Monday, 2 April, 2018 5:15 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; support@preciseauto.sg  
**Subject:** FW: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.  
**Attachments:** 02042018170538.pdf; 02042018130457.pdf

Dear Catherine,

Kindly refer to email below and attachments.

Please proceed to appoint Marcus Chua conduct a survey of the vehicle SJN 6627K on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

02042018 @ 5:23pm  
Arine deh in  
mums.

---

**From:** Precise Auto Service [mailto:support@preciseauto.sg]  
**Sent:** Monday, 2 April, 2018 5:09 PM  
**To:** ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Mr. Eric,

We refer to your email on dated 02-04-2018. Please be informed that we are select **Mr. Marcus Chua from LKK Auto** as our SJE.

Thank You

Best Regards  
Arine

On 2 April 2018 at 15:23, ERIC WOO JUN KIAT <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)> wrote:

Dear Arine,

We refer to your email below.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Precise Auto Service [<mailto:support@preciseauto.sg>]

**Sent:** Monday, 2 April, 2018 1:11 PM

**To:** GERALD POH WEE BIN

**Subject:** Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for SJN 6627K in our workshop ASAP.

Thank You!

Best Regards

Arine

--

**T** : 6745 7367 | **F** : 6841 3390

**E** : [support@preciseauto.sg](mailto:support@preciseauto.sg)

**W**: [www.preciseauto.sg](http://www.preciseauto.sg)

**A** : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



*Follow us on social media:*



--

**T** : 6745 7367 | **F** : 6841 3390


**E** : [support@preciseauto.sg](mailto:support@preciseauto.sg)

**W**: [www.preciseauto.sg](http://www.preciseauto.sg)

**A** : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



*Follow us on social media:*



## Shu Pei (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 5 April 2018 9:02 AM  
**To:** Shu Pei (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G. \*\*\*LKK REF:CC4/LPC18006107/Uwb3  
**Attachments:** 05042018085919.pdf

Dear Shu Pei,

Attached insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Wednesday, 4 April, 2018 6:28 PM  
**To:** ERIC WOO JUN KIAT; GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A; Vivian Lau (LKKAuto)  
**Subject:** RE: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G. \*\*\*LKK REF:CC4/LPC18006107/Uwb3

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJN 6627K at M/s Precise Auto Service.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Monday, 2 April 2018 5:23 PM

**To:** 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Eric,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

**Sent:** Monday, 2 April, 2018 5:15 PM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; [support@preciseauto.sg](mailto:support@preciseauto.sg)

**Subject:** FW: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Catherine,

Kindly refer to email below and attachments.

Please proceed to appoint Marcus Chua conduct a survey of the vehicle SJN 6627K on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Precise Auto Service [<mailto:support@preciseauto.sg>]

**Sent:** Monday, 2 April, 2018 5:09 PM

**To:** ERIC WOO JUN KIAT

**Cc:** MT\_Claim\_SG

**Subject:** Re: Our Ref: 17/18/18/VP05/020501 DOA: 31/3/18 Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Mr. Eric,

We refer to your email on dated 02-04-2018. Please be informed that we are select **Mr. Marcus Chua from LKK Auto** as our SJE.

Thank You

Best Regards

Arine

On 2 April 2018 at 15:23, ERIC WOO JUN KIAT <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)> wrote:

Dear Arine,

We refer to your email below.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** Precise Auto Service [<mailto:support@preciseauto.sg>]

**Sent:** Monday, 2 April, 2018 1:11 PM

**To:** GERALD POH WEE BIN

**Subject:** Pre-repair Inspection for SJN 6627K. Your Insured Vehicle no : SJT 4388G.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for SJN 6627K in our workshop ASAP.

Thank You!

Best Regards

Arine

--

**T :** 6745 7367 | **F :** 6841 3390

**E :** [support@preciseauto.sg](mailto:support@preciseauto.sg)

**W :** [www.preciseauto.sg](http://www.preciseauto.sg)

**A :** 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



***Follow us on social media:***



**T** : 6745 7367 | **F** : 6841 3390

**E** : [support@preciseauto.sg](mailto:support@preciseauto.sg)

**W** : [www.preciseauto.sg](http://www.preciseauto.sg)

**A** : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



***Follow us on social media:***





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18006107/Uwb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-05-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 4388G	Veh. Inspected	SJN 6627K
Policy No.	Z17VP05015414	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020501	Excess (\$)	0.00
Assign From	GERALD	Assign Date	02/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61135763	Colour	SILVER
Odometer	163152	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	NEUTON	6 mm
L/H Front Tyre	185/65 R15	NEUTON	6 mm
R/H Rear Tyre	185/65 R15	NEUTON	6 mm
L/H Rear Tyre	185/65 R15	NEUTON	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	31/03/2018	Inspection Date	03/04/2018
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>8 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 6627K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER FASCIA	DISTORTED	686.20	460.50
2	REAR BUMPER SIDE RETAINER @\$14.80	BENT	29.60	29.60
2	REAR BUMPER BRACKET @\$8.60	O/S BENT	17.20	8.60
10	REAR BUMPER CLIPS @\$4.10	NECESSARY	41.00	41.00
1	TAIL GATE	BADLY DENTED	878.90	784.80
2	TAIL GATE HINGE @\$35.80	NOT NECESSARY	71.60	-
2	TAIL GATE STOPPER @\$10.00	NOT NECESSARY	20.00	-
2	TAILGATE ABSORBER @\$169.30	NOT NECESSARY	338.60	-
1	TAIL GATE LOCK	TWISTED / SHORTED	230.20	230.20
1	TAIL GATE LOCK STRIKER	NOT NECESSARY	25.00	-
1	TAIL GATE INNER TRIM BOARD	DEFORMED / CRACKED	180.30	180.30
10	TAIL GATE INNER TRIM BOARD CLIPS @\$4.10	NECESSARY	41.00	41.00
1	TAIL GATE WEATHER STRIPE	TWISTED	97.20	97.20
1	TAIL GATE INNER HANDLE HOLDER	NOT NECESSARY	18.00	-
1	TAIL GATE OUTER GARNISH	NOT NECESSARY	120.40	-
4	TAIL GATE OUTER GARNISH CLIPS @\$3.50	NOT NECESSARY	14.00	-
1	REAR WINDSCREEN GLASS MOULDING (TOP)	NECESSARY	40.60	40.60
1	REAR WINDSCREEN GLASS MOULDING (BOTTOM)	NECESSARY	51.70	51.70
14	REAR WINDSCREEN GLASS CLIPS @\$4.10	NOT NECESSARY	57.40	-
1	REAR WINDSCREEN GLASS SEAL	NECESSARY	24.00	24.00
2	TAIL LAMP ASSY -N/S & O/S @\$243.10	CRACKED	486.20	486.20
2	TAIL LAMP SEALANT @\$29.80	NOT NECESSARY	59.60	-
4	TAIL LAMP CLIPS @\$7.60	NOT NECESSARY	30.40	-
2	TAIL LAMP BASE PANEL @\$94.20	O/S DENTED	188.40	94.20
1	REAR END PANEL	BADLY DENTED	296.60	296.60
1	REAR END PANEL TOP TRIM	TWISTED	112.30	112.30
4	REAR END PANEL TOP TRIM CLIPS @\$4.10	NOT NECESSARY	16.40	-
2	REAR FENDER INNER TRM BOARD -RH & LH	O/S CRACKED	397.20	198.60
2	REAR FENDER INNER TRIM BOARD CLIPS @\$28.00	NOT NECESSARY	56.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL BOARD	TORN	185.00	185.00
1	REAR FLOOR PANEL INSULATOR CLOTH	NOT FITTED	258.10	-
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	590.10	590.10
1	EXHAUST SILENCER HOOK	NOT NECESSARY	55.00	-
1	TAIL GATE EMBLEM	NOT FITTED	60.60	-
	LESS 20% DISCOUNT		-1,154.96	-790.50
			<b>4,619.84</b>	<b>3,162.00</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER REVERSE SENSOR (SN)	TORN	380.00	200.00
			380.00	200.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS.		180.00	120.00
	TO TUFF COAT AFFECTED AREAS.		180.00	100.00
	TO REMOVE & REFIX INTERIOR UPHOLSTERY.		180.00	80.00
	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE.		280.00	60.00
	INSTALL BUMPER REVERSE SENSOR .		120.00	50.00
	TO CHECK WIRING SYSTEM.		120.00	30.00
	TO RESPRAY AFFECTED AREAS.		1,200.00	1,100.00
	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR SPARE TYRE PANEL ,REPAIR REAR CHASSIS SUB FRAME MEMBER & ALIGNED ALL PARTS.		1,600.00	1,300.00
	TO TRANSFER MECHANISM INTO NEW TAIL GATE.		150.00	60.00
			<b>4,010.00</b>	<b>2,900.00</b>
	<b>GRAND TOTAL</b>		<b>9,009.84</b>	<b>6,262.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,000.00</b>

Report Ref No. CC4/LPC18006107/Uwb3n2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.