



## CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

FWD/AIG(SLG9442U)  
DOA:22/03/2018@1900

AIG ASIA PACIFIC INSURANCE PTE LTD

3/4/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJV 2490 X - KIA CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR

CHASSIS NO: KNAFW411MA5125771 (2010)

Labour to jacking, panel beating, repair and  
straighten rear fender ~~LH~~ and rear bumper.

\$ ~~300.00~~ 250

Putty and respray rear fender ~~LH~~, rear bumper and  
rear door ~~LH~~ RH

\$ ~~600.00~~ 400  
\$ 900.00  
\$ 63.00  
\$ 963.00

ADD 7% GST

Note: The above is an estimate only. IF other parts requested  
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

749ml  
4p 9000068

3 days

P/P

05/04/18 @ 1535  
Rear after repair