

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 06 Apr 2018

## **Preliminary Advice**

Insured Vehicle No : SGS1253Y  
TP Vehicle No : SHC6413S  
Make : KIA OPTIMA  
Date of Inspection : 03/04/2018  
Inspection At : Premier Automotive Services Pte Ltd (HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Accident Date : 02/04/2018  
Assignment Date : 03/04/2018  
Est. Duration of Repair : 2 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...rear N/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,621.10
Revised Amount	:S\$	1,459.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,459.80

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.