


NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006132/K1qbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 10-04-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 2682B	Veh. Inspected	SHA 2702U	
Policy No.	5094242999	Coverage (\$)	0.00	
Claim No.	MT/0988139-002	Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU803568820	Colour	BLUE	
Odometer	71087	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	27/03/2018	Inspection Date	03/04/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			