

GST REG. NO.: 200907910H

11 Tannery Lane Singapore 347774 (Head Office)	Tel: 6292 5578 (3
1007/1009 Serangoon Road Singapore 328168 (Show Room)	Tel: 6341 5378 / 6
1 Kaki Bukit Ave 6 #02-54/55 Autobay @ Kaki Bukit Singapore 417883	Tel: 6844 6378 (3
48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586	Tel: 6515 4978 (3
280 Woodlands Industrial Park E5 #01-43 Harvest Singapore 757322	Tel: 6339 2178 (3

Tel: 6292 5578 (3 lines) Fax: 6295 5579
Tel: 6341 5378 / 6677 8999 Fax: 6341 7379
Tel: 6844 6378 (3 lines) Fax: 6844 6378

Tel: 6844 6378 (3 lines) Fax: 6844 6379
Tel: 6515 4978 (3 lines) Fax: 6515 4979

Tel: 6339 2178 (3 lines) Fax: 6339 3379

Our Ref: ACCUM.TL.FBL3163G

Your Ref:

Please quote your referance number when replying

Date: 27/03/2018

M/s India Insurance Pte Ltd 64 Cecil Street, #04/#05 IOB Building, Singapore 049711 BY FAX & POST
Fax No: 62244174

Attention: Motor Claims Department

Dear Sirs.

ACCIDENT INVOLVING FBL3163G & SH8484S ALONG PIE TOWARDS CHANGI ON 04TH FEBURARY 2018 AT ABOUT 0630 HOURS

- 1. We act for the owner of motor vehicle: FBL3163G in the above mentioned accident.
- 2. Pursuant to NIMA protocol, we hereby give you notice to conduct pre-repair inspection of our client's motorcycle at the under-stated workshop

UNIQUE MOTORSPORTS PTE LTD

11 Tannery Lane Singapore 347774

Tel: 62925578 (Ext 210) / Fax: 62955579 Email: alvin@uniquemotorsports.com.sg

Person-in-charge: Alvin Koh

3. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a prerepair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and proceed to repair our client's motor bike.

Yours faithfully

Name of Surveyor & Signature

Date:_____

Time:____

UNIQUE MOTORSPORTS PTE LTD